

# Truth in Sale of Housing Disclosure Report

NOTICE - Read Entire Report Carefully. This is not a rental license inspection or a buyer's inspection!

**Address:** 3611 BRYANT AVE N Minneapolis, MN



**Current Owner Name:** 3611 Bryant Ave N Land Trust

**Contact:** 3611 Bryant Ave N Land Trust

**Owner Address:** 13570 Grove Drive, #224  
Maple Grove, MN 55311

**Business/Relationship:**  
**Phone Number:**

\*\*\*\*\* SEE ATTACHED PAGES FOR IMPORTANT CONSUMER INFORMATION \*\*\*\*\*

## THERE ARE REQUIRED REPAIR/REPLACE ITEMS NOTED IN THIS REPORT.

**Observed Number of Units:** 1

**City Reference as:** 1

**Building Type:** Single Family Home

**Zoning:** UN1

**Local Historic Designation:** No

To verify this structure complies with the current Zoning ordinance, please contact Zoning Administration via 311.

**Housing Orders:** No

**Condemnation Status:** NA

**Reason:** NA

1. This report offers a limited overview of the building components and fixtures and is not technically extensive. Prospective buyers may want to seek additional opinions from various experts in the inspections field prior to purchase. This report is not a warranty or guarantee, expressed or implied, by the City of Minneapolis or by the evaluator or of any building component or fixture. Further, the buyer may want to seek additional information regarding any open permits. For 1st time condominium units, this report includes only those items located within the residential units. The Professional Opinion covers those items in the common areas of the building.
2. The buyer must repair all items marked Repair/Replace, unless the seller agrees to do the repairs. The seller is not required to complete the RR's if the property does not sell. All required R.R.'s items are enforceable by Minneapolis Ordinance Chapter 248 and/or 250. All other items will not be used by the Inspections Division as a basis for enforcing Minneapolis ordinances.
3. The ordinance requires that no person shall exhibit or show a dwelling for sale without first having obtained an official Evaluation Report and places the responsibility on the seller or agent to make sure that this report (and in the case of 1st time condo conversions, the Professional Opinion,) is publicly displayed on the premises at all times when the house is shown to prospective buyers. The seller or agent must give a copy of this report (and Professional Opinion for 1st time condo conversions) to the buyer prior to the signing of a Purchase Agreement, or as otherwise required in Minneapolis Ordinance Chapter 248 and/or 250.
4. This report covers only those items listed on the form. The evaluator is not required to ignite the heating plant, use a ladder to observe the condition of the roofing, evaluate inaccessible or concealed areas or disassemble items. This report does not address formaldehyde, lead paint, any airborne gasses (including radon), asbestos, wood stoves, fireplaces or air conditioners. Gas inserts in fireplaces WILL be evaluated.
5. This report is not an FHA, VA or Section 8 inspection. This report is not a code compliance inspection. It is not an appraisal. This report may be based upon different standards than the lender, FHA or VA. This is not a rental inspection. If planning to rent, additional requirements may apply and a license will be required.
6. The seller is required to provide the disclosure information in the box above. If this is not filled out, buyers are advised to request the seller to do so.
7. This report is valid for two years from the date of issue or one sale and only for the owner named on the report. It is required for all single-family homes, duplexes, townhouses or 1st time condominium conversions offered for sale.
8. **Any questions** regarding this report should be directed to the evaluator whose name and phone number appear below. **Any complaints** regarding this report should be directed to Truth in Housing at (612) 673-5840, Construction Code Services, 250 South 4th Street #300, Minneapolis, MN 55415.

I hereby certify that this report is made in compliance with the Minneapolis Code of Ordinances, Chapter 248, and that I utilized care and diligence reasonable and ordinary for one meeting the Certification Standards. The report covers only those problems listed and reasonably visible at the time of my evaluation and does not warrant future useful life of any house component or fixture. I have included all required information pages with this report.

**Evaluator Name:** Dan Brausen

**Phone:** 651-483-8407

**Evaluation Date:** 6/28/2024

**Signature:** Dan Brausen

**Evaluation #:** 20242795

# Truth in Sale of Housing Disclosure Report

Address: 3611 BRYANT AVE N Minneapolis, MN



## EVALUATION CODES:

**M** :=Meets Minimum Requirements    **C** :=Comments    **NA** :=Not Applicable/Does Not Apply    **B** :=Below Minimum Requirements    **SC** :=Suggested Correction  
**RRE** :=Repair/Replace, Evaluator Verification Required    **RRP** :=Repair/Replace, Permit/City Inspector Required    **LIC** :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

## Basement

1. Basement Stairs/Railings
  - B, Uneven riser heights.
  - B, Stairway headroom is less than 6' 8".
2. Basement Floors
  - C, Other Comment: - Areas finished and not visible. Stored items restrict view.
3. Foundation Walls
  - C, Other Comment: - Areas finished - not visible. Stored items restrict view.
4. Evidence of Dampness or Staining
  - M, Meets Minimum Requirements
5. First Floor, Floor System
  - B, Missing joist hangers and/or joist hanger nails.
  - C, Other Comment: - Areas finished, not visible.
6. Columns & Beams
  - C, Other Comment: - Areas finished, not visible.
7. Basement Sleeping Rooms
  - C, Yes, there are basement bedrooms. See Bedroom Section for details.
8. Basement Plumbing Fixtures
  - NA, Not Applicable/Does Not Apply
9. Sump Pumps
  - M, Meets Minimum Requirements
10. Smoke Detectors / CO Detectors
  - M, Meets Minimum Requirements
11. Basement Electrical Outlets/Fixtures
  - B, Below Minimum Requirements: - Improperly routed/shielded NM wiring in areas.

## Electric

**Amps:** 100

**Volts:** 110/220

12. Electrical service installation
  - RRE, Repair/Replace: - Water meter is in locked bedroom - reinspection required to confirm electric ground.
13. Separate 20-amp Kitchen Circuit indexed at Service Panel
  - M, Meets Minimum Requirements
14. Separate 20-amp Laundry Circuit indexed at Service Panel
  - C, Separate 20-amp laundry circuit is not indexed at service panel

# Truth in Sale of Housing Disclosure Report

Address: 3611 BRYANT AVE N Minneapolis, MN



## EVALUATION CODES:

**M** :=Meets Minimum Requirements    **C** :=Comments    **NA** :=Not Applicable/Does Not Apply    **B** :=Below Minimum Requirements    **SC** :=Suggested Correction  
**RRE** :=Repair/Replace, Evaluator Verification Required    **RRP** :=Repair/Replace, Permit/City Inspector Required    **LIC** :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

## Plumbing

---

- 15. Floor Drains  
C, Other Comment: - Unable to remove drain plate - not fully evaluated.
- 16. Drain, Waste & Vent Piping  
C, Main cleanout not located.
- 17. Water Supply Piping  
M, Meets Minimum Requirements
- 18. Gas Piping  
M, Meets Minimum Requirements
- 19. Copper Water Line Visible on the Street Side of Water Meter  
M, Meets Minimum Requirements

## Water heater

---

- 20. Water Heater & Installation  
M, Meets Minimum Requirements
- 21. Water Heater Venting  
M, Meets Minimum Requirements

## Heating

---

**Heating System Type:** forced air furnace

**Heating System Venting Type:** condensing

- 22. Heating Plant Viewed in Operation  
M, Meets Minimum Requirements
- 23. Heating Plant & Installation  
M, Meets Minimum Requirements
- 24. Heating Plant Combustion Venting  
M, Meets Minimum Requirements
- 25. Incinerator / Abandoned Oil Tanks / Misc Gas Fixtures  
M, Meets Minimum Requirements

# Truth in Sale of Housing Disclosure Report

Address: 3611 BRYANT AVE N Minneapolis, MN



## EVALUATION CODES:

**M** :=Meets Minimum Requirements    **C** :=Comments    **NA** :=Not Applicable/Does Not Apply    **B** :=Below Minimum Requirements    **SC** :=Suggested Correction  
**RRE** :=Repair/Replace, Evaluator Verification Required    **RRP** :=Repair/Replace, Permit/City Inspector Required    **LIC** :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

## Laundry

---

- 26. Gas Piping  
M, Meets Minimum Requirements
- 27. Dryer Venting  
M, Meets Minimum Requirements
- 28. Plumbing Fixtures  
M, Meets Minimum Requirements

## Kitchen

---

- 29. Walls and Ceiling Components  
M, Meets Minimum Requirements
- 30. Evidence of Dampness or Staining  
M, Meets Minimum Requirements
- 31. Floor Condition  
M, Meets Minimum Requirements
- 32. Window Size & Openable Area  
M, Meets Minimum Requirements
- 33. Window & Door Condition/Mechanical Venting  
M, Meets Minimum Requirements
- 34. Electrical Outlets/Fixtures  
M, Meets Minimum Requirements
- 35. Plumbing Fixtures  
M, Meets Minimum Requirements
- 36. Water Flow  
M, Meets Minimum Requirements
- 37. Gas Piping  
M, Meets Minimum Requirements

# Truth in Sale of Housing Disclosure Report

Address: 3611 BRYANT AVE N Minneapolis, MN



## EVALUATION CODES:

**M** :=Meets Minimum Requirements    **C** :=Comments    **NA** :=Not Applicable/Does Not Apply    **B** :=Below Minimum Requirements    **SC** :=Suggested Correction  
**RRE** :=Repair/Replace, Evaluator Verification Required    **RRP** :=Repair/Replace, Permit/City Inspector Required    **LIC** :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

## Dining Room/Living Room

---

### 38. Walls and Ceiling Components

M, Meets Minimum Requirements

### 39. Evidence of Dampness or Staining

M, Meets Minimum Requirements

### 40. Floor Area & Ceiling Height

M, Meets Minimum Requirements

### 41. Floor Condition

M, Meets Minimum Requirements

### 42. Window Size & Openable Area

M, Meets Minimum Requirements

### 43. Window & Door Condition

M, Meets Minimum Requirements

### 44. Electrical Outlets/Fixtures

C, Other Comment: - Furnishings and stored items restrict access to some possible receptacle locations.

## Bathroom (Main)

---

### 45. Walls & Ceiling Components

M, Meets Minimum Requirements

### 46. Evidence of Dampness or Staining

M, Meets Minimum Requirements

### 47. Floor Condition

M, Meets Minimum Requirements

### 48. Window Size & Openable Area/Mechanical Vent

M, Meets Minimum Requirements

### 49. Window & Door Condition

M, Meets Minimum Requirements

### 50. Electrical Outlets & Fixtures

M, Meets Minimum Requirements

### 51. Plumbing Fixtures

M, Meets Minimum Requirements

### 52. Water Flow

M, Meets Minimum Requirements

# Truth in Sale of Housing Disclosure Report

Address: 3611 BRYANT AVE N Minneapolis, MN



## EVALUATION CODES:

**M** :=Meets Minimum Requirements    **C** :=Comments    **NA** :=Not Applicable/Does Not Apply    **B** :=Below Minimum Requirements    **SC** :=Suggested Correction  
**RRE** :=Repair/Replace, Evaluator Verification Required    **RRP** :=Repair/Replace, Permit/City Inspector Required    **LIC** :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

## Bathroom (Bsmt)

---

- 45. Walls & Ceiling Components  
M, Meets Minimum Requirements
- 46. Evidence of Dampness or Staining  
M, Meets Minimum Requirements
- 47. Floor Condition  
M, Meets Minimum Requirements
- 48. Window Size & Openable Area/Mechanical Vent  
M, Meets Minimum Requirements
- 49. Window & Door Condition  
M, Meets Minimum Requirements
- 50. Electrical Outlets & Fixtures  
C, Other Comment: - Receptacle(s) not GFCI protected.
- 51. Plumbing Fixtures  
M, Meets Minimum Requirements
- 52. Water Flow  
M, Meets Minimum Requirements

## Hallways/Stairwells

---

- 53. Walls and Ceiling Components  
M, Meets Minimum Requirements
- 54. Evidence of Dampness or Staining  
M, Meets Minimum Requirements
- 55. Floor Condition  
M, Meets Minimum Requirements
- 56. Window & Door Condition  
M, Meets Minimum Requirements
- 57. Electrical Outlets/Fixtures  
M, Meets Minimum Requirements
- 58. Stairs and Railings  
B, Headroom less than 6'8".  
B, Below Minimum Requirements: - Riser height greater than 8": Uneven risers. Improper landing size. Stair tread (s) less than 9". .
- 59. Smoke Detectors /CO Detectors  
M, Meets Minimum Requirements

# Truth in Sale of Housing Disclosure Report

Address: 3611 BRYANT AVE N Minneapolis, MN



## EVALUATION CODES:

**M** :=Meets Minimum Requirements    **C** :=Comments    **NA** :=Not Applicable/Does Not Apply    **B** :=Below Minimum Requirements    **SC** :=Suggested Correction  
**RRE** :=Repair/Replace, Evaluator Verification Required    **RRP** :=Repair/Replace, Permit/City Inspector Required    **LIC** :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

## Bedroom (Main East)

---

### 60. Walls and Ceiling Components

M, Meets Minimum Requirements

### 61. Evidence of Dampness or Staining

M, Meets Minimum Requirements

### 62. Floor Area & Ceiling Height

M, Meets Minimum Requirements

### 63. Floor Condition

M, Meets Minimum Requirements

### 64. Window Size & Openable Area

M, Meets Minimum Requirements

### 65. Window & Door Condition

M, Meets Minimum Requirements

### 66. Electrical Outlets/Fixtures

C, Other Comment: - Furnishings and stored items restrict access to some possible receptacle locations.

## Bedroom (Main West)

---

### 60. Walls and Ceiling Components

M, Meets Minimum Requirements

### 61. Evidence of Dampness or Staining

M, Meets Minimum Requirements

### 62. Floor Area & Ceiling Height

M, Meets Minimum Requirements

### 63. Floor Condition

M, Meets Minimum Requirements

### 64. Window Size & Openable Area

M, Meets Minimum Requirements

### 65. Window & Door Condition

M, Meets Minimum Requirements

### 66. Electrical Outlets/Fixtures

RRE, Repair/Replace: - Room locked - reinspection required.

# Truth in Sale of Housing Disclosure Report

Address: 3611 BRYANT AVE N Minneapolis, MN



## EVALUATION CODES:

**M** :=Meets Minimum Requirements    **C** :=Comments    **NA** :=Not Applicable/Does Not Apply    **B** :=Below Minimum Requirements    **SC** :=Suggested Correction  
**RRE** :=Repair/Replace, Evaluator Verification Required    **RRP** :=Repair/Replace, Permit/City Inspector Required    **LIC** :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

## Bedroom (2nd)

---

- 60. Walls and Ceiling Components  
M, Meets Minimum Requirements
- 61. Evidence of Dampness or Staining  
M, Meets Minimum Requirements
- 62. Floor Area & Ceiling Height  
B, Below Minimum Requirements: - Ceiling height is less than 7' for continuous 7' width.
- 63. Floor Condition  
M, Meets Minimum Requirements
- 64. Window Size & Openable Area  
M, Meets Minimum Requirements
- 65. Window & Door Condition  
M, Meets Minimum Requirements
- 66. Electrical Outlets/Fixtures  
C, Other Comment: - Furnishings and stored items restrict access to some possible receptacle locations.

## Bedroom (Bsmt North)

---

- 60. Walls and Ceiling Components  
M, Meets Minimum Requirements
- 61. Evidence of Dampness or Staining  
M, Meets Minimum Requirements
- 62. Floor Area & Ceiling Height  
M, Meets Minimum Requirements
- 63. Floor Condition  
M, Meets Minimum Requirements
- 64. Window Size & Openable Area  
M, Meets Minimum Requirements
- 65. Window & Door Condition  
M, Meets Minimum Requirements
- 66. Electrical Outlets/Fixtures  
C, Other Comment: - Furnishings and stored items restrict access to some possible receptacle locations.



# Truth in Sale of Housing Disclosure Report

Address: 3611 BRYANT AVE N Minneapolis, MN



## EVALUATION CODES:

**M** :=Meets Minimum Requirements    **C** :=Comments    **NA** :=Not Applicable/Does Not Apply    **B** :=Below Minimum Requirements    **SC** :=Suggested Correction  
**RRE** :=Repair/Replace, Evaluator Verification Required    **RRP** :=Repair/Replace, Permit/City Inspector Required    **LIC** :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

## Bedroom (Main South)

---

- 60. Walls and Ceiling Components  
M, Meets Minimum Requirements
- 61. Evidence of Dampness or Staining  
M, Meets Minimum Requirements
- 62. Floor Area & Ceiling Height  
M, Meets Minimum Requirements
- 63. Floor Condition  
M, Meets Minimum Requirements
- 64. Window Size & Openable Area  
M, Meets Minimum Requirements
- 65. Window & Door Condition  
M, Meets Minimum Requirements
- 66. Electrical Outlets/Fixtures  
RRE, Repair/Replace: - Room locked - reinspeciton required.

## Porch/Sunroom/Other

---

- 67. Walls and Ceiling Components  
C, Other Comment: - Porch area settled.
- 68. Evidence of Dampness or Staining  
M, Meets Minimum Requirements
- 69. Floor Condition, Area & Ceiling Height  
M, Meets Minimum Requirements
- 70. Window & Door Condition  
M, Meets Minimum Requirements
- 71. Electrical Outlets/Fixtures  
M, Meets Minimum Requirements

# Truth in Sale of Housing Disclosure Report

Address: 3611 BRYANT AVE N Minneapolis, MN



## EVALUATION CODES:

**M** :=Meets Minimum Requirements    **C** :=Comments    **NA** :=Not Applicable/Does Not Apply    **B** :=Below Minimum Requirements    **SC** :=Suggested Correction  
**RRE** :=Repair/Replace, Evaluator Verification Required    **RRP** :=Repair/Replace, Permit/City Inspector Required    **LIC** :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

## Attic Space

---

**Attic Type:** peak

**Attic Is Accessible?:** no

**Estimated Attic Insulated Sq Ft:** 170

- 72. Roof Boards & Rafters / Ventilation  
C, Other Comment: - Area is not accessible.
- 73. Evidence of Dampness or Staining  
M, Meets Minimum Requirements
- 74. Electrical Outlets & Fixtures  
M, Meets Minimum Requirements
- 75. Mechanical Venting  
M, Meets Minimum Requirements

## Attic Space

---

**Attic Type:** slant

**Attic Is Accessible?:** no

**Estimated Attic Insulated Sq Ft:** 350

- 72. Roof Boards & Rafters / Ventilation  
C, Other Comment: - Area is not accessible.
- 73. Evidence of Dampness or Staining  
M, Meets Minimum Requirements
- 74. Electrical Outlets & Fixtures  
M, Meets Minimum Requirements
- 75. Mechanical Venting  
M, Meets Minimum Requirements

# Truth in Sale of Housing Disclosure Report

Address: 3611 BRYANT AVE N Minneapolis, MN



## EVALUATION CODES:

**M** :=Meets Minimum Requirements    **C** :=Comments    **NA** :=Not Applicable/Does Not Apply    **B** :=Below Minimum Requirements    **SC** :=Suggested Correction  
**RRE** :=Repair/Replace, Evaluator Verification Required    **RRP** :=Repair/Replace, Permit/City Inspector Required    **LIC** :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

## Attic Space

---

**Attic Type:** slant

**Attic Is Accessible?:** no

**Estimated Attic Insulated Sq Ft:** 340

72. Roof Boards & Rafters / Ventilation

C, Other Comment: - Area is not accessible.

73. Evidence of Dampness or Staining

M, Meets Minimum Requirements

74. Electrical Outlets & Fixtures

M, Meets Minimum Requirements

75. Mechanical Venting

M, Meets Minimum Requirements

# Truth in Sale of Housing Disclosure Report

Address: 3611 BRYANT AVE N Minneapolis, MN



## EVALUATION CODES:

**M** :=Meets Minimum Requirements    **C** :=Comments    **NA** :=Not Applicable/Does Not Apply    **B** :=Below Minimum Requirements    **SC** :=Suggested Correction  
**RRE** :=Repair/Replace, Evaluator Verification Required    **RRP** :=Repair/Replace, Permit/City Inspector Required    **LIC** :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

## Exterior

### Estimated number of single pane windows without storms: 0

#### 76. Foundation

C, Other Comment: - Vegetation restricts view in areas.

#### 77. Basement Windows

C, Other Comment: - Vegetation restricts view in areas.

#### 78. Drainage (Grade) / Rainleaders

B, Below Minimum Requirements: - Walks cracked/settled in areas.

C, Other Comment: - Landscaping restricts view.

#### 79. Exterior Walls

M, Meets Minimum Requirements

#### 80. Doors (frames/storms/screens/deadbolt locks)

M, Meets Minimum Requirements

#### 81. Windows (frames/storms/screens)

C, Other Comment: - Some peeling paint.

#### 82. Stoops

B, Below Minimum Requirements: - Guardrail less than 36".Missing guardrail on steps with 4 or more risers.

#### 83. Cornice & Trim

M, Meets Minimum Requirements

#### 84. Roof Covering & Flashing

M, Meets Minimum Requirements

#### 85. Chimney

C, Other Comment: - Some missing mortar.

#### 86. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

#### 87. Exterior Plumbing-Backflow Prevention

M, Meets Minimum Requirements

#### 88. Two-Family Dwelling Egress

NA, Not Applicable/Does Not Apply

## Open/Unheated Porch

Not Applicable

# Truth in Sale of Housing Disclosure Report

Address: 3611 BRYANT AVE N Minneapolis, MN



## EVALUATION CODES:

**M** :=Meets Minimum Requirements    **C** :=Comments    **NA** :=Not Applicable/Does Not Apply    **B** :=Below Minimum Requirements    **SC** :=Suggested Correction  
**RRE** :=Repair/Replace, Evaluator Verification Required    **RRP** :=Repair/Replace, Permit/City Inspector Required    **LIC** :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

## Garage

---

- 94. Roof Structure & Covering  
M, Meets Minimum Requirements
- 95. Wall Structure & Covering  
C, Other Comment: - Some damaged siding.  
RRE, Repair/Replace: - Garage locked - interior not viewed.
- 96. Garage Doors  
M, Meets Minimum Requirements
- 97. Automatic Garage Door Opener  
RRE, Repair/Replace: - Garage locked /reinspection required.
- 98. Electrical Outlets/Fixtures  
RRE, Repair/Replace: - Garage locked - reinspection required.

## Miscellaneous

---

- 99. Clutter/Sanitation/Vermin  
M, Meets Minimum Requirements
- 100. Other  
M, Meets Minimum Requirements

## Wall Insulation

---

- Wall Insulation Depth:** 0 inches
  - Wall Insulation Type:** None
-

# Truth in Sale of Housing Disclosure Report

Address: 3611 BRYANT AVE N Minneapolis, MN



## Truth in Housing Repair Notification

City of Minneapolis - Truth in Sale of Housing  
250 South 4th Street, Room 300  
Minneapolis, MN 55415

### Issued To:

3611 Bryant Ave N Land Trust  
13570 Grove Drive, #224  
Maple Grove, MN 55311

6/28/2024

Owner does not have to complete repairs if the house is not sold.

Pursuant to Minneapolis Code of Ordinances, Sections 248.20 and 248.225, the owner may make the repairs. If the owner makes the repairs, a Certificate of Approval (needed for closing) will be issued after the repairs have been inspected and approved. The owner does not have to complete the repairs if the house does not sell. If the owner does not make the repairs, the buyer must sign an acknowledgement of responsibility form (provided by the City) and return it to the City. The buyer has 90 days from closing to complete the repairs. Your prompt cooperation in attending to the repair items is appreciated however, failure to comply by these deadlines may result in legal action.

### REQUIRED REPAIRS

ID	Description	Area	Comment
12	Electrical service installation	Electric	Repair/Replace: - Water meter is in locked bedroom - reinspection required to confirm electric ground.
66	Electrical Outlets/Fixtures	Bedroom(Main West)	Repair/Replace: - Room locked - reinspection required.
66	Electrical Outlets/Fixtures	Bedroom(Main South)	Repair/Replace: - Room locked - reinspection required.
95	Wall Structure & Covering	Garage	Repair/Replace: - Garage locked - interior not viewed.
97	Automatic Garage Door Opener	Garage	Repair/Replace: - Garage locked /reinspection required.
98	Electrical Outlets/Fixtures	Garage	Repair/Replace: - Garage locked - reinspection required.

### SAFETY CHECKS

The systems listed below must be checked by a licensed contractor. The contractor must be licensed by the City of Minneapolis and/or the State of Minnesota in that specific trade to check the work. Return safety check forms to the address above or fax to (612) 673-2437. If "Evaluator Return" is indicated below, the evaluator may return to view the system that was not in operation at the time of the initial evaluation. The evaluator may find additional work is needed on the system.

If the system was repaired or replaced, only a licensed contractor (not the evaluator) can do the safety check. Permits may be needed.

**NONE**

### PERMIT REQUIRED REPAIR

The permit must be pulled before scheduling. Call the inspector listed on the permit to set an appointment. You need to have the permit number to set the appointment. There will be a charge for the permit, which covers the inspection.

**NONE**

### Reinspection Process

When all the items are completed they must be inspected and approved.

Evaluator Name: Dan Brausen

Evaluation Date: 6/28/2024

Page 14 of 15

Evaluation #: 20242795

# Truth in Sale of Housing Disclosure Report

Address: 3611 BRYANT AVE N Minneapolis, MN



## ***For items that need a permit:***

If your notification indicates PERMIT NEEDED, the permit(s) must be pulled and work completed BEFORE the re-inspection takes place. If you are a homeowner occupant of a single family house, you may obtain a permit, if you are not, you must hire a licensed contractor. Bring this notification with you when you apply for permits.

## ***For items that do not need a permit:***

Call the evaluator who did the initial TISH report to re-inspect all the non-permit items. The evaluator's name and phone number are on the bottom of page 1 of the report. There will be a charge for this inspection.

## **Appeal**

This repair notice may be appealed. Section 248.150 of the Minneapolis Code of Ordinances provides that an appeal must be filed in writing within thirty (30) days of the date of this notice accompanied with a \$100 filing fee. If you wish to appeal this order, call (612) 673-5840 for an application.

## **Assistance**

If you need financial assistance to complete these repairs, you may call the Center for Energy and Environment at 612-335-5884.

# Energy Disclosure Report

## Home Profile

**Location:**  
3611 BRYANT AVE N  
Minneapolis, MN 55412

**Year built:** 1917

**House sq. ft.:** 1,872

**Number of stories:** 1.5

**Visit Date:** 6/28/24

## How it Works


The energy score for your home is similar to MPG for a car, but it evaluates the energy performance of the home. The higher the home scores, the lower your energy bills will be.

**Improve your score by completing the energy improvements below.** Homes with the highest scores typically sell for 2-6% more.\*\*

**When you are ready to begin, contact an Energy Advisor at 651-328-6225.** They can answer questions and connect you to helpful resources.

**Financing and rebates are available** from the City of Minneapolis and CenterPoint Energy to help you complete these energy improvements.

## Energy Score



## Home Energy Summary

**Your home is not energy efficient.** This results in a lot of wasted energy when trying to heat and cool your home, which leads to higher energy bills. You have significant opportunities to increase your home's comfort and make cost-effective energy improvements. To learn more visit [mncee.org/TISH](https://mncee.org/TISH) or contact an Energy Advisor.

	Energy Improvements <i>(by priority)</i>	Improvement Points	Typical Cost	Incentives Up To	Yearly Bill Savings
Attic Insulation	Air seal and insulate your attic	28	\$2,500-\$6,000	\$2,600 rebate; \$2,000 tax credit	\$150-\$300
Wall Insulation	Insulate your exterior walls	26	\$2,500-\$6,000	\$3,000 rebate; \$2,000 tax credit	\$200-\$400
Heating System	Energy Badge earned! The furnace is efficient.	_____	_____	_____	_____
Storm Windows	All single-pane windows have storm windows.	_____	_____	_____	_____





# Next Step:

## Contact an Energy Advisor



Mike



Kat

651-328-6225 or  
[energydisclosure@mncee.org](mailto:energydisclosure@mncee.org)  
[mncee.org/TISH](http://mncee.org/TISH)

## An Energy Advisor can help:



Answer your questions



Connect you to financing and utility rebates



Refer you to trusted contractors

*The energy advisor service is provided by CEE with funding from CenterPoint Energy.*

# Prioritized Energy Improvements

### Current attic insulation depth:

No access

### Recommended attic insulation depth:

16 inches

## Attic Insulation

28 improvement points

**Air seal and insulate your attic** to improve the comfort of your home. I was not able to fully inspect your attic. However, research indicates that homes of a similar age and construction typically are not properly insulated or air-sealed. This can be especially true with half story homes like yours. Do this work to prevent ice dams, lower energy bills and increase your home's comfort and durability. Contact an Energy Advisor to learn more and get help with next steps.

### Typical Cost:\*

\$2,500–\$6,000

### Yearly Bill Savings:\*

\$150–\$300

### Incentives Up To:

\$2,600 rebate;

\$2,000 tax credit

### Current wall insulation depth:

0 inches

### Recommended wall insulation depth:

3.5 inches

## Wall Insulation

26 improvement points

**Insulate your walls.** Walls with little insulation are cold and drafty. Dense packing your walls with insulation will reduce home drafts and improve home comfort. This will also reduce energy waste and save money. Contact an Energy Advisor to learn more and get help with next steps.

### Typical Cost:\*

\$2,500–\$6,000

### Yearly Bill Savings:\*

\$200–\$400

### Incentives Up To:

\$3,000 rebate;

\$2,000 tax credit

### About heat pumps:

- Energy efficient cooling
- Low-emissions heating
- Can pair with a furnace

## Heating System

The furnace is energy efficient and within the typical 20-year service lifespan. When it is time to replace it, choose another high-efficiency furnace to keep energy bills low.

You can install a heat pump at the same time as a new furnace. A heat pump provides high-efficiency heating and cooling. A heat pump plus a furnace (called a dual fuel or hybrid system) can significantly reduce household emissions. Visit [electrifyeverythingmn.org](http://electrifyeverythingmn.org) to learn more about equipment options that benefit indoor air quality and the climate.

### Typical Heat Pump Cost:\*



\$12,000–\$24,000

### Incentives Up To:

\$1,500 rebate;

\$2,000 tax credit

# This home has an energy efficient heating system.



## Benefits

Lower energy bills

Healthier indoor climate



## This home has an energy efficient **heating system**.

The energy inspection of this home found an efficient heating system. The benefits include:

**Lower energy bills** — efficient heating systems save up to \$300 a year.


**Healthier indoor climate** — efficient heating systems improve indoor air quality by safely managing exhaust.

For more information visit [mncee.org/tish](http://mncee.org/tish).

Curious about additional ways to save energy in your home?  
Contact an Energy Advisor today.

651-328-6225 or [energydisclosure@mncee.org](mailto:energydisclosure@mncee.org)

### Energy Badge Earned



Energy Badges are delivered by Center For Energy And Environment, a local energy nonprofit.