

# Minnesota Lead Testers

952-200-5044

## Client Information

Performance Equity LLC  
8362 Tamarack vlg, ste  
119-308

Woodburv mn 55125

**Contact:** Jon 715-220-7467



*Paul Nygren*  
Director, Env. Health Div.

**MDH** LEAD  
DEPARTMENT OF HEALTH Risk Assessor

Licensed by:  
State of Minnesota  
Department of Health  
**License No. LR3633**  
Expires 11/11/2017

**Paul Nygren**  
6225 207th Ave NE  
Wyoming, MN 55092

## XRF Test Results

Time of Test:	8:06 AM	12/28/16
---------------	---------	----------

## Test Site Information

**Owner:** THOMAS AVENUE APARTMENTS LLC

**Age of Property:** 1928

**Address:** 2601 Golden Valley Rd  
Minneapolis MN 55411



## Minnesota Lead Testers

6225 207th Ave. NE, Wyoming MN 55092  
952-200-5044 Paul Nygren, Owner

**Firm License #** LF 3614

**XRF Analyzer Manufacture:** Innov-X

**Model:** Delta LBP-4000 **Serial #** 560309

# Minnesota Lead Testers

952-200-5044

**These readings are for calibration purposes only, not part of test results.**

Start	8:06 AM	NIST Check - Passed
Finish	3:09 PM	NIST Check - Passed

- = no or minute amounts of lead present
- = 0.2 - .99 Micrograms per square cm of lead present
- = 1.0 Microgram or greater per square cm of lead present: **Lead safe practices required if disturbing these surfaces**

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
▼ (blank)												
▼ Laundry												
PASS	0	12/28/16	8:06 AM	#3	Laundry	LL	North	Ceiling	Center	White	Plaster	
PASS	0.02	12/28/16	8:07 AM	#4	Laundry	LL	North	Wall	Center	Gray	Plaster	
PASS	0.03	12/28/16	8:08 AM	#5	Laundry	LL	West	Wall	Center	Gray	Plaster	
PASS	0	12/28/16	8:08 AM	#6	Laundry	LL	South	Wall	Upper	Gray	Plaster	
PASS	0	12/28/16	8:09 AM	#7	Laundry	LL	East	Wall	Lower	Gray	Plaster	
FAIL	4.8	12/28/16	8:09 AM	#8	Laundry	LL	West	Window casing	Center	White	Wood	
FAIL	3.15	12/28/16	8:10 AM	#9	Laundry	LL	North	Window casing	Center	White	Wood	
FAIL	2.87	12/28/16	8:10 AM	#10	Laundry	LL	South	Door casing	Left	White	Wood	
FAIL	2.99	12/28/16	8:10 AM	#11	Laundry	LL	South	Door	Right	White	Wood	
FAIL	2.82	12/28/16	8:11 AM	#12	Laundry	LL	East	Door	Center	White	Wood	
FAIL	3.34	12/28/16	8:11 AM	#13	Laundry	LL	East	Door jamb	Center	White	Wood	
PASS	0.37	12/28/16	8:12 AM	#14	Laundry	LL	East	Floor	Center	Red	Concrete	
▼ Electric rm												
PASS	0	12/28/16	8:13 AM	#15	Electric rm	LL	East	Ceiling	Center	White	Plaster	
PASS	0	12/28/16	8:13 AM	#16	Electric rm	LL	West	Wall	Center	White	Plaster	
PASS	0	12/28/16	8:14 AM	#17	Electric rm	LL	South	Wall	Center	White	Plaster	
PASS	0	12/28/16	8:14 AM	#18	Electric rm	LL	East	Wall	Upper	White	Plaster	

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
FAIL	4.98	12/28/16	8:15 AM	#19	Electric rm	LL	North	Wall	Lower	Green	Plaster	
PASS	0	12/28/16	8:15 AM	#20	Electric rm	LL	North	Wall	Upper	White	Plaster	
FAIL	2.69	12/28/16	8:15 AM	#21	Electric rm	LL	East	Door	Center	Gray	Wood	
FAIL	2.54	12/28/16	8:16 AM	#22	Electric rm	LL	East	Door casing	Center	Gray	Wood	
▼ Storage												
PASS	0	12/28/16	8:17 AM	#23	Storage	LL	East	Ceiling	Center	White	Plaster	
PASS	0	12/28/16	8:17 AM	#24	Storage	LL	North	Wall	Center	White	Plaster	
PASS	0	12/28/16	8:18 AM	#25	Storage	LL	South	Wall	Center	White	Plaster	
PASS	0	12/28/16	8:18 AM	#26	Storage	LL	East	Wall	Upper	White	Plaster	
PASS	0	12/28/16	8:18 AM	#27	Storage	LL	West	Wall	Lower	White	Plaster	
FAIL	5	12/28/16	8:19 AM	#28	Storage	LL	West	Window sash	Center	Gray	Wood	
FAIL	2.48	12/28/16	8:19 AM	#29	Storage	LL	East	Door	Center	Gray	Wood	
FAIL	3.28	12/28/16	8:20 AM	#30	Storage	LL	South	Door	Center	Gray	Wood	
FAIL	2.65	12/28/16	8:20 AM	#31	Storage	LL	North	Door	Center	Gray	Wood	
▼ Office												
FAIL	1.39	12/28/16	9:30 AM	#135	Office	LL	East	Ceiling	Center	White	Plaster	
FAIL	1.27	12/28/16	9:31 AM	#136	Office	LL	North	Wall	Center	White	Plaster	
PASS	0.44	12/28/16	9:32 AM	#137	Office	LL	South	Wall	Center	White	Plaster	
PASS	0	12/28/16	9:32 AM	#138	Office	LL	West	Wall	Upper	White	Plaster	
PASS	0	12/28/16	9:33 AM	#139	Office	LL	East	Wall	Lower	White	Plaster	
PASS	0.02	12/28/16	9:34 AM	#140	Office	LL	East	Window stool	Center	White	Wood	
PASS	0.01	12/28/16	9:34 AM	#141	Office	LL	North	Window casing	Center	White	Wood	
PASS	0.14	12/28/16	9:35 AM	#142	Office	LL	East	Door casing	Center	White	Wood	
PASS	0.01	12/28/16	9:35 AM	#143	Office	LL	East	Door casing	Lower	White	Wood	
PASS	0.02	12/28/16	9:36 AM	#144	Office	LL	East	Door	Center	Yellow	Metal	
PASS	0.01	12/28/16	9:37 AM	#145	Office	LL	South	Door jamb	Center	White	Wood	
▼ Kitchen												
FAIL	1.83	12/28/16	9:38 AM	#146	Kitchen	LL	South	Ceiling	Center	White	Plaster	
PASS	0	12/28/16	9:38 AM	#147	Kitchen	LL	South	Wall	Center	White	Plaster	
FAIL	1.41	12/28/16	9:38 AM	#148	Kitchen	LL	North	Wall	Center	White	Plaster	
FAIL	1.61	12/28/16	9:39 AM	#149	Kitchen	LL	West	Wall	Upper	White	Plaster	
FAIL	1.99	12/28/16	9:39 AM	#150	Kitchen	LL	East	Wall	Lower	White	Plaster	
PASS	0.35	12/28/16	9:40 AM	#151	Kitchen	LL	East	Window casing	Center	White	Wood	
PASS	0.41	12/28/16	9:40 AM	#152	Kitchen	LL	South	Door casing	Center	White	Wood	
PASS	0.63	12/28/16	9:41 AM	#153	Kitchen	LL	North	Door casing	Center	White	Wood	
PASS	0.62	12/28/16	9:41 AM	#154	Kitchen	LL	West	Baseboard	Center	White	Wood	
PASS	0.68	12/28/16	9:42 AM	#155	Kitchen	LL	North	Radiator	Right	White	Metal	

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
▼ Bathroom												
PASS	0.78	12/28/16	9:43 AM	#156	Bathroom	LL	North	Ceiling	Center	White	Plaster	
PASS	0	12/28/16	9:43 AM	#157	Bathroom	LL	North	Wall	Center	White	Plaster	
PASS	0.18	12/28/16	9:44 AM	#158	Bathroom	LL	South	Wall	Center	White	Plaster	
PASS	0.65	12/28/16	9:44 AM	#159	Bathroom	LL	West	Wall	Upper	White	Plaster	
FAIL	1.02	12/28/16	9:45 AM	#160	Bathroom	LL	East	Wall	Lower	White	Plaster	
PASS	0.02	12/28/16	9:45 AM	#161	Bathroom	LL	East	Window casing	Center	White	Wood	
PASS	0.01	12/28/16	9:46 AM	#162	Bathroom	LL	North	Door casing	Center	White	Wood	
PASS	0.01	12/28/16	9:46 AM	#163	Bathroom	LL	North	Door	Center	White	Wood	
▼ (blank)												
FAIL	1.13	12/28/16	1:26 PM	31-Avg(3)		2nd						
▼ common												
▼ Hall												
PASS	0	12/28/16	8:21 AM	#32	Hall	LL	North	Ceiling	Center	White	Plaster	common
PASS	0	12/28/16	8:22 AM	#33	Hall	LL	West	Wall	Center	White	Plaster	common
PASS	0.01	12/28/16	8:22 AM	#34	Hall	LL	East	Wall	Center	White	Plaster	common
PASS	0	12/28/16	8:23 AM	#35	Hall	LL	South	Wall	Upper	White	Plaster	common
PASS	0	12/28/16	8:23 AM	#36	Hall	LL	North	Wall	Lower	White	Plaster	common
FAIL	2.38	12/28/16	8:23 AM	#37	Hall	LL	North	Door	Center	White	Metal	common
FAIL	2.52	12/28/16	8:24 AM	#38	Hall	LL	South	Door casing	Center	White	Metal	common
FAIL	2.41	12/28/16	8:24 AM	#39	Hall	LL	West	Door	Left	Gray	Metal	common
FAIL	2.98	12/28/16	8:25 AM	#40	Hall	LL	East	Door casing	Right	White	Wood	common
FAIL	3.2	12/28/16	8:25 AM	#41	Hall	LL	East	Door	Center	White	Wood	common
▼ Hall 2												
PASS	0.73	12/28/16	9:01 AM	#96	Hall 2	1st	North	Ceiling	Center	White	Plaster	common
PASS	0.04	12/28/16	9:02 AM	#97	Hall 2	1st	East	Wall	Center	White	Plaster	common
PASS	0.07	12/28/16	9:03 AM	#98	Hall 2	1st	West	Wall	Center	White	Plaster	common
PASS	0.03	12/28/16	9:03 AM	#99	Hall 2	1st	North	Wall	Upper	White	Plaster	common
PASS	0.12	12/28/16	9:04 AM	#100	Hall 2	1st	South	Wall	Lower	White	Plaster	common
FAIL	1.34	12/28/16	9:04 AM	#101	Hall 2	1st	South	Door	Center	White	Metal	common
PASS	0.1	12/28/16	9:05 AM	#102	Hall 2	1st	South	Door casing	Center	White	Wood	common
PASS	0.02	12/28/16	9:05 AM	#103	Hall 2	1st	East	Door casing	Right	Brown	Wood	common
PASS	0.03	12/28/16	9:06 AM	#104	Hall 2	1st	East	Door	Left	Brown	Wood	common
PASS	0.03	12/28/16	9:07 AM	#105	Hall 2	1st	West	Door casing	Right	Brown	Wood	common
PASS	0.03	12/28/16	9:07 AM	#106	Hall 2	1st	West	Door	Left	Brown	Wood	common
PASS	0.03	12/28/16	9:08 AM	#107	Hall 2	1st	West	Baseboard	Center	Brown	Wood	common
FAIL	1.31	12/28/16	9:09 AM	#108	Hall 2	1st	West	Radiator	Right	White	Metal	common



PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.72	12/28/16	9:09 AM	#109	Hall 2	1st	West	Radiator	Right	White	Metal	common
▼ Hall 3												
PASS	0.05	12/28/16	9:10 AM	#110	Hall 3	2nd	West	Ceiling	Center	White	Plaster	common
PASS	0.04	12/28/16	9:11 AM	#111	Hall 3	2nd	West	Wall	Center	White	Plaster	common
PASS	0.05	12/28/16	9:12 AM	#112	Hall 3	2nd	East	Wall	Center	White	Plaster	common
PASS	0.04	12/28/16	9:12 AM	#113	Hall 3	2nd	North	Wall	Upper	White	Plaster	common
PASS	0.05	12/28/16	9:13 AM	#114	Hall 3	2nd	South	Wall	Lower	White	Plaster	common
FAIL	1	12/28/16	9:13 AM	#115	Hall 3	2nd	South	Door	Center	White	Metal	common
PASS	0.33	12/28/16	9:14 AM	#116	Hall 3	2nd	South	Door casing	Center	White	Wood	common
PASS	0.04	12/28/16	9:15 AM	#117	Hall 3	2nd	West	Door casing	Left	Brown	Wood	common
PASS	0.03	12/28/16	9:16 AM	#118	Hall 3	2nd	West	Door	Right	Brown	Wood	common
PASS	0.03	12/28/16	9:17 AM	#119	Hall 3	2nd	East	Door casing	Left	Brown	Wood	common
PASS	0.03	12/28/16	9:17 AM	#120	Hall 3	2nd	East	Door	Right	Brown	Wood	common
PASS	0.03	12/28/16	9:18 AM	#121	Hall 3	2nd	East	Baseboard	Center	Brown	Wood	common
▼ Outside												
FAIL	1.23	12/28/16	9:20 AM	#122	Outside	1st	North	Door	Center	Yellow	Wood	common
FAIL	4.91	12/28/16	9:21 AM	#123	Outside	1st	North	Door casing	Center	Brown	Wood	common
FAIL	5	12/28/16	9:21 AM	#124	Outside	1st	North	Window casing	Left	Brown	Wood	common
FAIL	5	12/28/16	9:22 AM	#125	Outside	LL	North	Window casing	Right	Brown	Wood	common
FAIL	1.96	12/28/16	9:22 AM	#126	Outside	1st	West	Window casing	Left	Brown	Wood	common
FAIL	1.45	12/28/16	9:23 AM	#127	Outside	1st	West	Window casing	Right	Brown	Wood	common
FAIL	1.23	12/28/16	9:24 AM	#128	Outside	1st	South	Window casing	Left	Brown	Wood	common
FAIL	5	12/28/16	9:24 AM	#129	Outside	LL	South	Window casing	Right	Brown	Wood	common
PASS	0.01	12/28/16	9:25 AM	#130	Outside	LL	South	Door casing	Center	Brown	Wood	common
PASS	0	12/28/16	9:25 AM	#131	Outside	LL	South	Door	Center	Yellow	Metal	common
FAIL	5	12/28/16	9:26 AM	#132	Outside	LL	East	Window casing	Left	Brown	Wood	common
FAIL	5	12/28/16	9:27 AM	#133	Outside	LL	East	Window casing	Right	Brown	Wood	common
FAIL	2.13	12/28/16	9:27 AM	#134	Outside	1st	East	Window casing	Center	Brown	Wood	common
▼ common south												
▼ Staircase												
PASS	0	12/28/16	8:27 AM	#42	Staircase	LL	North	Wall	Center	White	Plaster	common south
PASS	0.01	12/28/16	8:27 AM	#43	Staircase	LL	South	Wall	Center	White	Plaster	common south
PASS	0	12/28/16	8:28 AM	#44	Staircase	LL	East	Wall	Upper	White	Plaster	common south
FAIL	1.1	12/28/16	8:28 AM	#45	Staircase	LL	West	Wall	Lower	Gray	Plaster	common south
FAIL	2.07	12/28/16	8:29 AM	#46	Staircase	LL	North	Door casing	Center	Gray	Metal	common south
FAIL	1.65	12/28/16	8:29 AM	#47	Staircase	LL	North	Stair riser	Center	Gray	Metal	common south
FAIL	1.78	12/28/16	8:30 AM	#48	Staircase	LL	North	Stair newel	Center	Gray	Metal	common south

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
FAIL	1.89	12/28/16	8:30 AM	#49	Staircase	LL	North	Stair riser	Center	Gray	Concrete	common south
PASS	0	12/28/16	8:31 AM	#50	Staircase	LL	South	Door	Center	Green	Metal	common south
PASS	0	12/28/16	8:32 AM	#51	Staircase	LL	South	Door casing	Center	Green	Metal	common south
PASS	0	12/28/16	8:33 AM	#52	Staircase	1st	South	Ceiling	Center	White	Plaster	common south
PASS	0	12/28/16	8:33 AM	#53	Staircase	1st	North	Wall	Center	White	Plaster	common south
PASS	0	12/28/16	8:34 AM	#54	Staircase	1st	East	Wall	Center	White	Plaster	common south
FAIL	1.12	12/28/16	8:34 AM	#55	Staircase	1st	West	Wall	Lower	Gray	Plaster	common south
PASS	0.86	12/28/16	8:35 AM	#56	Staircase	1st	South	Wall	Upper	Gray	Plaster	common south
FAIL	2.93	12/28/16	8:35 AM	#57	Staircase	1st	South	Door	Upper	Gray	Wood	common south
FAIL	2.2	12/28/16	8:36 AM	#58	Staircase	1st	North	Door	Center	Gray	Metal	common south
FAIL	1.51	12/28/16	8:36 AM	#59	Staircase	1st	South	Stair newel	Center	Gray	Metal	common south
FAIL	5	12/28/16	8:36 AM	#60	Staircase	1st	South	Stair riser	Center	Gray	Concrete	common south
PASS	0	12/28/16	8:38 AM	#61	Staircase	2nd	South	Ceiling	Center	White	Plaster	common south
PASS	0	12/28/16	8:39 AM	#62	Staircase	2nd	North	Wall	Center	White	Plaster	common south
PASS	0	12/28/16	8:39 AM	#63	Staircase	2nd	East	Wall	Center	White	Plaster	common south
FAIL	1.03	12/28/16	8:40 AM	#64	Staircase	2nd	West	Wall	Lower	Gray	Plaster	common south
FAIL	2.69	12/28/16	8:40 AM	#65	Staircase	2nd	North	Door	Center	Gray	Metal	common south
▼ common north												
▼ Staircase												
FAIL	1.14	12/28/16	8:41 AM	#66	Staircase	2nd	North	Ceiling	Center	White	Plaster	common north
PASS	0.04	12/28/16	8:42 AM	#67	Staircase	2nd	South	Wall	Center	White	Plaster	common north
PASS	0.07	12/28/16	8:43 AM	#68	Staircase	2nd	East	Wall	Center	White	Plaster	common north
PASS	0.06	12/28/16	8:43 AM	#69	Staircase	2nd	West	Wall	Upper	White	Plaster	common north
PASS	0.52	12/28/16	8:44 AM	#70	Staircase	2nd	North	Wall	Lower	White	Plaster	common north
PASS	0.02	12/28/16	8:44 AM	#71	Staircase	2nd	North	Window casing	Center	Brown	Wood	common north
PASS	0.71	12/28/16	8:45 AM	#72	Staircase	2nd	North	Window sash	Center	Brown	Wood	common north
PASS	0.44	12/28/16	8:46 AM	#73	Staircase	2nd	North	Stair newel	Center	Brown	Wood	common north
PASS	0.04	12/28/16	8:46 AM	#74	Staircase	2nd	East	Stair stringer	Center	Brown	Wood	common north
PASS	0.04	12/28/16	8:47 AM	#75	Staircase	1st	East	Stair newel	Center	Brown	Wood	common north
PASS	0.04	12/28/16	8:48 AM	#76	Staircase	1st	East	Wall	Center	White	Plaster	common north
PASS	0.06	12/28/16	8:48 AM	#77	Staircase	1st	West	Wall	Center	White	Plaster	common north
PASS	0.03	12/28/16	8:49 AM	#78	Staircase	1st	North	Door casing	Center	Brown	Wood	common north
PASS	0.04	12/28/16	8:50 AM	#79	Staircase	1st	North	Door	Center	Brown	Wood	common north
PASS	0.05	12/28/16	8:51 AM	#80	Staircase	LL	North	Door	Center	Brown	Wood	common north
FAIL	2.29	12/28/16	8:51 AM	#81	Staircase	LL	South	Door	Center	Gray	Metal	common north
PASS	0	12/28/16	8:52 AM	#82	Staircase	LL	South	Ceiling	Center	White	Plaster	common north
PASS	0	12/28/16	8:53 AM	#83	Staircase	LL	South	Wall	Center	White	Plaster	common north

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0	12/28/16	8:53 AM	#84	Staircase	LL	East	Wall	Center	White	Plaster	common north
FAIL	1.21	12/28/16	8:54 AM	#85	Staircase	LL	West	Wall	Lower	Gray	Plaster	common north
FAIL	2.83	12/28/16	8:54 AM	#86	Staircase	LL	West	Stair riser	Center	Gray	Concrete	common north
▼ Foyer												
PASS	0	12/28/16	8:55 AM	#87	Foyer	1st	West	Ceiling	Center	Pink	Plaster	common north
PASS	0.11	12/28/16	8:56 AM	#88	Foyer	1st	West	Wall	Upper	Pink	Plaster	common north
PASS	0.67	12/28/16	8:57 AM	#89	Foyer	1st	East	Wall	Lower	Green	Plaster	common north
PASS	0.55	12/28/16	8:57 AM	#90	Foyer	1st	North	Wall	Center	Green	Plaster	common north
PASS	0.48	12/28/16	8:58 AM	#91	Foyer	1st	South	Wall	Center	Green	Plaster	common north
PASS	0.42	12/28/16	8:59 AM	#92	Foyer	1st	South	Door	Right	Brown	Metal	common north
PASS	0.05	12/28/16	8:59 AM	#93	Foyer	1st	South	Door casing	Left	Brown	Wood	common north
PASS	0.05	12/28/16	9:00 AM	#94	Foyer	1st	North	Door casing	Center	Brown	Wood	common north
FAIL	4.94	12/28/16	9:00 AM	#95	Foyer	1st	North	Door	Center	Brown	Wood	common north
▼ unit 9												
▼ Bdrm 1												
PASS	0	12/28/16	10:16 AM	#164	Bdrm 1	LL	North	Ceiling	Center	White	Plaster	unit 9
PASS	0	12/28/16	10:17 AM	#165	Bdrm 1	LL	North	Wall	Center	White	Plaster	unit 9
PASS	0	12/28/16	10:17 AM	#166	Bdrm 1	LL	South	Wall	Center	White	Plaster	unit 9
PASS	0	12/28/16	10:17 AM	#167	Bdrm 1	LL	West	Wall	Upper	White	Plaster	unit 9
PASS	0	12/28/16	10:17 AM	#168	Bdrm 1	LL	East	Wall	Lower	White	Plaster	unit 9
PASS	0.14	12/28/16	10:18 AM	#169	Bdrm 1	LL	East	Window casing	Center	White	Wood	unit 9
FAIL	1.8	12/28/16	10:18 AM	#170	Bdrm 1	LL	South	Window sash	Center	White	Wood	unit 9
PASS	0.2	12/28/16	10:19 AM	#171	Bdrm 1	LL	West	Door	Left	White	Wood	unit 9
PASS	0.38	12/28/16	10:19 AM	#172	Bdrm 1	LL	West	Door casing	Right	White	Wood	unit 9
PASS	0.06	12/28/16	10:20 AM	#173	Bdrm 1	LL	North	Baseboard	Center	White	Wood	unit 9
PASS	0	12/28/16	10:20 AM	#174	Bdrm 1	LL	North	Floor	Center	Stain	Wood	unit 9
PASS	0.04	12/28/16	10:21 AM	#175	Bdrm 1	LL	West	Closet	Center	White	Plaster	unit 9
▼ Bathroom												
PASS	0	12/28/16	10:22 AM	#176	Bathroom	LL	North	Wall	Center	White	Plaster	unit 9
FAIL	2.23	12/28/16	10:22 AM	#177	Bathroom	LL	West	Wall	Center	White	Plaster	unit 9
PASS	0	12/28/16	10:22 AM	#178	Bathroom	LL	East	Wall	Upper	White	Plaster	unit 9
PASS	0	12/28/16	10:23 AM	#179	Bathroom	LL	South	Wall	Upper	White	Plaster	unit 9
PASS	0.15	12/28/16	10:23 AM	#180	Bathroom	LL	South	Window stool	Center	White	Wood	unit 9
FAIL	5	12/28/16	10:24 AM	#181	Bathroom	LL	South	Bathtub	Center	White	Metal	unit 9
PASS	0.16	12/28/16	10:24 AM	#182	Bathroom	LL	East	Radiator	Center	White	Metal	unit 9
PASS	0.12	12/28/16	10:25 AM	#183	Bathroom	LL	North	Door header	Center	White	Wood	unit 9
PASS	0	12/28/16	10:25 AM	#184	Bathroom	LL	West	Cabinet	Center	White	Wood	unit 9

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
▼ Hall												
PASS	0.18	12/28/16	10:26 AM	#185	Hall	LL	East	Cabinet	Center	White	Wood	unit 9
PASS	0.16	12/28/16	10:27 AM	#186	Hall	LL	North	Door casing	Center	White	Wood	unit 9
PASS	0.15	12/28/16	10:27 AM	#187	Hall	LL	West	Door	Center	White	Wood	unit 9
PASS	0	12/28/16	10:27 AM	#188	Hall	LL	West	Ceiling	Center	White	Plaster	unit 9
PASS	0	12/28/16	10:28 AM	#189	Hall	LL	North	Wall	Center	White	Plaster	unit 9
PASS	0	12/28/16	10:28 AM	#190	Hall	LL	South	Wall	Center	White	Plaster	unit 9
PASS	0	12/28/16	10:28 AM	#191	Hall	LL	East	Wall	Upper	White	Plaster	unit 9
PASS	0	12/28/16	10:29 AM	#192	Hall	LL	West	Wall	Lower	White	Plaster	unit 9
PASS	0.16	12/28/16	10:29 AM	#193	Hall	LL	West	Baseboard	Center	White	Wood	unit 9
▼ Living room												
PASS	0.01	12/28/16	10:30 AM	#194	Living room	LL	West	Ceiling	Center	White	Plaster	unit 9
PASS	0	12/28/16	10:30 AM	#195	Living room	LL	North	Wall	Center	White	Plaster	unit 9
PASS	0	12/28/16	10:31 AM	#196	Living room	LL	South	Wall	Center	White	Plaster	unit 9
PASS	0	12/28/16	10:31 AM	#197	Living room	LL	West	Wall	Upper	White	Plaster	unit 9
PASS	0	12/28/16	10:31 AM	#198	Living room	LL	East	Wall	Lower	White	Plaster	unit 9
FAIL	3.23	12/28/16	10:32 AM	#199	Living room	LL	East	Window sash	Center	White	Wood	unit 9
PASS	0.03	12/28/16	10:32 AM	#200	Living room	LL	West	Door casing	Center	White	Wood	unit 9
PASS	0.08	12/28/16	10:33 AM	#201	Living room	LL	West	Baseboard	Center	White	Wood	unit 9
▼ Kitchen												
PASS	0.01	12/28/16	10:34 AM	#202	Kitchen	LL	West	Ceiling	Center	White	Plaster	unit 9
PASS	0	12/28/16	10:34 AM	#203	Kitchen	LL	North	Wall	Center	White	Plaster	unit 9
PASS	0	12/28/16	10:34 AM	#204	Kitchen	LL	West	Wall	Center	White	Plaster	unit 9
PASS	0	12/28/16	10:35 AM	#205	Kitchen	LL	South	Wall	Upper	White	Plaster	unit 9
PASS	0	12/28/16	10:35 AM	#206	Kitchen	LL	East	Wall	Lower	White	Plaster	unit 9
PASS	0.1	12/28/16	10:36 AM	#207	Kitchen	LL	East	Window casing	Center	White	Metal	unit 9
PASS	0.02	12/28/16	10:36 AM	#208	Kitchen	LL	North	Radiator	Center	White	Metal	unit 9
PASS	0	12/28/16	10:37 AM	#209	Kitchen	LL	North	Door casing	Center	White	Wood	unit 9
PASS	0	12/28/16	10:37 AM	#210	Kitchen	LL	North	Baseboard	Center	White	Wood	unit 9
PASS	0	12/28/16	10:38 AM	#211	Kitchen	LL	North	Chair rail	Center	White	Wood	unit 9
▼ Bdrm 2												
PASS	0.01	12/28/16	10:38 AM	#212	Bdrm 2	LL	North	Ceiling	Center	White	Plaster	unit 9
PASS	0	12/28/16	10:38 AM	#213	Bdrm 2	LL	North	Wall	Center	White	Plaster	unit 9
PASS	0.01	12/28/16	10:39 AM	#214	Bdrm 2	LL	South	Wall	Center	White	Plaster	unit 9
PASS	0.01	12/28/16	10:39 AM	#215	Bdrm 2	LL	West	Wall	Upper	White	Plaster	unit 9
PASS	0.01	12/28/16	10:40 AM	#216	Bdrm 2	LL	East	Wall	Lower	White	Plaster	unit 9
FAIL	3.06	12/28/16	10:40 AM	#217	Bdrm 2	LL	East	Window sash	Center	White	Wood	unit 9



PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.17	12/28/16	10:41 AM	#218	Bdrm 2	LL	South	Door	Center	White	Wood	unit 9
PASS	0.12	12/28/16	10:41 AM	#219	Bdrm 2	LL	South	Baseboard	Center	White	Wood	unit 9
PASS	0	12/28/16	10:42 AM	#220	Bdrm 2	LL	North	Closet	Center	White	Plaster	unit 9
▼ unit 4												
▼ Bdrm 1												
PASS	0	12/28/16	10:45 AM	#221	Bdrm 1	1st	North	Ceiling	Center	White	Plaster	unit 4
PASS	0.01	12/28/16	10:45 AM	#222	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 4
PASS	0.01	12/28/16	10:46 AM	#223	Bdrm 1	1st	South	Wall	Center	White	Plaster	unit 4
PASS	0.01	12/28/16	10:46 AM	#224	Bdrm 1	1st	East	Wall	Upper	White	Plaster	unit 4
PASS	0.01	12/28/16	10:47 AM	#225	Bdrm 1	1st	West	Wall	Lower	White	Plaster	unit 4
PASS	0.2	12/28/16	10:48 AM	#226	Bdrm 1	1st	West	Window casing	Center	White	Wood	unit 4
PASS	0.48	12/28/16	10:48 AM	#227	Bdrm 1	1st	South	Window sash	Center	White	Wood	unit 4
PASS	0.01	12/28/16	10:49 AM	#228	Bdrm 1	1st	East	Door	Right	White	Wood	unit 4
PASS	0.24	12/28/16	10:50 AM	#229	Bdrm 1	1st	East	Door jamb	Left	White	Wood	unit 4
PASS	0.18	12/28/16	10:50 AM	#230	Bdrm 1	1st	South	Baseboard	Center	White	Wood	unit 4
PASS	0	12/28/16	10:51 AM	#231	Bdrm 1	1st	South	Floor	Center	Stain	Wood	unit 4
PASS	0.02	12/28/16	10:51 AM	#232	Bdrm 1	1st	East	Closet	Center	White	Plaster	unit 4
PASS	0	12/28/16	10:52 AM	#233	Bdrm 1	1st	East	Wall	Center	White	Plaster	unit 4
FAIL	1.88	12/28/16	10:53 AM	#234	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 4
PASS	0	12/28/16	10:53 AM	#235	Bdrm 1	1st	West	Wall	Lower	White	Plaster	unit 4
PASS	0.01	12/28/16	10:53 AM	#236	Bdrm 1	1st	South	Wall	Upper	White	Plaster	unit 4
PASS	0.01	12/28/16	10:54 AM	#237	Bdrm 1	1st	South	Window casing	Center	White	Wood	unit 4
PASS	0.39	12/28/16	10:54 AM	#238	Bdrm 1	1st	North	Door casing	Center	White	Wood	unit 4
PASS	0.76	12/28/16	10:55 AM	#239	Bdrm 1	1st	East	Cabinet	Center	White	Wood	unit 4
PASS	0.34	12/28/16	10:55 AM	#240	Bdrm 1	1st	West	Chair rail	Center	White	Wood	unit 4
FAIL	5	12/28/16	10:56 AM	#241	Bdrm 1	1st	South	Bathtub	Center	White	Metal	unit 4
PASS	0.46	12/28/16	10:56 AM	#242	Bdrm 1	1st	West	Radiator	Center	White	Metal	unit 4
▼ Hall												
PASS	0.01	12/28/16	10:57 AM	#243	Hall	1st	West	Ceiling	Center	White	Plaster	unit 4
PASS	0.01	12/28/16	10:58 AM	#244	Hall	1st	North	Wall	Center	White	Plaster	unit 4
PASS	0.01	12/28/16	10:58 AM	#245	Hall	1st	East	Wall	Center	White	Plaster	unit 4
PASS	0.01	12/28/16	10:58 AM	#246	Hall	1st	South	Wall	Lower	White	Plaster	unit 4
PASS	0.01	12/28/16	10:59 AM	#247	Hall	1st	West	Wall	Upper	White	Plaster	unit 4
PASS	0.21	12/28/16	11:00 AM	#248	Hall	1st	West	Door casing	Right	White	Wood	unit 4
PASS	0.23	12/28/16	11:00 AM	#249	Hall	1st	North	Door jamb	Center	White	Wood	unit 4
PASS	0.15	12/28/16	11:01 AM	#250	Hall	1st	South	Baseboard	Center	White	Wood	unit 4
▼ Living room												

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.01	12/28/16	11:01 AM	#251	Living room	1st	South	Ceiling	Center	White	Plaster	unit 4
PASS	0.12	12/28/16	11:02 AM	#252	Living room	1st	North	Wall	Center	White	Plaster	unit 4
PASS	0.03	12/28/16	11:02 AM	#253	Living room	1st	South	Wall	Center	White	Plaster	unit 4
PASS	0.11	12/28/16	11:03 AM	#254	Living room	1st	East	Wall	Upper	White	Plaster	unit 4
PASS	0.04	12/28/16	11:04 AM	#255	Living room	1st	West	Wall	Lower	White	Plaster	unit 4
PASS	0.02	12/28/16	11:04 AM	#256	Living room	1st	West	Window casing	Center	White	Wood	unit 4
PASS	0.02	12/28/16	11:05 AM	#257	Living room	1st	East	Door casing	Center	Stain	Wood	unit 4
PASS	0.03	12/28/16	11:06 AM	#258	Living room	1st	South	Baseboard	Center	Stain	Wood	unit 4
PASS	0.02	12/28/16	11:06 AM	#259	Living room	1st	South	Crown molding	Center	Stain	Wood	unit 4
▼ Kitchen												
PASS	0	12/28/16	11:07 AM	#260	Kitchen	1st	South	Ceiling	Center	White	Plaster	unit 4
PASS	0.06	12/28/16	11:08 AM	#261	Kitchen	1st	South	Wall	Center	White	Plaster	unit 4
FAIL	1.04	12/28/16	11:09 AM	#262	Kitchen	1st	East	Wall	Center	Brown	Wood	unit 4
PASS	0.07	12/28/16	11:09 AM	#263	Kitchen	1st	North	Wall	Upper	White	Plaster	unit 4
PASS	0.03	12/28/16	11:10 AM	#264	Kitchen	1st	West	Wall	Lower	White	Plaster	unit 4
PASS	0.19	12/28/16	11:10 AM	#265	Kitchen	1st	West	Window sash	Center	White	Wood	unit 4
PASS	0.7	12/28/16	11:11 AM	#266	Kitchen	1st	North	Cabinet	Center	White	Wood	unit 4
PASS	0.18	12/28/16	11:12 AM	#267	Kitchen	1st	North	Door casing	Center	White	Wood	unit 4
PASS	0.1	12/28/16	11:12 AM	#268	Kitchen	1st	West	Radiator	Center	White	Metal	unit 4
▼ Bdrm 2												
PASS	0.14	12/28/16	11:13 AM	#269	Bdrm 2	1st	North	Radiator	Left	White	Metal	unit 4
PASS	0	12/28/16	11:13 AM	#270	Bdrm 2	1st	North	Ceiling	Center	White	Plaster	unit 4
PASS	0	12/28/16	11:14 AM	#271	Bdrm 2	1st	North	Wall	Center	White	Plaster	unit 4
PASS	0	12/28/16	11:14 AM	#272	Bdrm 2	1st	South	Wall	Center	White	Plaster	unit 4
PASS	0	12/28/16	11:15 AM	#273	Bdrm 2	1st	East	Wall	Lower	White	Plaster	unit 4
PASS	0	12/28/16	11:15 AM	#274	Bdrm 2	1st	West	Wall	Upper	White	Plaster	unit 4
FAIL	1.3	12/28/16	11:16 AM	#275	Bdrm 2	1st	West	Window casing	Center	White	Wood	unit 4
PASS	0.51	12/28/16	11:16 AM	#276	Bdrm 2	1st	South	Door casing	Center	White	Wood	unit 4
PASS	0.01	12/28/16	11:17 AM	#277	Bdrm 2	1st	East	Closet	Center	White	Plaster	unit 4
▼ unit 1												
▼ Bdrm 1												
PASS	0.01	12/28/16	11:21 AM	#278	Bdrm 1	1st	East	Closet	Center	White	Plaster	unit 1
PASS	0	12/28/16	11:21 AM	#279	Bdrm 1	1st	East	Ceiling	Center	White	Plaster	unit 1
PASS	0	12/28/16	11:22 AM	#280	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 1
PASS	0	12/28/16	11:22 AM	#281	Bdrm 1	1st	West	Wall	Center	White	Plaster	unit 1
PASS	0	12/28/16	11:22 AM	#282	Bdrm 1	1st	South	Wall	Upper	White	Plaster	unit 1
PASS	0	12/28/16	11:23 AM	#283	Bdrm 1	1st	East	Wall	Lower	White	Plaster	unit 1

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
FAIL	1.27	12/28/16	11:23 AM	#284	Bdrm 1	1st	East	Window casing	Center	White	Wood	unit 1
FAIL	1.11	12/28/16	11:24 AM	#285	Bdrm 1	1st	North	Door casing	Center	White	Wood	unit 1
FAIL	1.5	12/28/16	11:25 AM	#286	Bdrm 1	1st	North	Baseboard	Center	White	Wood	unit 1
▼ Hall												
PASS	0	12/28/16	11:25 AM	#287	Hall	1st	North	Ceiling	Center	White	Plaster	unit 1
PASS	0	12/28/16	11:26 AM	#288	Hall	1st	North	Wall	Upper	White	Plaster	unit 1
PASS	0	12/28/16	11:26 AM	#289	Hall	1st	West	Wall	Upper	White	Plaster	unit 1
PASS	0	12/28/16	11:26 AM	#290	Hall	1st	South	Wall	Upper	White	Plaster	unit 1
PASS	0	12/28/16	11:27 AM	#291	Hall	1st	East	Wall	Lower	White	Plaster	unit 1
FAIL	1.01	12/28/16	11:28 AM	#292	Hall	1st	East	Door casing	Center	White	Wood	unit 1
FAIL	1.28	12/28/16	11:28 AM	#293	Hall	1st	West	Cabinet	Center	White	Wood	unit 1
▼ Bathroom												
FAIL	3.36	12/28/16	11:29 AM	#294	Bathroom	1st	West	Ceiling	Center	White	Plaster	unit 1
PASS	0	12/28/16	11:30 AM	#295	Bathroom	1st	West	Wall	Center	White	Plaster	unit 1
FAIL	1.21	12/28/16	11:30 AM	#296	Bathroom	1st	South	Wall	Center	White	Plaster	unit 1
FAIL	1.42	12/28/16	11:31 AM	#297	Bathroom	1st	North	Wall	Lower	White	Plaster	unit 1
FAIL	2.42	12/28/16	11:31 AM	#298	Bathroom	1st	East	Wall	Upper	White	Plaster	unit 1
PASS	0.54	12/28/16	11:32 AM	#299	Bathroom	1st	East	Window casing	Center	White	Wood	unit 1
PASS	0.41	12/28/16	11:32 AM	#300	Bathroom	1st	West	Door	Center	White	Wood	unit 1
PASS	0.9	12/28/16	11:33 AM	#301	Bathroom	1st	West	Chair rail	Center	White	Wood	unit 1
PASS	0.15	12/28/16	11:34 AM	#302	Bathroom	1st	South	Radiator	Center	White	Metal	unit 1
FAIL	5	12/28/16	11:34 AM	#303	Bathroom	1st	East	Bathtub	Center	White	Metal	unit 1
▼ Kitchen												
PASS	0	12/28/16	11:35 AM	#304	Kitchen	1st	East	Ceiling	Center	White	Plaster	unit 1
PASS	0.74	12/28/16	11:35 AM	#305	Kitchen	1st	West	Ceiling	Center	White	Plaster	unit 1
PASS	0.71	12/28/16	11:36 AM	#306	Kitchen	1st	North	Wall	Left	White	Plaster	unit 1
PASS	0	12/28/16	11:36 AM	#307	Kitchen	1st	North	Wall	Right	White	Plaster	unit 1
PASS	0	12/28/16	11:37 AM	#308	Kitchen	1st	South	Wall	Left	White	Plaster	unit 1
PASS	0	12/28/16	11:37 AM	#309	Kitchen	1st	West	Wall	Upper	White	Plaster	unit 1
PASS	0	12/28/16	11:38 AM	#310	Kitchen	1st	East	Wall	Lower	White	Plaster	unit 1
PASS	0.12	12/28/16	11:38 AM	#311	Kitchen	1st	East	Window sash	Center	White	Wood	unit 1
PASS	0.17	12/28/16	11:39 AM	#312	Kitchen	1st	East	Window casing	Center	White	Wood	unit 1
PASS	0.13	12/28/16	11:40 AM	#313	Kitchen	1st	South	Door casing	Center	White	Wood	unit 1
PASS	0.3	12/28/16	11:40 AM	#314	Kitchen	1st	South	Door casing	Center	White	Wood	unit 1
▼ Living room												
PASS	0	12/28/16	11:41 AM	#315	Living room	1st	South	Ceiling	Center	White	Plaster	unit 1
PASS	0	12/28/16	11:41 AM	#316	Living room	1st	South	Wall	Center	White	Plaster	unit 1

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0	12/28/16	11:42 AM	#317	Living room	1st	West	Wall	Center	White	Plaster	unit 1
PASS	0	12/28/16	11:42 AM	#318	Living room	1st	North	Wall	Upper	White	Plaster	unit 1
PASS	0	12/28/16	11:43 AM	#319	Living room	1st	East	Wall	Lower	White	Plaster	unit 1
PASS	0	12/28/16	11:43 AM	#320	Living room	1st	East	Window casing	Center	White	Plaster	unit 1
PASS	0.01	12/28/16	11:44 AM	#321	Living room	1st	North	Window sash	Center	White	Plaster	unit 1
PASS	0.57	12/28/16	11:45 AM	#322	Living room	1st	North	Radiator	Center	White	Metal	unit 1
▼ unit 2												
▼ Bdrm 1												
PASS	0	12/28/16	11:47 AM	#323	Bdrm 1	1st	North	Ceiling	Center	White	Plaster	unit 2
PASS	0	12/28/16	11:48 AM	#324	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 2
PASS	0	12/28/16	11:48 AM	#325	Bdrm 1	1st	South	Wall	Center	White	Plaster	unit 2
PASS	0	12/28/16	11:49 AM	#326	Bdrm 1	1st	East	Wall	Upper	White	Plaster	unit 2
PASS	0	12/28/16	11:49 AM	#327	Bdrm 1	1st	West	Wall	Lower	White	Plaster	unit 2
FAIL	1.31	12/28/16	11:50 AM	#328	Bdrm 1	1st	West	Window casing	Center	White	Wood	unit 2
FAIL	1.06	12/28/16	11:51 AM	#329	Bdrm 1	1st	North	Door casing	Right	White	Wood	unit 2
PASS	0.09	12/28/16	11:51 AM	#330	Bdrm 1	1st	North	Door	Left	White	Wood	unit 2
FAIL	1.17	12/28/16	11:52 AM	#331	Bdrm 1	1st	South	Door jamb	Center	White	Wood	unit 2
FAIL	1.48	12/28/16	11:52 AM	#332	Bdrm 1	1st	West	Baseboard	Center	White	Wood	unit 2
PASS	0.02	12/28/16	11:53 AM	#333	Bdrm 1	1st	South	Radiator	Right	White	Metal	unit 2
PASS	0	12/28/16	11:53 AM	#334	Bdrm 1	1st	South	Floor	Center	Stain	Wood	unit 2
PASS	0.02	12/28/16	11:54 AM	#335	Bdrm 1	1st	North	Closet	Center	White	Plaster	unit 2
▼ Bathroom												
PASS	0	12/28/16	11:55 AM	#336	Bathroom	1st	North	Ceiling	Center	White	Plaster	unit 2
PASS	0.67	12/28/16	11:55 AM	#337	Bathroom	1st	North	Wall	Center	White	Plaster	unit 2
PASS	0	12/28/16	11:56 AM	#338	Bathroom	1st	East	Wall	Center	White	Plaster	unit 2
PASS	0.09	12/28/16	11:56 AM	#339	Bathroom	1st	South	Wall	Lower	White	Plaster	unit 2
PASS	0.78	12/28/16	11:57 AM	#340	Bathroom	1st	West	Wall	Upper	White	Plaster	unit 2
FAIL	1.03	12/28/16	11:58 AM	#341	Bathroom	1st	West	Window casing	Center	White	Wood	unit 2
FAIL	1.75	12/28/16	11:58 AM	#342	Bathroom	1st	East	Door casing	Center	White	Wood	unit 2
FAIL	1.28	12/28/16	11:59 AM	#343	Bathroom	1st	North	Cabinet	Center	White	Wood	unit 2
FAIL	5	12/28/16	11:59 AM	#344	Bathroom	1st	West	Bathtub	Center	White	Metal	unit 2
PASS	0	12/28/16	12:00 PM	#345	Bathroom	1st	South	Radiator	Center	Green	Metal	unit 2
PASS	0.01	12/28/16	12:00 PM	#346	Bathroom	1st	South	Floor	Center	White	Ceramic	unit 2
▼ Hall												
PASS	0	12/28/16	12:01 PM	#347	Hall	1st	South	Ceiling	Center	White	Plaster	unit 2
PASS	0	12/28/16	12:02 PM	#348	Hall	1st	North	Wall	Upper	White	Plaster	unit 2
PASS	0	12/28/16	12:02 PM	#349	Hall	1st	East	Wall	Upper	White	Plaster	unit 2



PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0	12/28/16	12:03 PM	#350	Hall	1st	South	Wall	Upper	White	Plaster	unit 2
PASS	0	12/28/16	12:04 PM	#352	Hall	1st	West	Wall	Lower	White	Plaster	unit 2
PASS	0.55	12/28/16	12:04 PM	#353	Hall	1st	East	Cabinet	Center	White	Wood	unit 2
PASS	0.59	12/28/16	12:05 PM	#354	Hall	1st	West	Door casing	Center	White	Wood	unit 2
▼ Kitchen												
PASS	0	12/28/16	12:06 PM	#355	Kitchen	1st	West	Ceiling	Center	White	Plaster	unit 2
PASS	0.82	12/28/16	12:06 PM	#356	Kitchen	1st	North	Wall	Right	White	Plaster	unit 2
PASS	0	12/28/16	12:07 PM	#357	Kitchen	1st	North	Wall	Left	White	Plaster	unit 2
PASS	0	12/28/16	12:07 PM	#358	Kitchen	1st	East	Wall	Center	White	Plaster	unit 2
PASS	0	12/28/16	12:08 PM	#359	Kitchen	1st	South	Wall	Upper	White	Plaster	unit 2
PASS	0	12/28/16	12:08 PM	#360	Kitchen	1st	West	Wall	Lower	White	Plaster	unit 2
PASS	0.86	12/28/16	12:09 PM	#361	Kitchen	1st	West	Window sash	Center	White	Wood	unit 2
PASS	0.28	12/28/16	12:10 PM	#362	Kitchen	1st	South	Cabinet	Center	White	Wood	unit 2
FAIL	1.55	12/28/16	12:10 PM	#363	Kitchen	1st	South	Baseboard	Center	White	Wood	unit 2
PASS	0.09	12/28/16	12:11 PM	#364	Kitchen	1st	West	Radiator	Center	White	Metal	unit 2
▼ Living room												
PASS	0.02	12/28/16	12:12 PM	#365	Living room	1st	North	Radiator	Center	White	Metal	unit 2
PASS	0.01	12/28/16	12:12 PM	#366	Living room	1st	North	Ceiling	Center	White	Plaster	unit 2
PASS	0.02	12/28/16	12:13 PM	#367	Living room	1st	South	Wall	Center	Orange	Plaster	unit 2
PASS	0.01	12/28/16	12:13 PM	#368	Living room	1st	East	Wall	Center	Orange	Plaster	unit 2
PASS	0.44	12/28/16	12:14 PM	#369	Living room	1st	West	Wall	Upper	Orange	Plaster	unit 2
PASS	0.01	12/28/16	12:15 PM	#370	Living room	1st	North	Wall	Lower	Orange	Plaster	unit 2
PASS	0.02	12/28/16	12:15 PM	#371	Living room	1st	North	Window casing	Center	Stain	Wood	unit 2
PASS	0.03	12/28/16	12:16 PM	#372	Living room	1st	West	Window sash	Center	Stain	Wood	unit 2
PASS	0.01	12/28/16	12:17 PM	#373	Living room	1st	South	Door casing	Center	Stain	Wood	unit 2
PASS	0.01	12/28/16	12:17 PM	#374	Living room	1st	South	Baseboard	Center	Stain	Wood	unit 2
PASS	0.01	12/28/16	12:18 PM	#375	Living room	1st	South	Floor	Center	Stain	Wood	unit 2
▼ unit 5												
▼ Bdrm 1												
PASS	0	12/28/16	12:20 PM	#376	Bdrm 1	2nd	South	Ceiling	Center	White	Plaster	unit 5
PASS	0	12/28/16	12:21 PM	#377	Bdrm 1	2nd	South	Wall	Center	White	Plaster	unit 5
PASS	0	12/28/16	12:21 PM	#378	Bdrm 1	2nd	North	Wall	Center	White	Plaster	unit 5
PASS	0	12/28/16	12:22 PM	#379	Bdrm 1	2nd	West	Wall	Upper	White	Plaster	unit 5
PASS	0	12/28/16	12:23 PM	#380	Bdrm 1	2nd	East	Wall	Lower	White	Plaster	unit 5
PASS	0.88	12/28/16	12:23 PM	#381	Bdrm 1	2nd	East	Window casing	Center	White	Wood	unit 5
PASS	0.31	12/28/16	12:24 PM	#382	Bdrm 1	2nd	North	Door casing	Center	White	Wood	unit 5
PASS	0.46	12/28/16	12:25 PM	#383	Bdrm 1	2nd	South	Baseboard	Center	White	Wood	unit 5

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.16	12/28/16	12:25 PM	#384	Bdrm 1	2nd	South	Closet	Center	Gray	Plaster	unit 5
PASS	0.42	12/28/16	12:26 PM	#385	Bdrm 1	2nd	North	Closet	Center	Gray	Plaster	unit 5
PASS	0.31	12/28/16	12:27 PM	#386	Bdrm 1	2nd	South	Radiator	Left	White	Metal	unit 5
▼ Bathroom												
PASS	0.23	12/28/16	12:28 PM	#387	Bathroom	2nd	South	Radiator	Center	White	Metal	unit 5
FAIL	5	12/28/16	12:28 PM	#388	Bathroom	2nd	East	Bathtub	Center	White	Metal	unit 5
FAIL	1.34	12/28/16	12:28 PM	#389	Bathroom	2nd	East	Ceiling	Center	White	Plaster	unit 5
PASS	0.94	12/28/16	12:29 PM	#390	Bathroom	2nd	North	Wall	Center	White	Plaster	unit 5
PASS	0.8	12/28/16	12:30 PM	#391	Bathroom	2nd	South	Wall	Center	White	Plaster	unit 5
PASS	0.32	12/28/16	12:30 PM	#392	Bathroom	2nd	West	Wall	Lower	White	Plaster	unit 5
PASS	0.97	12/28/16	12:31 PM	#393	Bathroom	2nd	East	Wall	Upper	White	Plaster	unit 5
PASS	0.51	12/28/16	12:32 PM	#394	Bathroom	2nd	East	Window casing	Center	White	Wood	unit 5
PASS	0.28	12/28/16	12:32 PM	#395	Bathroom	2nd	West	Door casing	Center	White	Wood	unit 5
PASS	0.01	12/28/16	12:33 PM	#396	Bathroom	2nd	West	Floor	Center	White	Ceramic	unit 5
▼ Hall												
PASS	0	12/28/16	12:33 PM	#397	Hall	2nd	West	Ceiling	Center	White	Plaster	unit 5
PASS	0	12/28/16	12:34 PM	#398	Hall	2nd	North	Wall	Upper	White	Plaster	unit 5
PASS	0	12/28/16	12:34 PM	#399	Hall	2nd	South	Wall	Upper	White	Plaster	unit 5
PASS	0	12/28/16	12:34 PM	#400	Hall	2nd	West	Wall	Upper	White	Plaster	unit 5
PASS	0	12/28/16	12:35 PM	#401	Hall	2nd	East	Wall	Lower	White	Plaster	unit 5
PASS	0.33	12/28/16	12:35 PM	#402	Hall	2nd	West	Cabinet	Center	White	Wood	unit 5
▼ Kitchen												
PASS	0.18	12/28/16	12:36 PM	#403	Kitchen	2nd	East	Cabinet	Center	White	Wood	unit 5
PASS	0.19	12/28/16	12:36 PM	#404	Kitchen	2nd	North	Cabinet	Center	White	Wood	unit 5
PASS	0.19	12/28/16	12:37 PM	#405	Kitchen	2nd	South	Baseboard	Center	White	Wood	unit 5
PASS	0.31	12/28/16	12:37 PM	#406	Kitchen	2nd	East	Window casing	Center	White	Wood	unit 5
PASS	0.23	12/28/16	12:38 PM	#407	Kitchen	2nd	East	Radiator	Center	White	Metal	unit 5
FAIL	1.15	12/28/16	12:39 PM	#408	Kitchen	2nd	West	Ceiling	Center	White	Plaster	unit 5
PASS	0	12/28/16	12:39 PM	#409	Kitchen	2nd	East	Ceiling	Center	White	Plaster	unit 5
PASS	0	12/28/16	12:40 PM	#410	Kitchen	2nd	West	Wall	Center	White	Plaster	unit 5
FAIL	1.48	12/28/16	12:40 PM	#411	Kitchen	2nd	North	Wall	Left	White	Plaster	unit 5
PASS	0	12/28/16	12:40 PM	#412	Kitchen	2nd	North	Wall	Right	White	Plaster	unit 5
PASS	0	12/28/16	12:41 PM	#413	Kitchen	2nd	South	Wall	Left	White	Plaster	unit 5
PASS	0.47	12/28/16	12:41 PM	#414	Kitchen	2nd	South	Wall	Right	White	Plaster	unit 5
PASS	0	12/28/16	12:42 PM	#415	Kitchen	2nd	East	Wall	Center	White	Plaster	unit 5
▼ Living room												
PASS	0	12/28/16	12:42 PM	#416	Living room	2nd	East	Ceiling	Center	White	Plaster	unit 5

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0	12/28/16	12:43 PM	#417	Living room	2nd	South	Wall	Center	White	Plaster	unit 5
PASS	0	12/28/16	12:43 PM	#418	Living room	2nd	West	Wall	Center	White	Plaster	unit 5
PASS	0	12/28/16	12:44 PM	#419	Living room	2nd	East	Wall	Upper	White	Plaster	unit 5
PASS	0	12/28/16	12:44 PM	#420	Living room	2nd	North	Wall	Lower	White	Plaster	unit 5
PASS	0.01	12/28/16	12:44 PM	#421	Living room	2nd	North	Window casing	Center	White	Wood	unit 5
PASS	0.04	12/28/16	12:45 PM	#422	Living room	2nd	East	Window sash	Center	White	Wood	unit 5
PASS	0.02	12/28/16	12:45 PM	#423	Living room	2nd	West	Door casing	Center	Stain	Wood	unit 5
PASS	0.01	12/28/16	12:46 PM	#424	Living room	2nd	South	Door jamb	Center	Stain	Wood	unit 5
PASS	0.03	12/28/16	12:46 PM	#425	Living room	2nd	South	Closet	Center	Gray	Plaster	unit 5
PASS	0.02	12/28/16	12:47 PM	#426	Living room	2nd	South	Floor	Center	Stain	Wood	unit 5
▼ unit 6												
▼ Bdrm 1												
PASS	0	12/28/16	12:48 PM	#427	Bdrm 1	2nd	South	Ceiling	Center	White	Plaster	unit 6
PASS	0.02	12/28/16	12:49 PM	#428	Bdrm 1	2nd	North	Wall	Center	White	Plaster	unit 6
PASS	0.03	12/28/16	12:49 PM	#429	Bdrm 1	2nd	South	Wall	Center	White	Plaster	unit 6
PASS	0.02	12/28/16	12:50 PM	#430	Bdrm 1	2nd	East	Wall	Upper	White	Plaster	unit 6
PASS	0.02	12/28/16	12:50 PM	#431	Bdrm 1	2nd	West	Wall	Lower	White	Plaster	unit 6
PASS	0.21	12/28/16	12:50 PM	#432	Bdrm 1	2nd	West	Window casing	Center	White	Wood	unit 6
PASS	0.06	12/28/16	12:51 PM	#433	Bdrm 1	2nd	North	Door	Right	White	Wood	unit 6
PASS	0.47	12/28/16	12:51 PM	#434	Bdrm 1	2nd	North	Door casing	Left	White	Wood	unit 6
PASS	0.18	12/28/16	12:52 PM	#435	Bdrm 1	2nd	South	Door jamb	Center	White	Wood	unit 6
PASS	0.33	12/28/16	12:52 PM	#436	Bdrm 1	2nd	South	Baseboard	Center	White	Wood	unit 6
PASS	0	12/28/16	12:52 PM	#437	Bdrm 1	2nd	South	Floor	Center	Stain	Wood	unit 6
PASS	0.21	12/28/16	12:53 PM	#438	Bdrm 1	2nd	South	Closet	Center	Gray	Plaster	unit 6
▼ Bathroom												
PASS	0.99	12/28/16	12:54 PM	#439	Bathroom	2nd	South	Ceiling	Center	White	Plaster	unit 6
FAIL	1.01	12/28/16	12:55 PM	#440	Bathroom	2nd	North	Wall	Center	White	Plaster	unit 6
PASS	0.86	12/28/16	12:55 PM	#441	Bathroom	2nd	South	Wall	Center	White	Plaster	unit 6
PASS	0.17	12/28/16	12:56 PM	#442	Bathroom	2nd	East	Wall	Lower	White	Plaster	unit 6
PASS	0.63	12/28/16	12:56 PM	#443	Bathroom	2nd	West	Wall	Upper	White	Plaster	unit 6
PASS	0.24	12/28/16	12:57 PM	#444	Bathroom	2nd	West	Window casing	Center	White	Wood	unit 6
FAIL	1.2	12/28/16	12:57 PM	#445	Bathroom	2nd	West	Wall	Center	White	Plaster	unit 6
PASS	0.19	12/28/16	12:58 PM	#446	Bathroom	2nd	East	Door casing	Center	White	Wood	unit 6
PASS	0.45	12/28/16	12:58 PM	#447	Bathroom	2nd	North	Cabinet	Center	White	Wood	unit 6
PASS	0.24	12/28/16	12:59 PM	#448	Bathroom	2nd	South	Radiator	Center	White	Metal	unit 6
FAIL	5	12/28/16	12:59 PM	#449	Bathroom	2nd	West	Bathtub	Center	White	Metal	unit 6
PASS	0.01	12/28/16	12:59 PM	#450	Bathroom	2nd	West	Floor	Center	White	Ceramic	unit 6

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
▼ Hall												
PASS	0	12/28/16	1:00 PM	#451	Hall	2nd	West	Ceiling	Center	White	Plaster	unit 6
PASS	0	12/28/16	1:00 PM	#452	Hall	2nd	North	Floor	Upper	White	Plaster	unit 6
PASS	0	12/28/16	1:01 PM	#453	Hall	2nd	South	Wall	Upper	White	Plaster	unit 6
PASS	0	12/28/16	1:01 PM	#454	Hall	2nd	East	Wall	Upper	White	Plaster	unit 6
PASS	0.05	12/28/16	1:01 PM	#455	Hall	2nd	West	Wall	Lower	White	Plaster	unit 6
PASS	0.26	12/28/16	1:02 PM	#456	Hall	2nd	West	Door casing	Center	White	Wood	unit 6
PASS	0.28	12/28/16	1:02 PM	#457	Hall	2nd	East	Cabinet	Center	Orange	Wood	unit 6
▼ Kitchen												
PASS	0.02	12/28/16	1:03 PM	#458	Kitchen	2nd	East	Ceiling	Center	White	Plaster	unit 6
PASS	0	12/28/16	1:03 PM	#459	Kitchen	2nd	West	Ceiling	Center	White	Plaster	unit 6
FAIL	1.03	12/28/16	1:04 PM	#460	Kitchen	2nd	North	Wall	Right	White	Plaster	unit 6
PASS	0.01	12/28/16	1:05 PM	#461	Kitchen	2nd	North	Wall	Left	White	Plaster	unit 6
PASS	0.02	12/28/16	1:05 PM	#462	Kitchen	2nd	South	Wall	Right	White	Plaster	unit 6
PASS	0.5	12/28/16	1:05 PM	#463	Kitchen	2nd	South	Wall	Left	White	Plaster	unit 6
PASS	0	12/28/16	1:06 PM	#464	Kitchen	2nd	East	Wall	Upper	White	Plaster	unit 6
PASS	0.01	12/28/16	1:06 PM	#465	Kitchen	2nd	West	Wall	Lower	White	Plaster	unit 6
PASS	0.53	12/28/16	1:07 PM	#466	Kitchen	2nd	West	Window casing	Center	White	Wood	unit 6
PASS	0.4	12/28/16	1:07 PM	#467	Kitchen	2nd	South	Cabinet	Center	White	Wood	unit 6
PASS	0.56	12/28/16	1:08 PM	#468	Kitchen	2nd	North	Cabinet	Center	White	Wood	unit 6
▼ Living room												
PASS	0	12/28/16	1:09 PM	#469	Living room	2nd	North	Ceiling	Center	White	Plaster	unit 6
PASS	0.01	12/28/16	1:09 PM	#470	Living room	2nd	North	Wall	Center	White	Plaster	unit 6
PASS	0.01	12/28/16	1:10 PM	#471	Living room	2nd	South	Wall	Center	White	Plaster	unit 6
PASS	0.01	12/28/16	1:10 PM	#472	Living room	2nd	East	Wall	Upper	White	Plaster	unit 6
PASS	0.01	12/28/16	1:11 PM	#473	Living room	2nd	East	Wall	Lower	White	Plaster	unit 6
PASS	0.02	12/28/16	1:11 PM	#474	Living room	2nd	East	Window casing	Center	White	Wood	unit 6
PASS	0.05	12/28/16	1:11 PM	#475	Living room	2nd	North	Window sash	Center	White	Wood	unit 6
PASS	0.03	12/28/16	1:12 PM	#476	Living room	2nd	South	Door casing	Center	White	Wood	unit 6
PASS	0	12/28/16	1:12 PM	#477	Living room	2nd	East	Door	Center	Brown	Wood	unit 6
PASS	0.01	12/28/16	1:13 PM	#478	Living room	2nd	South	Baseboard	Center	White	Wood	unit 6
PASS	0.13	12/28/16	1:13 PM	#479	Living room	2nd	South	Closet	Center	Gray	Plaster	unit 6
PASS	0	12/28/16	1:14 PM	#480	Living room	2nd	South	Floor	Center	Stain	Wood	unit 6
▼ unit 8												
▼ Bdrm 1												
PASS	0	12/28/16	1:39 PM	#482	Bdrm 1	2nd	South	Ceiling	Center	White	Plaster	unit 8
PASS	0	12/28/16	1:39 PM	#483	Bdrm 1	2nd	North	Wall	Center	White	Plaster	unit 8



PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0	12/28/16	1:40 PM	#484	Bdrm 1	2nd	South	Wall	Center	White	Plaster	unit 8
PASS	0	12/28/16	1:40 PM	#485	Bdrm 1	2nd	East	Wall	Upper	White	Plaster	unit 8
PASS	0	12/28/16	1:40 PM	#486	Bdrm 1	2nd	West	Wall	Lower	White	Plaster	unit 8
PASS	0.35	12/28/16	1:41 PM	#487	Bdrm 1	2nd	West	Window casing	Center	White	Wood	unit 8
PASS	0.04	12/28/16	1:41 PM	#488	Bdrm 1	2nd	South	Window stool	Center	White	Wood	unit 8
PASS	0.23	12/28/16	1:41 PM	#489	Bdrm 1	2nd	East	Door	Right	White	Wood	unit 8
PASS	0.55	12/28/16	1:42 PM	#490	Bdrm 1	2nd	East	Door casing	Left	White	Wood	unit 8
PASS	0.4	12/28/16	1:42 PM	#491	Bdrm 1	2nd	East	Baseboard	Center	White	Wood	unit 8
PASS	0	12/28/16	1:42 PM	#492	Bdrm 1	2nd	East	Floor	Center	Stain	Wood	unit 8
PASS	0.02	12/28/16	1:43 PM	#493	Bdrm 1	2nd	East	Closet	Center	White	Plaster	unit 8
▼ Bathroom												
FAIL	1.17	12/28/16	1:44 PM	#494	Bathroom	2nd	East	Ceiling	Center	White	Plaster	unit 8
FAIL	1.35	12/28/16	1:44 PM	#495	Bathroom	2nd	North	Wall	Center	White	Plaster	unit 8
FAIL	1.52	12/28/16	1:45 PM	#496	Bathroom	2nd	East	Wall	Center	White	Plaster	unit 8
PASS	0.28	12/28/16	1:45 PM	#497	Bathroom	2nd	West	Wall	Lower	White	Plaster	unit 8
FAIL	2.07	12/28/16	1:46 PM	#498	Bathroom	2nd	South	Wall	Upper	White	Plaster	unit 8
PASS	0.95	12/28/16	1:46 PM	#499	Bathroom	2nd	South	Window casing	Center	White	Wood	unit 8
PASS	0.86	12/28/16	1:47 PM	#500	Bathroom	2nd	North	Door casing	Center	White	Wood	unit 8
FAIL	5	12/28/16	1:47 PM	#501	Bathroom	2nd	South	Bathtub	Center	White	Metal	unit 8
PASS	0.39	12/28/16	1:48 PM	#502	Bathroom	2nd	West	Radiator	Center	White	Metal	unit 8
PASS	0.01	12/28/16	1:48 PM	#503	Bathroom	2nd	West	Floor	Center	White	Ceramic	unit 8
▼ Hall												
PASS	0	12/28/16	1:49 PM	#504	Hall	2nd	West	Ceiling	Center	White	Plaster	unit 8
PASS	0	12/28/16	1:49 PM	#505	Hall	2nd	North	Wall	Center	White	Plaster	unit 8
PASS	0	12/28/16	1:49 PM	#506	Hall	2nd	South	Wall	Center	White	Plaster	unit 8
PASS	0	12/28/16	1:50 PM	#507	Hall	2nd	East	Wall	Lower	White	Plaster	unit 8
PASS	0	12/28/16	1:50 PM	#508	Hall	2nd	West	Wall	Upper	White	Plaster	unit 8
PASS	0.03	12/28/16	1:50 PM	#509	Hall	2nd	West	Door casing	Right	White	Wood	unit 8
PASS	0.12	12/28/16	1:51 PM	#510	Hall	2nd	East	Cabinet	Center	White	Wood	unit 8
▼ Living room												
PASS	0	12/28/16	1:51 PM	#511	Living room	2nd	East	Ceiling	Center	White	Plaster	unit 8
PASS	0	12/28/16	1:52 PM	#512	Living room	2nd	South	Wall	Center	White	Plaster	unit 8
PASS	0	12/28/16	1:52 PM	#513	Living room	2nd	North	Wall	Center	White	Plaster	unit 8
PASS	0	12/28/16	1:52 PM	#514	Living room	2nd	East	Wall	Lower	White	Plaster	unit 8
PASS	0	12/28/16	1:53 PM	#515	Living room	2nd	West	Wall	Upper	White	Plaster	unit 8
PASS	0.01	12/28/16	1:53 PM	#516	Living room	2nd	West	Door casing	Center	White	Wood	unit 8
PASS	0.01	12/28/16	1:54 PM	#517	Living room	2nd	East	Door casing	Center	White	Wood	unit 8

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.01	12/28/16	1:54 PM	#518	Living room	2nd	South	Baseboard	Center	White	Wood	unit 8
PASS	0.02	12/28/16	1:54 PM	#519	Living room	2nd	South	Floor	Center	Stain	Wood	unit 8
▼ Kitchen												
PASS	0	12/28/16	1:55 PM	#520	Kitchen	2nd	West	Ceiling	Center	White	Plaster	unit 8
FAIL	1.96	12/28/16	1:55 PM	#521	Kitchen	2nd	East	Ceiling	Center	White	Plaster	unit 8
PASS	0	12/28/16	1:56 PM	#522	Kitchen	2nd	North	Wall	Center	White	Plaster	unit 8
FAIL	2.37	12/28/16	1:56 PM	#523	Kitchen	2nd	East	Wall	Center	White	Plaster	unit 8
FAIL	5	12/28/16	1:57 PM	#524	Kitchen	2nd	South	Wall	Upper	White	Plaster	unit 8
PASS	0	12/28/16	1:57 PM	#525	Kitchen	2nd	West	Wall	Lower	White	Plaster	unit 8
PASS	0.2	12/28/16	1:58 PM	#526	Kitchen	2nd	West	Window casing	Center	White	Wood	unit 8
PASS	0.03	12/28/16	1:58 PM	#527	Kitchen	2nd	North	Window trough	Center	White	Wood	unit 8
PASS	0.01	12/28/16	1:59 PM	#528	Kitchen	2nd	North	Baseboard	Center	White	Wood	unit 8
PASS	0.14	12/28/16	1:59 PM	#529	Kitchen	2nd	West	Radiator	Center	White	Metal	unit 8
PASS	0.65	12/28/16	2:00 PM	#530	Kitchen	2nd	North	Cabinet	Center	White	Wood	unit 8
PASS	0.23	12/28/16	2:00 PM	#531	Kitchen	2nd	East	Cabinet	Center	White	Wood	unit 8
▼ Bdrm 2												
PASS	0	12/28/16	2:01 PM	#532	Bdrm 2	2nd	East	Ceiling	Center	White	Plaster	unit 8
PASS	0	12/28/16	2:01 PM	#533	Bdrm 2	2nd	North	Wall	Center	White	Plaster	unit 8
PASS	0	12/28/16	2:02 PM	#534	Bdrm 2	2nd	South	Wall	Center	White	Plaster	unit 8
PASS	0	12/28/16	2:02 PM	#535	Bdrm 2	2nd	East	Wall	Lower	White	Plaster	unit 8
PASS	0	12/28/16	2:02 PM	#536	Bdrm 2	2nd	West	Wall	Upper	White	Plaster	unit 8
PASS	0.79	12/28/16	2:03 PM	#537	Bdrm 2	2nd	West	Window casing	Center	White	Wood	unit 8
PASS	0.19	12/28/16	2:03 PM	#538	Bdrm 2	2nd	North	Radiator	Center	White	Metal	unit 8
PASS	0.02	12/28/16	2:04 PM	#539	Bdrm 2	2nd	South	Door casing	Center	White	Wood	unit 8
PASS	0.01	12/28/16	2:05 PM	#540	Bdrm 2	2nd	South	Baseboard	Center	White	Wood	unit 8
▼ unit 7												
▼ Bdrm 1												
PASS	0	12/28/16	2:07 PM	#541	Bdrm 1	2nd	South	Ceiling	Center	White	Plaster	unit 7
PASS	0	12/28/16	2:07 PM	#542	Bdrm 1	2nd	North	Wall	Center	White	Plaster	unit 7
PASS	0	12/28/16	2:08 PM	#543	Bdrm 1	2nd	South	Wall	Center	White	Plaster	unit 7
PASS	0	12/28/16	2:08 PM	#544	Bdrm 1	2nd	West	Wall	Upper	White	Plaster	unit 7
PASS	0	12/28/16	2:08 PM	#545	Bdrm 1	2nd	East	Wall	Lower	White	Plaster	unit 7
PASS	0.24	12/28/16	2:09 PM	#546	Bdrm 1	2nd	East	Window casing	Center	White	Wood	unit 7
PASS	0.69	12/28/16	2:09 PM	#547	Bdrm 1	2nd	South	Window sash	Center	White	Wood	unit 7
PASS	0.25	12/28/16	2:10 PM	#548	Bdrm 1	2nd	West	Door casing	Left	White	Wood	unit 7
PASS	0.2	12/28/16	2:10 PM	#549	Bdrm 1	2nd	West	Door jamb	Right	White	Wood	unit 7
PASS	0.01	12/28/16	2:10 PM	#550	Bdrm 1	2nd	East	Baseboard	Center	White	Wood	unit 7

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.31	12/28/16	2:11 PM	#551	Bdrm 1	2nd	East	Radiator	Center	White	Metal	unit 7
▼ Bathroom												
PASS	0.32	12/28/16	2:11 PM	#552	Bathroom	2nd	East	Radiator	Center	White	Metal	unit 7
FAIL	5	12/28/16	2:12 PM	#553	Bathroom	2nd	South	Bathtub	Center	White	Metal	unit 7
FAIL	1.2	12/28/16	2:12 PM	#554	Bathroom	2nd	South	Floor	Center	White	Plaster	unit 7
PASS	0.92	12/28/16	2:12 PM	#555	Bathroom	2nd	North	Wall	Center	White	Plaster	unit 7
PASS	0.8	12/28/16	2:13 PM	#556	Bathroom	2nd	West	Wall	Center	White	Plaster	unit 7
PASS	0.58	12/28/16	2:13 PM	#557	Bathroom	2nd	East	Wall	Lower	White	Plaster	unit 7
PASS	0.45	12/28/16	2:14 PM	#558	Bathroom	2nd	South	Wall	Upper	White	Plaster	unit 7
PASS	0.93	12/28/16	2:14 PM	#559	Bathroom	2nd	South	Window casing	Center	White	Wood	unit 7
PASS	0.68	12/28/16	2:15 PM	#560	Bathroom	2nd	North	Door casing	Center	White	Wood	unit 7
PASS	0.01	12/28/16	2:15 PM	#561	Bathroom	2nd	North	Floor	Center	White	Ceramic	unit 7
▼ Hall												
PASS	0	12/28/16	2:16 PM	#562	Hall	2nd	North	Ceiling	Center	White	Plaster	unit 7
PASS	0	12/28/16	2:16 PM	#563	Hall	2nd	North	Wall	Center	White	Plaster	unit 7
PASS	0	12/28/16	2:16 PM	#564	Hall	2nd	South	Wall	Center	White	Plaster	unit 7
PASS	0	12/28/16	2:17 PM	#565	Hall	2nd	West	Wall	Lower	White	Plaster	unit 7
PASS	0	12/28/16	2:17 PM	#566	Hall	2nd	East	Wall	Upper	White	Plaster	unit 7
PASS	0.02	12/28/16	2:18 PM	#567	Hall	2nd	East	Door casing	Center	White	Wood	unit 7
PASS	0.03	12/28/16	2:18 PM	#568	Hall	2nd	East	Cabinet	Center	White	Wood	unit 7
▼ Living room												
PASS	0	12/28/16	2:19 PM	#569	Living room	2nd	East	Ceiling	Center	White	Plaster	unit 7
PASS	0.54	12/28/16	2:19 PM	#570	Living room	2nd	North	Wall	Center	White	Plaster	unit 7
PASS	0.33	12/28/16	2:19 PM	#571	Living room	2nd	South	Wall	Center	White	Plaster	unit 7
PASS	0.03	12/28/16	2:20 PM	#572	Living room	2nd	West	Wall	Upper	White	Plaster	unit 7
PASS	0.43	12/28/16	2:20 PM	#573	Living room	2nd	East	Wall	Lower	White	Plaster	unit 7
PASS	0.06	12/28/16	2:21 PM	#574	Living room	2nd	East	Window casing	Center	White	Wood	unit 7
PASS	0.01	12/28/16	2:21 PM	#575	Living room	2nd	West	Door casing	Center	White	Wood	unit 7
PASS	0.01	12/28/16	2:22 PM	#576	Living room	2nd	North	Baseboard	Center	White	Wood	unit 7
PASS	0	12/28/16	2:22 PM	#577	Living room	2nd	North	Floor	Center	Stain	Wood	unit 7
PASS	0.33	12/28/16	2:23 PM	#578	Living room	2nd	East	Radiator	Center	White	Metal	unit 7
▼ Kitchen												
PASS	0	12/28/16	2:23 PM	#579	Kitchen	2nd	East	Ceiling	Center	White	Plaster	unit 7
PASS	0.38	12/28/16	2:24 PM	#580	Kitchen	2nd	West	Ceiling	Center	White	Plaster	unit 7
PASS	0.01	12/28/16	2:24 PM	#581	Kitchen	2nd	North	Wall	Center	White	Plaster	unit 7
FAIL	1.28	12/28/16	2:24 PM	#582	Kitchen	2nd	East	Wall	Right	White	Plaster	unit 7
FAIL	2.1	12/28/16	2:25 PM	#583	Kitchen	2nd	East	Wall	Left	White	Plaster	unit 7

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
FAIL	1.64	12/28/16	2:25 PM	#584	Kitchen	2nd	East	Wall	Upper	White	Plaster	unit 7
PASS	0	12/28/16	2:26 PM	#585	Kitchen	2nd	West	Wall	Lower	White	Plaster	unit 7
PASS	0.49	12/28/16	2:26 PM	#586	Kitchen	2nd	East	Window casing	Center	White	Wood	unit 7
PASS	0.2	12/28/16	2:27 PM	#587	Kitchen	2nd	North	Door casing	Center	White	Wood	unit 7
PASS	0.75	12/28/16	2:27 PM	#588	Kitchen	2nd	North	Baseboard	Center	White	Wood	unit 7
PASS	0.53	12/28/16	2:28 PM	#589	Kitchen	2nd	North	Cabinet	Center	White	Wood	unit 7
▼ Bdrm 2												
PASS	0	12/28/16	2:28 PM	#590	Bdrm 2	2nd	North	Ceiling	Center	White	Plaster	unit 7
FAIL	1.36	12/28/16	2:29 PM	#591	Bdrm 2	2nd	North	Wall	Center	White	Plaster	unit 7
PASS	0.87	12/28/16	2:29 PM	#592	Bdrm 2	2nd	South	Wall	Center	White	Plaster	unit 7
FAIL	1.05	12/28/16	2:30 PM	#593	Bdrm 2	2nd	West	Wall	Upper	White	Plaster	unit 7
FAIL	1.05	12/28/16	2:30 PM	#594	Bdrm 2	2nd	East	Wall	Lower	White	Plaster	unit 7
PASS	0.25	12/28/16	2:31 PM	#595	Bdrm 2	2nd	East	Window casing	Center	White	Wood	unit 7
PASS	0.69	12/28/16	2:31 PM	#596	Bdrm 2	2nd	South	Door jamb	Center	White	Wood	unit 7
PASS	0.21	12/28/16	2:32 PM	#597	Bdrm 2	2nd	West	Door	Center	White	Wood	unit 7
PASS	0.19	12/28/16	2:32 PM	#598	Bdrm 2	2nd	West	Baseboard	Center	White	Wood	unit 7
PASS	0.69	12/28/16	2:33 PM	#599	Bdrm 2	2nd	West	Closet	Center	Gray	Plaster	unit 7
PASS	0.31	12/28/16	2:33 PM	#600	Bdrm 2	2nd	North	Radiator	Center	White	Metal	unit 7
▼ unit 3												
▼ Bdrm 1												
PASS	0	12/28/16	2:39 PM	#601	Bdrm 1	1st	North	Ceiling	Center	White	Plaster	unit 3
PASS	0	12/28/16	2:40 PM	#602	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 3
PASS	0	12/28/16	2:40 PM	#603	Bdrm 1	1st	South	Wall	Center	White	Plaster	unit 3
PASS	0	12/28/16	2:40 PM	#604	Bdrm 1	1st	West	Wall	Upper	White	Plaster	unit 3
PASS	0	12/28/16	2:40 PM	#605	Bdrm 1	1st	West	Wall	Upper	White	Plaster	unit 3
PASS	0	12/28/16	2:41 PM	#606	Bdrm 1	1st	East	Wall	Lower	White	Plaster	unit 3
PASS	0.33	12/28/16	2:41 PM	#607	Bdrm 1	1st	East	Window casing	Center	White	Wood	unit 3
PASS	0.38	12/28/16	2:42 PM	#608	Bdrm 1	1st	South	Window sash	Center	White	Wood	unit 3
PASS	0	12/28/16	2:42 PM	#609	Bdrm 1	1st	West	Door casing	Left	White	Wood	unit 3
PASS	0.18	12/28/16	2:43 PM	#610	Bdrm 1	1st	West	Door	Right	White	Wood	unit 3
PASS	0.29	12/28/16	2:43 PM	#611	Bdrm 1	1st	East	Baseboard	Center	White	Wood	unit 3
PASS	0	12/28/16	2:43 PM	#612	Bdrm 1	1st	East	Floor	Center	Stain	Wood	unit 3
PASS	0	12/28/16	2:44 PM	#613	Bdrm 1	1st	West	Closet	Center	White	Plaster	unit 3
PASS	0.7	12/28/16	2:45 PM	#614	Bdrm 1	1st	East	Radiator	Center	White	Metal	unit 3
▼ Bathroom												
PASS	0.79	12/28/16	2:46 PM	#615	Bathroom	1st	East	Radiator	Center	White	Metal	unit 3
FAIL	5	12/28/16	2:46 PM	#616	Bathroom	1st	South	Bathtub	Center	White	Metal	unit 3



PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0	12/28/16	2:47 PM	#617	Bathroom	1st	South	Floor	Center	White	Ceramic	unit 3
PASS	0.03	12/28/16	2:47 PM	#618	Bathroom	1st	North	Ceiling	Center	White	Plaster	unit 3
FAIL	1.43	12/28/16	2:48 PM	#619	Bathroom	1st	North	Wall	Center	White	Plaster	unit 3
PASS	0.54	12/28/16	2:48 PM	#620	Bathroom	1st	West	Wall	Center	White	Plaster	unit 3
PASS	0	12/28/16	2:48 PM	#621	Bathroom	1st	East	Wall	Lower	White	Plaster	unit 3
PASS	0	12/28/16	2:49 PM	#622	Bathroom	1st	South	Wall	Upper	White	Plaster	unit 3
PASS	0.9	12/28/16	2:49 PM	#623	Bathroom	1st	South	Window casing	Center	White	Wood	unit 3
PASS	0.3	12/28/16	2:50 PM	#624	Bathroom	1st	North	Door casing	Center	White	Wood	unit 3
PASS	0.01	12/28/16	2:50 PM	#625	Bathroom	1st	West	Cabinet	Center	White	Wood	unit 3
PASS	0.67	12/28/16	2:51 PM	#626	Bathroom	1st	North	Chair rail	Center	White	Wood	unit 3
▼ Hall												
PASS	0	12/28/16	2:51 PM	#627	Hall	1st	North	Ceiling	Center	White	Plaster	unit 3
PASS	0	12/28/16	2:52 PM	#628	Hall	1st	East	Wall	Upper	White	Plaster	unit 3
PASS	0	12/28/16	2:52 PM	#629	Hall	1st	West	Wall	Lower	White	Plaster	unit 3
PASS	0	12/28/16	2:52 PM	#630	Hall	1st	North	Wall	Center	White	Plaster	unit 3
PASS	0	12/28/16	2:53 PM	#631	Hall	1st	South	Wall	Center	White	Plaster	unit 3
PASS	0.36	12/28/16	2:53 PM	#632	Hall	1st	South	Door casing	Center	White	Wood	unit 3
PASS	0.38	12/28/16	2:54 PM	#633	Hall	1st	East	Cabinet	Center	White	Wood	unit 3
▼ Living room												
PASS	0	12/28/16	2:54 PM	#634	Living room	1st	East	Ceiling	Center	White	Plaster	unit 3
PASS	0	12/28/16	2:55 PM	#635	Living room	1st	North	Wall	Center	White	Plaster	unit 3
PASS	0	12/28/16	2:55 PM	#636	Living room	1st	West	Wall	Center	White	Plaster	unit 3
PASS	0	12/28/16	2:56 PM	#637	Living room	1st	South	Wall	Upper	White	Plaster	unit 3
PASS	0	12/28/16	2:56 PM	#638	Living room	1st	East	Wall	Lower	White	Plaster	unit 3
PASS	0.35	12/28/16	2:57 PM	#639	Living room	1st	East	Window casing	Center	White	Wood	unit 3
PASS	0.05	12/28/16	2:57 PM	#640	Living room	1st	South	Door casing	Center	Stain	Wood	unit 3
PASS	0.05	12/28/16	2:57 PM	#641	Living room	1st	North	Baseboard	Center	Stain	Wood	unit 3
PASS	0	12/28/16	2:58 PM	#642	Living room	1st	North	Floor	Center	Stain	Wood	unit 3
▼ Kitchen												
PASS	0.2	12/28/16	2:59 PM	#643	Kitchen	1st	East	Radiator	Center	White	Metal	unit 3
PASS	0	12/28/16	3:00 PM	#644	Kitchen	1st	East	Ceiling	Center	White	Plaster	unit 3
FAIL	1.5	12/28/16	3:00 PM	#645	Kitchen	1st	West	Ceiling	Center	White	Plaster	unit 3
PASS	0	12/28/16	3:01 PM	#646	Kitchen	1st	North	Wall	Right	White	Plaster	unit 3
FAIL	1.78	12/28/16	3:01 PM	#647	Kitchen	1st	South	Wall	Right	White	Plaster	unit 3
PASS	0	12/28/16	3:01 PM	#648	Kitchen	1st	South	Wall	Left	White	Plaster	unit 3
PASS	0	12/28/16	3:02 PM	#649	Kitchen	1st	East	Wall	Upper	White	Plaster	unit 3
PASS	0	12/28/16	3:02 PM	#650	Kitchen	1st	West	Wall	Lower	White	Plaster	unit 3

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.54	12/28/16	3:03 PM	#651	Kitchen	1st	West	Window casing	Center	White	Wood	unit 3
PASS	0.31	12/28/16	3:03 PM	#652	Kitchen	1st	West	Window sash	Center	White	Wood	unit 3
PASS	0.27	12/28/16	3:04 PM	#653	Kitchen	1st	North	Door casing	Center	White	Wood	unit 3
PASS	0.58	12/28/16	3:04 PM	#654	Kitchen	1st	North	Baseboard	Center	White	Wood	unit 3
PASS	0.27	12/28/16	3:04 PM	#655	Kitchen	1st	North	Cabinet	Center	White	Wood	unit 3
▼ Bdrm 2												
PASS	0	12/28/16	3:05 PM	#656	Bdrm 2	1st	North	Ceiling	Center	White	Plaster	unit 3
PASS	0	12/28/16	3:06 PM	#657	Bdrm 2	1st	North	Wall	Center	White	Plaster	unit 3
PASS	0	12/28/16	3:06 PM	#658	Bdrm 2	1st	West	Wall	Center	White	Plaster	unit 3
PASS	0	12/28/16	3:06 PM	#659	Bdrm 2	1st	South	Wall	Upper	White	Plaster	unit 3
PASS	0	12/28/16	3:07 PM	#660	Bdrm 2	1st	East	Wall	Lower	White	Plaster	unit 3
PASS	0.31	12/28/16	3:07 PM	#661	Bdrm 2	1st	East	Window casing	Center	White	Wood	unit 3
PASS	0.32	12/28/16	3:08 PM	#662	Bdrm 2	1st	South	Door casing	Center	White	Wood	unit 3
PASS	0.14	12/28/16	3:08 PM	#663	Bdrm 2	1st	West	Door	Center	White	Wood	unit 3
PASS	0.32	12/28/16	3:08 PM	#664	Bdrm 2	1st	North	Baseboard	Center	White	Wood	unit 3
PASS	0	12/28/16	3:09 PM	#665	Bdrm 2	1st	North	Floor	Center	Stain	Wood	unit 3