

# Minnesota Lead Testers

952-200-5044

## Client Information

Performance Equity LLC  
8362 Tamarack vlg, ste  
119-308

Woodburv mn 55125

**Contact:** Jon 715-220-7467



*Paul Nygren*  
Director, Env. Health Div.

 **LEAD  
Risk Assessor**

Licensed by:  
State of Minnesota  
Department of Health  
**License No. LR3633**  
**Expires 11/11/2017**

**Paul Nygren**  
6225 207th Ave NE  
Wyoming, MN 55092

## XRF Test Results

Time of Test:	8:06 AM	12/7/16
---------------	---------	---------

## Test Site Information

**Owner:** Performance Equity LLC

**Age of Property:** 1929

**Address:** 2517 Golden Valley Rd  
Minneapolis MN 55411



## Minnesota Lead Testers

6225 207th Ave. NE, Wyoming MN 55092  
952-200-5044 Paul Nygren, Owner

**Firm License # LF 3614**

**XRF Analyzer Manufacture:** Innov-X

**Model:** Delta LBP-4000 **Serial #** 560309

# Minnesota Lead Testers

952-200-5044

**These readings are for calibration purposes only, not part of test results.**

Start	8:06 AM	NIST Check - Passed
Finish	4:41 PM	NIST Check - Passed

- = no or minute amounts of lead present
- = 0.2 - .99 Micrograms per square cm of lead present
- = 1.0 Microgram or greater per square cm of lead present: **Lead safe practices required if disturbing these surfaces**

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
▼ unit 101												
▼ Kitchen												
PASS	<span style="background-color: yellow;">0.33</span>	12/7/16	8:06 AM	#3	Kitchen	LL	South	Ceiling	Center	White	Plaster	unit 101
PASS	<span style="background-color: yellow;">0.28</span>	12/7/16	8:07 AM	#4	Kitchen	1st	North	Wall	Center	White	Plaster	unit 101
PASS	<span style="background-color: green;">0</span>	12/7/16	8:07 AM	#5	Kitchen	1st	South	Wall	Center	White	Plaster	unit 101
PASS	<span style="background-color: yellow;">0.6</span>	12/7/16	8:08 AM	#6	Kitchen	1st	East	Wall	Upper	White	Plaster	unit 101
PASS	<span style="background-color: green;">0</span>	12/7/16	8:08 AM	#7	Kitchen	1st	West	Wall	Lower	White	Plaster	unit 101
PASS	<span style="background-color: yellow;">0.43</span>	12/7/16	8:09 AM	#8	Kitchen	1st	North	Window casing	Center	White	Wood	unit 101
PASS	<span style="background-color: green;">0.17</span>	12/7/16	8:09 AM	#9	Kitchen	1st	North	Window sash	Center	White	Wood	unit 101
PASS	<span style="background-color: green;">0.15</span>	12/7/16	8:10 AM	#10	Kitchen	1st	West	Door casing	Center	White	Wood	unit 101
PASS	<span style="background-color: green;">0</span>	12/7/16	8:10 AM	#11	Kitchen	1st	West	Baseboard	Center	White	Wood	unit 101
PASS	<span style="background-color: green;">0.14</span>	12/7/16	8:11 AM	#12	Kitchen	1st	South	Cabinet	Center	White	Wood	unit 101
▼ Dining												
PASS	<span style="background-color: green;">0.01</span>	12/7/16	8:12 AM	#13	Dining	1st	South	Ceiling	Center	White	Plaster	unit 101
PASS	<span style="background-color: yellow;">0.54</span>	12/7/16	8:12 AM	#14	Dining	1st	South	Wall	Center	White	Plaster	unit 101
PASS	<span style="background-color: green;">0.16</span>	12/7/16	8:13 AM	#15	Dining	1st	North	Wall	Center	White	Plaster	unit 101
PASS	<span style="background-color: yellow;">0.67</span>	12/7/16	8:13 AM	#16	Dining	1st	West	Wall	Upper	White	Plaster	unit 101
PASS	<span style="background-color: yellow;">0.54</span>	12/7/16	8:14 AM	#17	Dining	1st	East	Wall	Lower	White	Plaster	unit 101
PASS	<span style="background-color: green;">0.05</span>	12/7/16	8:14 AM	#18	Dining	1st	North	Window casing	Center	Stain	Wood	unit 101

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.05	12/7/16	8:15 AM	#19	Dining	1st	East	Door casing	Center	Stain	Wood	unit 101
PASS	0.58	12/7/16	8:16 AM	#20	Dining	1st	South	Cabinet	Left	Stain	Wood	unit 101
PASS	0.05	12/7/16	8:16 AM	#21	Dining	1st	South	Baseboard	Center	Stain	Wood	unit 101
▼ Living room												
PASS	0.8	12/7/16	8:17 AM	#22	Living room	1st	South	Ceiling	Center	White	Plaster	unit 101
PASS	0.53	12/7/16	8:18 AM	#23	Living room	1st	South	Wall	Center	White	Plaster	unit 101
PASS	0.53	12/7/16	8:18 AM	#24	Living room	1st	West	Wall	Center	White	Plaster	unit 101
PASS	0.01	12/7/16	8:19 AM	#25	Living room	1st	East	Wall	Upper	White	Plaster	unit 101
PASS	0.96	12/7/16	8:20 AM	#26	Living room	1st	North	Wall	Lower	White	Plaster	unit 101
PASS	0.06	12/7/16	8:20 AM	#27	Living room	1st	North	Window casing	Center	Stain	Wood	unit 101
PASS	0	12/7/16	8:21 AM	#28	Living room	1st	South	Door	Center	Stain	Wood	unit 101
PASS	0.06	12/7/16	8:21 AM	#29	Living room	1st	South	Door casing	Center	Stain	Wood	unit 101
PASS	0.08	12/7/16	8:22 AM	#30	Living room	1st	West	Door casing	Right	Stain	Wood	unit 101
PASS	0.05	12/7/16	8:23 AM	#31	Living room	1st	East	Baseboard	Center	Stain	Wood	unit 101
▼ Bathroom												
PASS	0	12/7/16	8:24 AM	#32	Bathroom	1st	South	Wall	Center	White	Plaster	unit 101
PASS	0	12/7/16	8:25 AM	#33	Bathroom	1st	West	Wall	Center	White	Plaster	unit 101
PASS	0.73	12/7/16	8:25 AM	#34	Bathroom	1st	East	Wall	Upper	White	Plaster	unit 101
PASS	0.02	12/7/16	8:26 AM	#35	Bathroom	1st	North	Wall	Upper	White	Ceramic	unit 101
PASS	0.35	12/7/16	8:26 AM	#36	Bathroom	1st	North	Window casing	Center	White	Wood	unit 101
PASS	0.19	12/7/16	8:27 AM	#37	Bathroom	1st	South	Door casing	Center	White	Wood	unit 101
FAIL	5	12/7/16	8:28 AM	#38	Bathroom	1st	North	Bathtub	Center	White	Metal	unit 101
▼ Bdrm 1												
PASS	0	12/7/16	8:28 AM	#39	Bdrm 1	1st	North	Ceiling	Center	White	Plaster	unit 101
PASS	0	12/7/16	8:29 AM	#40	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 101
PASS	0	12/7/16	8:29 AM	#41	Bdrm 1	1st	South	Wall	Center	White	Plaster	unit 101
PASS	0	12/7/16	8:30 AM	#42	Bdrm 1	1st	East	Wall	Lower	White	Plaster	unit 101
PASS	0	12/7/16	8:30 AM	#43	Bdrm 1	1st	West	Wall	Upper	White	Plaster	unit 101
PASS	0.08	12/7/16	8:31 AM	#44	Bdrm 1	1st	West	Window casing	Center	White	Wood	unit 101
PASS	0.08	12/7/16	8:31 AM	#45	Bdrm 1	1st	North	Window sash	Center	White	Wood	unit 101
PASS	0.06	12/7/16	8:32 AM	#46	Bdrm 1	1st	South	Door casing	Center	White	Wood	unit 101
PASS	0.03	12/7/16	8:33 AM	#47	Bdrm 1	1st	East	Door	Center	Stain	Wood	unit 101
PASS	0.01	12/7/16	8:33 AM	#48	Bdrm 1	1st	South	Closet	Center	White	Plaster	unit 101
▼ unit 106												
▼ Bdrm 1												
PASS	0	12/7/16	8:35 AM	#49	Bdrm 1	1st	South	Ceiling	Center	White	Plaster	unit 106
PASS	0	12/7/16	8:36 AM	#50	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 106

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0	12/7/16	8:36 AM	#51	Bdrm 1	1st	South	Wall	Center	White	Plaster	unit 106
PASS	0	12/7/16	8:37 AM	#52	Bdrm 1	1st	West	Wall	Upper	White	Plaster	unit 106
PASS	0	12/7/16	8:37 AM	#53	Bdrm 1	1st	East	Wall	Lower	White	Plaster	unit 106
PASS	0.38	12/7/16	8:37 AM	#54	Bdrm 1	1st	East	Window casing	Center	White	Wood	unit 106
PASS	0	12/7/16	8:38 AM	#55	Bdrm 1	1st	South	Window sash	Center	White	Wood	unit 106
PASS	0.02	12/7/16	8:38 AM	#56	Bdrm 1	1st	West	Door casing	Left	White	Wood	unit 106
PASS	0.09	12/7/16	8:39 AM	#57	Bdrm 1	1st	West	Door jamb	Right	White	Wood	unit 106
PASS	0	12/7/16	8:40 AM	#58	Bdrm 1	1st	North	Baseboard	Center	White	Wood	unit 106
▼ Bdrm 2												
PASS	0	12/7/16	8:40 AM	#59	Bdrm 2	1st	North	Ceiling	Center	White	Plaster	unit 106
PASS	0	12/7/16	8:41 AM	#60	Bdrm 2	1st	North	Wall	Center	White	Plaster	unit 106
PASS	0	12/7/16	8:41 AM	#61	Bdrm 2	1st	East	Wall	Center	White	Plaster	unit 106
PASS	0	12/7/16	8:41 AM	#62	Bdrm 2	1st	West	Wall	Upper	White	Plaster	unit 106
PASS	0	12/7/16	8:42 AM	#63	Bdrm 2	1st	South	Wall	Lower	White	Plaster	unit 106
PASS	0.02	12/7/16	8:42 AM	#64	Bdrm 2	1st	South	Window casing	Center	White	Wood	unit 106
PASS	0.64	12/7/16	8:43 AM	#65	Bdrm 2	1st	West	Window sash	Center	White	Wood	unit 106
PASS	0.01	12/7/16	8:44 AM	#66	Bdrm 2	1st	South	Baseboard	Center	White	Wood	unit 106
PASS	0.01	12/7/16	8:44 AM	#67	Bdrm 2	1st	South	Radiator	Center	White	Metal	unit 106
▼ Bathroom												
PASS	0.51	12/7/16	8:45 AM	#68	Bathroom	1st	North	Radiator	Center	White	Metal	unit 106
FAIL	5	12/7/16	8:46 AM	#69	Bathroom	1st	East	Bathtub	Center	White	Metal	unit 106
PASS	0	12/7/16	8:46 AM	#70	Bathroom	1st	East	Ceiling	Center	White	Plaster	unit 106
PASS	0.01	12/7/16	8:47 AM	#71	Bathroom	1st	North	Wall	Center	White	Plaster	unit 106
PASS	0	12/7/16	8:47 AM	#72	Bathroom	1st	South	Wall	Center	White	Plaster	unit 106
PASS	0.75	12/7/16	8:48 AM	#73	Bathroom	1st	West	Wall	Upper	White	Plaster	unit 106
PASS	0	12/7/16	8:48 AM	#74	Bathroom	1st	East	Wall	Lower	White	Plaster	unit 106
PASS	0.17	12/7/16	8:49 AM	#75	Bathroom	1st	East	Window casing	Center	White	Wood	unit 106
PASS	0.2	12/7/16	8:50 AM	#76	Bathroom	1st	West	Door casing	Center	White	Wood	unit 106
PASS	0.01	12/7/16	8:50 AM	#77	Bathroom	1st	West	Floor	Center	Blue	Ceramic	unit 106
PASS	0.18	12/7/16	8:51 AM	#78	Bathroom	1st	South	Cabinet	Center	White	Wood	unit 106
▼ Living room												
PASS	0.01	12/7/16	8:52 AM	#79	Living room	1st	South	Ceiling	Center	White	Plaster	unit 106
PASS	0.64	12/7/16	8:52 AM	#80	Living room	1st	South	Wall	Center	White	Plaster	unit 106
PASS	0.45	12/7/16	8:53 AM	#81	Living room	1st	East	Wall	Center	White	Plaster	unit 106
PASS	0.12	12/7/16	8:53 AM	#82	Living room	1st	West	Wall	Upper	White	Plaster	unit 106
PASS	0.18	12/7/16	8:54 AM	#83	Living room	1st	North	Wall	Lower	White	Plaster	unit 106
PASS	0.09	12/7/16	8:55 AM	#84	Living room	1st	West	Window casing	Right	Stain	Wood	unit 106



PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.6	12/7/16	8:55 AM	#85	Living room	1st	West	Window sash	Left	Stain	Wood	unit 106
PASS	0.1	12/7/16	8:56 AM	#86	Living room	1st	East	Door casing	Right	Stain	Wood	unit 106
PASS	0.09	12/7/16	8:57 AM	#87	Living room	1st	East	Baseboard	Center	Stain	Wood	unit 106
▼ Kitchen												
PASS	0	12/7/16	8:58 AM	#88	Kitchen	1st	East	Ceiling	Center	White	Plaster	unit 106
PASS	0	12/7/16	8:59 AM	#89	Kitchen	1st	North	Wall	Center	White	Plaster	unit 106
PASS	0.57	12/7/16	8:59 AM	#90	Kitchen	1st	North	Wall	Left	White	Plaster	unit 106
PASS	0.1	12/7/16	9:00 AM	#91	Kitchen	1st	South	Wall	Center	White	Plaster	unit 106
PASS	0	12/7/16	9:00 AM	#92	Kitchen	1st	East	Wall	Upper	White	Plaster	unit 106
PASS	0.6	12/7/16	9:01 AM	#93	Kitchen	1st	West	Wall	Lower	White	Plaster	unit 106
PASS	0.07	12/7/16	9:01 AM	#94	Kitchen	1st	West	Window casing	Center	Stain	Wood	unit 106
PASS	0.06	12/7/16	9:02 AM	#95	Kitchen	1st	West	Cabinet	Left	Stain	Wood	unit 106
PASS	0.12	12/7/16	9:03 AM	#96	Kitchen	1st	South	Cabinet	Upper	White	Wood	unit 106
PASS	0.49	12/7/16	9:03 AM	#97	Kitchen	1st	South	Cabinet	Lower	White	Wood	unit 106
PASS	0	12/7/16	9:04 AM	#98	Kitchen	1st	East	Baseboard	Center	White	Wood	unit 106
▼ unit 105												
▼ Kitchen												
PASS	0	12/7/16	9:07 AM	#99	Kitchen	1st	East	Ceiling	Center	White	Plaster	unit 105
PASS	0	12/7/16	9:08 AM	#100	Kitchen	1st	North	Wall	Center	White	Plaster	unit 105
FAIL	2.82	12/7/16	9:08 AM	#101	Kitchen	1st	South	Wall	Center	White	Plaster	unit 105
FAIL	1.65	12/7/16	9:09 AM	#102	Kitchen	1st	East	Wall	Upper	White	Plaster	unit 105
PASS	0.07	12/7/16	9:10 AM	#103	Kitchen	1st	East	Window casing	Center	White	Wood	unit 105
PASS	0.1	12/7/16	9:10 AM	#104	Kitchen	1st	East	Cabinet	Center	White	Wood	unit 105
PASS	0.29	12/7/16	9:11 AM	#105	Kitchen	1st	West	Baseboard	Center	White	Wood	unit 105
▼ Living room												
PASS	0.01	12/7/16	9:12 AM	#106	Living room	1st	West	Ceiling	Center	White	Plaster	unit 105
PASS	0.78	12/7/16	9:13 AM	#107	Living room	1st	North	Wall	Center	White	Plaster	unit 105
FAIL	1.01	12/7/16	9:14 AM	#108	Living room	1st	South	Wall	Center	White	Plaster	unit 105
PASS	0	12/7/16	9:14 AM	#109	Living room	1st	West	Wall	Upper	White	Plaster	unit 105
PASS	0.47	12/7/16	9:15 AM	#110	Living room	1st	East	Wall	Lower	White	Plaster	unit 105
PASS	0.03	12/7/16	9:15 AM	#111	Living room	1st	South	Window casing	Center	White	Wood	unit 105
PASS	0.03	12/7/16	9:16 AM	#112	Living room	1st	East	Door casing	Center	White	Wood	unit 105
PASS	0.07	12/7/16	9:17 AM	#113	Living room	1st	East	Door	Left	White	Wood	unit 105
PASS	0.25	12/7/16	9:17 AM	#114	Living room	1st	West	Baseboard	Center	White	Wood	unit 105
▼ Bathroom												
PASS	0	12/7/16	9:18 AM	#115	Bathroom	1st	West	Ceiling	Center	White	Plaster	unit 105
PASS	0.01	12/7/16	9:19 AM	#116	Bathroom	1st	North	Wall	Center	White	Plaster	unit 105

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0	12/7/16	9:20 AM	#117	Bathroom	1st	West	Wall	Center	White	Plaster	unit 105
PASS	0	12/7/16	9:20 AM	#118	Bathroom	1st	East	Wall	Center	White	Plaster	unit 105
PASS	0	12/7/16	9:21 AM	#119	Bathroom	1st	South	Wall	Upper	White	Plaster	unit 105
PASS	0.21	12/7/16	9:21 AM	#120	Bathroom	1st	South	Window casing	Center	White	Wood	unit 105
PASS	0.01	12/7/16	9:22 AM	#121	Bathroom	1st	North	Door casing	Center	White	Wood	unit 105
PASS	0.02	12/7/16	9:22 AM	#122	Bathroom	1st	East	Cabinet	Center	White	Wood	unit 105
PASS	0.02	12/7/16	9:23 AM	#123	Bathroom	1st	East	Floor	Center	Blue	Ceramic	unit 105
FAIL	5	12/7/16	9:24 AM	#124	Bathroom	1st	South	Bathtub	Center	White	Metal	unit 105
▼ Bdrm 1												
PASS	0	12/7/16	9:25 AM	#125	Bdrm 1	1st	North	Ceiling	Center	White	Plaster	unit 105
PASS	0	12/7/16	9:25 AM	#126	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 105
PASS	0	12/7/16	9:26 AM	#127	Bdrm 1	1st	East	Wall	Center	White	Plaster	unit 105
PASS	0	12/7/16	9:26 AM	#128	Bdrm 1	1st	West	Wall	Upper	White	Plaster	unit 105
PASS	0	12/7/16	9:27 AM	#129	Bdrm 1	1st	South	Wall	Lower	White	Plaster	unit 105
PASS	0.1	12/7/16	9:28 AM	#130	Bdrm 1	1st	South	Window casing	Center	White	Wood	unit 105
PASS	0.09	12/7/16	9:28 AM	#131	Bdrm 1	1st	West	Door casing	Center	White	Wood	unit 105
PASS	0.06	12/7/16	9:29 AM	#132	Bdrm 1	1st	North	Door	Center	Stain	Wood	unit 105
PASS	0.01	12/7/16	9:29 AM	#133	Bdrm 1	1st	North	Baseboard	Center	White	Wood	unit 105
PASS	0.02	12/7/16	9:30 AM	#134	Bdrm 1	1st	North	Closet	Center	White	Plaster	unit 105
PASS	0	12/7/16	9:30 AM	#135	Bdrm 1	1st	North	Floor	Center	Stain	Wood	unit 105
▼ unit 104												
▼ Bathroom												
PASS	0.69	12/7/16	9:33 AM	#136	Bathroom	1st	North	Wall	Center	White	Plaster	unit 104
PASS	0.75	12/7/16	9:33 AM	#137	Bathroom	1st	South	Wall	Center	White	Plaster	unit 104
PASS	0.72	12/7/16	9:34 AM	#138	Bathroom	1st	East	Wall	Upper	White	Plaster	unit 104
PASS	0.31	12/7/16	9:34 AM	#139	Bathroom	1st	West	Wall	Upper	White	Plaster	unit 104
PASS	0.32	12/7/16	9:35 AM	#140	Bathroom	1st	West	Window casing	Center	White	Wood	unit 104
PASS	0.35	12/7/16	9:35 AM	#141	Bathroom	1st	North	Door casing	Center	White	Wood	unit 104
▼ Living room												
PASS	0.01	12/7/16	9:36 AM	#142	Living room	1st	North	Ceiling	Center	White	Plaster	unit 104
PASS	0.01	12/7/16	9:37 AM	#143	Living room	1st	North	Wall	Center	White	Plaster	unit 104
PASS	0.07	12/7/16	9:38 AM	#144	Living room	1st	South	Wall	Center	White	Plaster	unit 104
PASS	0.01	12/7/16	9:39 AM	#145	Living room	1st	West	Wall	Upper	White	Plaster	unit 104
PASS	0.48	12/7/16	9:39 AM	#146	Living room	1st	East	Wall	Lower	White	Plaster	unit 104
PASS	0.34	12/7/16	9:40 AM	#147	Living room	1st	West	Window casing	Center	White	Wood	unit 104
PASS	0.05	12/7/16	9:41 AM	#148	Living room	1st	South	Door casing	Right	Stain	Wood	unit 104
PASS	0	12/7/16	9:41 AM	#149	Living room	1st	East	Door	Center	White	Wood	unit 104

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.37	12/7/16	9:42 AM	#150	Living room	1st	North	Baseboard	Center	White	Wood	unit 104
▼ Kitchen												
PASS	0	12/7/16	9:43 AM	#151	Kitchen	1st	North	Ceiling	Center	White	Plaster	unit 104
PASS	0.55	12/7/16	9:43 AM	#152	Kitchen	1st	North	Wall	Left	White	Plaster	unit 104
PASS	0.19	12/7/16	9:44 AM	#153	Kitchen	1st	North	Wall	Right	White	Plaster	unit 104
PASS	0.49	12/7/16	9:44 AM	#154	Kitchen	1st	South	Wall	Right	White	Plaster	unit 104
PASS	0	12/7/16	9:45 AM	#155	Kitchen	1st	East	Wall	Upper	White	Plaster	unit 104
PASS	0.46	12/7/16	9:46 AM	#156	Kitchen	1st	West	Wall	Lower	White	Plaster	unit 104
PASS	0.33	12/7/16	9:46 AM	#157	Kitchen	1st	West	Window casing	Center	White	Wood	unit 104
PASS	0.11	12/7/16	9:47 AM	#158	Kitchen	1st	South	Cabinet	Upper	White	Wood	unit 104
PASS	0.4	12/7/16	9:48 AM	#159	Kitchen	1st	South	Cabinet	Lower	White	Wood	unit 104
PASS	0	12/7/16	9:48 AM	#160	Kitchen	1st	East	Baseboard	Center	White	Wood	unit 104
▼ unit 102												
▼ Kitchen												
PASS	0.15	12/7/16	9:51 AM	#161	Kitchen	1st	East	Ceiling	Center	White	Plaster	unit 102
PASS	0.13	12/7/16	9:52 AM	#162	Kitchen	1st	North	Wall	Center	White	Plaster	unit 102
PASS	0	12/7/16	9:52 AM	#163	Kitchen	1st	South	Wall	Center	White	Plaster	unit 102
PASS	0.09	12/7/16	9:53 AM	#164	Kitchen	1st	East	Wall	Upper	White	Plaster	unit 102
PASS	0	12/7/16	9:53 AM	#165	Kitchen	1st	West	Wall	Lower	White	Plaster	unit 102
PASS	0.1	12/7/16	9:54 AM	#166	Kitchen	1st	North	Window casing	Center	White	Wood	unit 102
PASS	0.11	12/7/16	9:54 AM	#167	Kitchen	1st	East	Door casing	Center	White	Wood	unit 102
PASS	0	12/7/16	9:55 AM	#168	Kitchen	1st	East	Baseboard	Center	White	Wood	unit 102
▼ Dining												
PASS	0.09	12/7/16	9:56 AM	#170	Dining	1st	West	Baseboard	Center	White	Wood	unit 102
PASS	0.1	12/7/16	9:56 AM	#171	Dining	1st	West	Door casing	Center	White	Wood	unit 102
PASS	0.11	12/7/16	9:57 AM	#172	Dining	1st	North	Window casing	Center	White	Wood	unit 102
PASS	0	12/7/16	9:57 AM	#173	Dining	1st	North	Ceiling	Center	White	Plaster	unit 102
PASS	0.01	12/7/16	9:58 AM	#174	Dining	1st	North	Wall	Center	White	Plaster	unit 102
PASS	0.8	12/7/16	9:58 AM	#175	Dining	1st	South	Wall	Center	White	Plaster	unit 102
PASS	0.09	12/7/16	9:59 AM	#176	Dining	1st	East	Wall	Upper	White	Plaster	unit 102
PASS	0.73	12/7/16	10:00 AM	#177	Dining	1st	West	Wall	Lower	White	Plaster	unit 102
PASS	0.08	12/7/16	10:00 AM	#178	Dining	1st	West	Cabinet	Right	White	Wood	unit 102
▼ Living room												
PASS	0.01	12/7/16	10:01 AM	#179	Living room	1st	West	Ceiling	Center	White	Plaster	unit 102
PASS	0.81	12/7/16	10:02 AM	#180	Living room	1st	West	Wall	Center	White	Plaster	unit 102
PASS	0.09	12/7/16	10:03 AM	#181	Living room	1st	South	Wall	Center	White	Plaster	unit 102
PASS	0.81	12/7/16	10:03 AM	#182	Living room	1st	East	Wall	Upper	White	Plaster	unit 102

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.02	12/7/16	10:04 AM	#183	Living room	1st	North	Wall	Lower	White	Plaster	unit 102
PASS	0.11	12/7/16	10:05 AM	#184	Living room	1st	North	Window casing	Center	White	Wood	unit 102
PASS	0.11	12/7/16	10:05 AM	#185	Living room	1st	South	Door casing	Center	White	Wood	unit 102
PASS	0.08	12/7/16	10:06 AM	#186	Living room	1st	East	Door jamb	Center	White	Wood	unit 102
▼ Bathroom												
PASS	0	12/7/16	10:07 AM	#187	Bathroom	1st	East	Ceiling	Center	White	Plaster	unit 102
PASS	0.04	12/7/16	10:07 AM	#188	Bathroom	1st	North	Wall	Center	White	Plaster	unit 102
PASS	0	12/7/16	10:08 AM	#189	Bathroom	1st	South	Wall	Center	White	Plaster	unit 102
PASS	0	12/7/16	10:08 AM	#190	Bathroom	1st	East	Wall	Upper	White	Plaster	unit 102
PASS	0.01	12/7/16	10:08 AM	#191	Bathroom	1st	West	Wall	Upper	White	Plaster	unit 102
PASS	0.09	12/7/16	10:09 AM	#192	Bathroom	1st	North	Window casing	Center	White	Wood	unit 102
PASS	0.02	12/7/16	10:10 AM	#193	Bathroom	1st	South	Door	Center	White	Wood	unit 102
PASS	0.1	12/7/16	10:10 AM	#194	Bathroom	1st	West	Radiator	Center	White	Metal	unit 102
▼ Bdrm 1												
PASS	0	12/7/16	10:11 AM	#195	Bdrm 1	1st	West	Ceiling	Center	White	Plaster	unit 102
PASS	0	12/7/16	10:12 AM	#196	Bdrm 1	1st	West	Wall	Center	White	Plaster	unit 102
PASS	0	12/7/16	10:12 AM	#197	Bdrm 1	1st	East	Wall	Center	White	Plaster	unit 102
PASS	0	12/7/16	10:13 AM	#198	Bdrm 1	1st	South	Wall	Upper	White	Plaster	unit 102
PASS	0	12/7/16	10:13 AM	#199	Bdrm 1	1st	North	Wall	Lower	White	Plaster	unit 102
PASS	0	12/7/16	10:14 AM	#200	Bdrm 1	1st	North	Window casing	Center	White	Wood	unit 102
PASS	0.02	12/7/16	10:14 AM	#201	Bdrm 1	1st	East	Window sash	Center	White	Wood	unit 102
PASS	0.01	12/7/16	10:15 AM	#202	Bdrm 1	1st	North	Baseboard	Center	White	Wood	unit 102
PASS	0.15	12/7/16	10:16 AM	#203	Bdrm 1	1st	North	Radiator	Center	White	Metal	unit 102
PASS	0.01	12/7/16	10:16 AM	#204	Bdrm 1	1st	South	Closet	Center	White	Plaster	unit 102
▼ unit 103												
▼ Living room												
PASS	0.01	12/7/16	10:19 AM	#205	Living room	1st	South	Ceiling	Center	White	Plaster	unit 103
PASS	0.56	12/7/16	10:19 AM	#206	Living room	1st	North	Wall	Center	White	Plaster	unit 103
PASS	0.26	12/7/16	10:20 AM	#207	Living room	1st	South	Wall	Center	White	Plaster	unit 103
PASS	0.67	12/7/16	10:20 AM	#208	Living room	1st	West	Wall	Upper	White	Plaster	unit 103
PASS	0.69	12/7/16	10:21 AM	#209	Living room	1st	East	Wall	Lower	White	Plaster	unit 103
PASS	0.07	12/7/16	10:22 AM	#210	Living room	1st	East	Window casing	Center	Stain	Wood	unit 103
PASS	0.09	12/7/16	10:22 AM	#211	Living room	1st	West	Door casing	Center	Stain	Wood	unit 103
PASS	0.08	12/7/16	10:23 AM	#212	Living room	1st	South	Door jamb	Center	Stain	Wood	unit 103
PASS	0.06	12/7/16	10:24 AM	#213	Living room	1st	South	Baseboard	Center	Stain	Wood	unit 103
PASS	0.32	12/7/16	10:24 AM	#214	Living room	1st	East	Radiator	Center	White	Metal	unit 103
▼ Entry												



PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.01	12/7/16	10:25 AM	#215	Entry	1st	East	Ceiling	Center	White	Plaster	unit 103
PASS	0.5	12/7/16	10:26 AM	#216	Entry	1st	North	Wall	Center	White	Plaster	unit 103
PASS	0.36	12/7/16	10:26 AM	#217	Entry	1st	South	Wall	Center	White	Plaster	unit 103
PASS	0.23	12/7/16	10:27 AM	#218	Entry	1st	West	Wall	Upper	White	Plaster	unit 103
PASS	0.11	12/7/16	10:27 AM	#219	Entry	1st	East	Wall	Lower	White	Plaster	unit 103
PASS	0.08	12/7/16	10:28 AM	#220	Entry	1st	East	Window casing	Center	Stain	Wood	unit 103
PASS	0.07	12/7/16	10:29 AM	#221	Entry	1st	North	Door casing	Center	Stain	Wood	unit 103
▼ Kitchen												
PASS	0.21	12/7/16	10:30 AM	#222	Kitchen	1st	North	Ceiling	Center	White	Plaster	unit 103
PASS	0.23	12/7/16	10:30 AM	#223	Kitchen	1st	North	Wall	Center	White	Plaster	unit 103
PASS	0.53	12/7/16	10:31 AM	#224	Kitchen	1st	South	Wall	Center	White	Plaster	unit 103
PASS	0	12/7/16	10:31 AM	#225	Kitchen	1st	West	Wall	Lower	White	Plaster	unit 103
PASS	0.02	12/7/16	10:32 AM	#226	Kitchen	1st	East	Wall	Upper	White	Plaster	unit 103
PASS	0.42	12/7/16	10:32 AM	#227	Kitchen	1st	East	Window casing	Center	White	Wood	unit 103
PASS	0.45	12/7/16	10:33 AM	#228	Kitchen	1st	South	Door casing	Center	White	Wood	unit 103
PASS	0	12/7/16	10:33 AM	#229	Kitchen	1st	West	Baseboard	Center	White	Wood	unit 103
PASS	0.16	12/7/16	10:34 AM	#230	Kitchen	1st	South	Cabinet	Center	White	Wood	unit 103
▼ Bathroom												
PASS	0.23	12/7/16	10:35 AM	#231	Bathroom	1st	North	Cabinet	Center	White	Wood	unit 103
PASS	0.43	12/7/16	10:36 AM	#232	Bathroom	1st	West	Door casing	Center	White	Wood	unit 103
PASS	0.01	12/7/16	10:36 AM	#233	Bathroom	1st	West	Cabinet	Left	White	Wood	unit 103
PASS	0.01	12/7/16	10:37 AM	#234	Bathroom	1st	East	Window casing	Center	White	Wood	unit 103
PASS	0	12/7/16	10:38 AM	#235	Bathroom	1st	East	Ceiling	Center	White	Plaster	unit 103
PASS	0.55	12/7/16	10:38 AM	#236	Bathroom	1st	East	Wall	Center	White	Plaster	unit 103
PASS	0	12/7/16	10:39 AM	#237	Bathroom	1st	North	Wall	Center	White	Plaster	unit 103
PASS	0	12/7/16	10:39 AM	#238	Bathroom	1st	South	Wall	Center	White	Plaster	unit 103
PASS	0	12/7/16	10:40 AM	#239	Bathroom	1st	West	Wall	Upper	White	Plaster	unit 103
▼ Bdrm 2												
PASS	0.02	12/7/16	10:41 AM	#240	Bdrm 2	1st	West	Ceiling	Center	White	Plaster	unit 103
PASS	0.01	12/7/16	10:41 AM	#241	Bdrm 2	1st	North	Wall	Center	White	Plaster	unit 103
PASS	0.01	12/7/16	10:42 AM	#242	Bdrm 2	1st	West	Wall	Center	White	Plaster	unit 103
PASS	0.01	12/7/16	10:42 AM	#243	Bdrm 2	1st	East	Wall	Upper	White	Plaster	unit 103
PASS	0.01	12/7/16	10:43 AM	#244	Bdrm 2	1st	South	Wall	Lower	White	Plaster	unit 103
PASS	0.1	12/7/16	10:44 AM	#245	Bdrm 2	1st	West	Window casing	Center	White	Wood	unit 103
PASS	0.02	12/7/16	10:45 AM	#246	Bdrm 2	1st	East	Door casing	Center	White	Wood	unit 103
PASS	0.5	12/7/16	10:45 AM	#247	Bdrm 2	1st	East	Baseboard	Center	White	Wood	unit 103
▼ Bdrm 1												

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.01	12/7/16	10:46 AM	#248	Bdrm 1	1st	East	Ceiling	Center	White	Plaster	unit 103
PASS	0	12/7/16	10:47 AM	#249	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 103
PASS	0.01	12/7/16	10:47 AM	#250	Bdrm 1	1st	South	Wall	Center	White	Plaster	unit 103
PASS	0.04	12/7/16	10:48 AM	#251	Bdrm 1	1st	West	Wall	Upper	White	Plaster	unit 103
PASS	0.01	12/7/16	10:49 AM	#252	Bdrm 1	1st	East	Wall	Lower	White	Plaster	unit 103
PASS	0.13	12/7/16	10:49 AM	#253	Bdrm 1	1st	East	Window casing	Center	White	Wood	unit 103
PASS	0.16	12/7/16	10:50 AM	#254	Bdrm 1	1st	South	Window sash	Center	White	Wood	unit 103
PASS	0.14	12/7/16	10:51 AM	#255	Bdrm 1	1st	West	Door casing	Left	White	Wood	unit 103
PASS	0.02	12/7/16	10:51 AM	#256	Bdrm 1	1st	West	Door	Right	White	Wood	unit 103
PASS	0.33	12/7/16	10:52 AM	#257	Bdrm 1	1st	West	Baseboard	Center	White	Wood	unit 103
PASS	0	12/7/16	10:52 AM	#258	Bdrm 1	1st	West	Floor	Center	Stain	Wood	unit 103
▼ unit 203												
▼ Kitchen												
PASS	0.67	12/7/16	10:56 AM	#259	Kitchen	2nd	West	Ceiling	Center	White	Plaster	unit 203
PASS	0.2	12/7/16	10:57 AM	#260	Kitchen	2nd	North	Wall	Center	White	Plaster	unit 203
PASS	0	12/7/16	10:57 AM	#261	Kitchen	2nd	South	Wall	Center	White	Plaster	unit 203
PASS	0	12/7/16	10:58 AM	#262	Kitchen	2nd	West	Wall	Center	White	Plaster	unit 203
PASS	0.22	12/7/16	10:58 AM	#263	Kitchen	2nd	East	Wall	Upper	White	Plaster	unit 203
PASS	0.02	12/7/16	10:59 AM	#264	Kitchen	2nd	East	Window casing	Center	White	Wood	unit 203
PASS	0.48	12/7/16	11:00 AM	#265	Kitchen	2nd	South	Door casing	Center	White	Wood	unit 203
PASS	0	12/7/16	11:00 AM	#266	Kitchen	2nd	South	Baseboard	Center	White	Wood	unit 203
PASS	0	12/7/16	11:01 AM	#267	Kitchen	2nd	West	Cabinet	Center	Stain	Wood	unit 203
▼ Dining												
PASS	0.05	12/7/16	11:02 AM	#268	Dining	2nd	West	Cabinet	Left	Stain	Wood	unit 203
PASS	0.63	12/7/16	11:02 AM	#269	Dining	2nd	North	Door jamb	Center	Stain	Wood	unit 203
PASS	0.08	12/7/16	11:03 AM	#270	Dining	2nd	East	Window casing	Center	Stain	Wood	unit 203
PASS	0.2	12/7/16	11:04 AM	#271	Dining	2nd	East	Baseboard	Center	White	Wood	unit 203
PASS	0.55	12/7/16	11:04 AM	#272	Dining	2nd	South	Radiator	Center	White	Metal	unit 203
PASS	0	12/7/16	11:05 AM	#273	Dining	2nd	South	Ceiling	Center	White	Plaster	unit 203
PASS	0.01	12/7/16	11:06 AM	#274	Dining	2nd	North	Wall	Center	White	Plaster	unit 203
PASS	0.01	12/7/16	11:06 AM	#275	Dining	2nd	West	Wall	Center	White	Plaster	unit 203
FAIL	1.06	12/7/16	11:07 AM	#276	Dining	2nd	South	Wall	Upper	White	Plaster	unit 203
PASS	0.01	12/7/16	11:08 AM	#277	Dining	2nd	East	Wall	Lower	White	Plaster	unit 203
▼ Living room												
PASS	0.01	12/7/16	11:09 AM	#278	Living room	2nd	East	Ceiling	Center	White	Plaster	unit 203
PASS	0	12/7/16	11:10 AM	#279	Living room	2nd	North	Wall	Center	White	Plaster	unit 203
FAIL	1.73	12/7/16	11:10 AM	#280	Living room	2nd	East	Wall	Center	White	Plaster	unit 203

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.09	12/7/16	11:11 AM	#281	Living room	2nd	South	Wall	Upper	White	Plaster	unit 203
PASS	0	12/7/16	11:11 AM	#282	Living room	2nd	West	Wall	Lower	White	Plaster	unit 203
PASS	0.51	12/7/16	11:12 AM	#283	Living room	2nd	East	Window casing	Center	Stain	Wood	unit 203
PASS	0	12/7/16	11:13 AM	#284	Living room	2nd	West	Door casing	Center	White	Wood	unit 203
PASS	0.33	12/7/16	11:13 AM	#285	Living room	2nd	West	Baseboard	Center	White	Wood	unit 203
PASS	0	12/7/16	11:14 AM	#286	Living room	2nd	West	Floor	Center	Stain	Wood	unit 203
PASS	0.66	12/7/16	11:14 AM	#287	Living room	2nd	North	Radiator	Center	White	Metal	unit 203
▼ Bathroom												
PASS	0.54	12/7/16	11:16 AM	#288	Bathroom	2nd	East	Radiator	Center	White	Metal	unit 203
PASS	0.22	12/7/16	11:16 AM	#289	Bathroom	2nd	East	Ceiling	Center	White	Plaster	unit 203
PASS	0.46	12/7/16	11:17 AM	#290	Bathroom	2nd	North	Wall	Center	White	Plaster	unit 203
PASS	0.23	12/7/16	11:17 AM	#291	Bathroom	2nd	South	Wall	Center	White	Plaster	unit 203
PASS	0.42	12/7/16	11:18 AM	#292	Bathroom	2nd	West	Wall	Upper	White	Plaster	unit 203
PASS	0.25	12/7/16	11:19 AM	#293	Bathroom	2nd	East	Wall	Upper	White	Plaster	unit 203
PASS	0.28	12/7/16	11:19 AM	#294	Bathroom	2nd	East	Window casing	Center	White	Wood	unit 203
PASS	0.17	12/7/16	11:20 AM	#295	Bathroom	2nd	West	Door	Center	White	Wood	unit 203
PASS	0.28	12/7/16	11:20 AM	#296	Bathroom	2nd	North	Cabinet	Left	White	Wood	unit 203
PASS	0.28	12/7/16	11:21 AM	#297	Bathroom	2nd	North	Cabinet	Center	White	Wood	unit 203
▼ Bdrm 1												
PASS	0.55	12/7/16	11:22 AM	#298	Bdrm 1	2nd	North	Ceiling	Center	White	Plaster	unit 203
PASS	0.22	12/7/16	11:22 AM	#299	Bdrm 1	2nd	North	Wall	Center	White	Plaster	unit 203
PASS	0.78	12/7/16	11:23 AM	#300	Bdrm 1	2nd	South	Wall	Center	White	Plaster	unit 203
PASS	0.42	12/7/16	11:23 AM	#301	Bdrm 1	2nd	West	Wall	Upper	White	Plaster	unit 203
PASS	0.18	12/7/16	11:24 AM	#302	Bdrm 1	2nd	East	Wall	Lower	White	Plaster	unit 203
PASS	0.2	12/7/16	11:24 AM	#303	Bdrm 1	2nd	East	Window casing	Center	White	Wood	unit 203
PASS	0.34	12/7/16	11:25 AM	#304	Bdrm 1	2nd	South	Window sash	Center	White	Wood	unit 203
PASS	0.16	12/7/16	11:25 AM	#305	Bdrm 1	2nd	West	Door jamb	Center	White	Wood	unit 203
PASS	0.04	12/7/16	11:26 AM	#306	Bdrm 1	2nd	West	Door	Lower	Stain	Wood	unit 203
PASS	0.09	12/7/16	11:27 AM	#307	Bdrm 1	2nd	West	Closet	Center	White	Plaster	unit 203
▼ Bdrm 2												
PASS	0.08	12/7/16	11:28 AM	#308	Bdrm 2	2nd	East	Closet	Center	White	Plaster	unit 203
PASS	0.23	12/7/16	11:28 AM	#309	Bdrm 2	2nd	East	Ceiling	Center	White	Plaster	unit 203
PASS	0.21	12/7/16	11:29 AM	#310	Bdrm 2	2nd	North	Wall	Center	White	Plaster	unit 203
PASS	0.64	12/7/16	11:30 AM	#311	Bdrm 2	2nd	East	Wall	Center	White	Plaster	unit 203
PASS	0.15	12/7/16	11:30 AM	#312	Bdrm 2	2nd	South	Wall	Upper	White	Plaster	unit 203
PASS	0.71	12/7/16	11:31 AM	#313	Bdrm 2	2nd	West	Wall	Lower	White	Plaster	unit 203
PASS	0.21	12/7/16	11:32 AM	#314	Bdrm 2	2nd	West	Window casing	Center	White	Wood	unit 203

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.18	12/7/16	11:32 AM	#315	Bdrm 2	2nd	South	Window sash	Center	White	Wood	unit 203
PASS	0.46	12/7/16	11:33 AM	#316	Bdrm 2	2nd	East	Door casing	Right	White	Wood	unit 203
PASS	0.21	12/7/16	11:33 AM	#317	Bdrm 2	2nd	East	Door jamb	Left	White	Wood	unit 203
PASS	0.6	12/7/16	11:34 AM	#318	Bdrm 2	2nd	North	Baseboard	Center	White	Wood	unit 203
PASS	0	12/7/16	11:34 AM	#319	Bdrm 2	2nd	North	Floor	Center	Stain	Wood	unit 203
▼ unit 202												
▼ Bdrm 1												
PASS	0	12/7/16	11:37 AM	#320	Bdrm 1	2nd	North	Floor	Center	Stain	Wood	unit 202
PASS	0	12/7/16	11:37 AM	#321	Bdrm 1	2nd	North	Ceiling	Center	White	Plaster	unit 202
PASS	0	12/7/16	11:38 AM	#322	Bdrm 1	2nd	North	Wall	Center	White	Plaster	unit 202
PASS	0	12/7/16	11:39 AM	#323	Bdrm 1	2nd	West	Wall	Center	White	Plaster	unit 202
PASS	0	12/7/16	11:39 AM	#324	Bdrm 1	2nd	South	Wall	Lower	White	Plaster	unit 202
PASS	0	12/7/16	11:40 AM	#325	Bdrm 1	2nd	East	Wall	Upper	White	Plaster	unit 202
FAIL	1.74	12/7/16	11:40 AM	#326	Bdrm 1	2nd	East	Window casing	Center	White	Wood	unit 202
PASS	0.29	12/7/16	11:41 AM	#327	Bdrm 1	2nd	South	Door casing	Center	White	Wood	unit 202
PASS	0.09	12/7/16	11:41 AM	#328	Bdrm 1	2nd	West	Door	Center	White	Wood	unit 202
PASS	0.01	12/7/16	11:42 AM	#329	Bdrm 1	2nd	West	Baseboard	Center	White	Wood	unit 202
PASS	0.01	12/7/16	11:42 AM	#330	Bdrm 1	2nd	West	Floor	Center	Stain	Wood	unit 202
PASS	0.47	12/7/16	11:43 AM	#331	Bdrm 1	2nd	North	Radiator	Center	White	Metal	unit 202
▼ Kitchen												
PASS	0.68	12/7/16	11:44 AM	#332	Kitchen	2nd	North	Ceiling	Center	White	Plaster	unit 202
PASS	0	12/7/16	11:45 AM	#333	Kitchen	2nd	North	Wall	Center	White	Plaster	unit 202
FAIL	1.01	12/7/16	11:45 AM	#334	Kitchen	2nd	South	Wall	Center	White	Plaster	unit 202
PASS	0	12/7/16	11:46 AM	#335	Kitchen	2nd	West	Wall	Upper	White	Plaster	unit 202
PASS	0.01	12/7/16	11:46 AM	#336	Kitchen	2nd	East	Wall	Lower	White	Plaster	unit 202
PASS	0.12	12/7/16	11:47 AM	#337	Kitchen	2nd	North	Window casing	Center	White	Wood	unit 202
PASS	0.56	12/7/16	11:47 AM	#338	Kitchen	2nd	East	Door casing	Center	White	Wood	unit 202
PASS	0	12/7/16	11:48 AM	#339	Kitchen	2nd	East	Baseboard	Center	White	Wood	unit 202
▼ Dining												
PASS	0.28	12/7/16	11:49 AM	#340	Dining	2nd	West	Baseboard	Center	White	Wood	unit 202
PASS	0.02	12/7/16	11:50 AM	#341	Dining	2nd	West	Door jamb	Center	White	Wood	unit 202
PASS	0.03	12/7/16	11:50 AM	#342	Dining	2nd	North	Window casing	Center	White	Wood	unit 202
PASS	0.07	12/7/16	11:51 AM	#343	Dining	2nd	South	Cabinet	Right	Stain	Wood	unit 202
PASS	0	12/7/16	11:51 AM	#344	Dining	2nd	South	Floor	Center	Stain	Wood	unit 202
PASS	0	12/7/16	11:53 AM	#345	Dining	2nd	South	Ceiling	Center	White	Plaster	unit 202
PASS	0.26	12/7/16	11:53 AM	#346	Dining	2nd	North	Wall	Center	White	Plaster	unit 202
FAIL	1.08	12/7/16	11:54 AM	#347	Dining	2nd	South	Wall	Center	White	Plaster	unit 202



PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.18	12/7/16	11:54 AM	#348	Dining	2nd	South	Wall	Center	White	Plaster	unit 202
PASS	0.11	12/7/16	11:55 AM	#349	Dining	2nd	East	Wall	Upper	White	Plaster	unit 202
PASS	0.35	12/7/16	11:55 AM	#350	Dining	2nd	East	Wall	Lower	White	Plaster	unit 202
▼ Living room												
FAIL	1.28	12/7/16	11:56 AM	#351	Living room	2nd	East	Ceiling	Center	White	Plaster	unit 202
PASS	0.53	12/7/16	11:57 AM	#352	Living room	2nd	North	Wall	Center	White	Plaster	unit 202
PASS	0.68	12/7/16	11:57 AM	#353	Living room	2nd	South	Wall	Center	White	Plaster	unit 202
PASS	0.52	12/7/16	11:58 AM	#354	Living room	2nd	West	Wall	Upper	White	Plaster	unit 202
PASS	0.02	12/7/16	11:59 AM	#355	Living room	2nd	East	Wall	Lower	White	Plaster	unit 202
PASS	0.47	12/7/16	11:59 AM	#356	Living room	2nd	East	Window casing	Center	White	Wood	unit 202
PASS	0.03	12/7/16	12:00 PM	#357	Living room	2nd	West	Door casing	Center	White	Wood	unit 202
PASS	0.07	12/7/16	12:00 PM	#358	Living room	2nd	West	Baseboard	Center	White	Wood	unit 202
PASS	0	12/7/16	12:01 PM	#359	Living room	2nd	West	Floor	Center	Stain	Wood	unit 202
PASS	0.47	12/7/16	12:02 PM	#360	Living room	2nd	North	Radiator	Center	White	Metal	unit 202
▼ Bdrm 2												
PASS	0.06	12/7/16	12:02 PM	#361	Bdrm 2	2nd	North	Radiator	Center	White	Metal	unit 202
PASS	0	12/7/16	12:03 PM	#362	Bdrm 2	2nd	North	Ceiling	Center	White	Plaster	unit 202
PASS	0	12/7/16	12:03 PM	#363	Bdrm 2	2nd	North	Wall	Center	White	Plaster	unit 202
PASS	0	12/7/16	12:04 PM	#364	Bdrm 2	2nd	South	Wall	Center	White	Plaster	unit 202
PASS	0	12/7/16	12:04 PM	#365	Bdrm 2	2nd	West	Wall	Upper	White	Plaster	unit 202
PASS	0	12/7/16	12:05 PM	#366	Bdrm 2	2nd	East	Wall	Lower	White	Plaster	unit 202
PASS	0.02	12/7/16	12:05 PM	#367	Bdrm 2	2nd	East	Window casing	Center	White	Wood	unit 202
PASS	0	12/7/16	12:06 PM	#368	Bdrm 2	2nd	South	Window sash	Center	White	Wood	unit 202
PASS	0.03	12/7/16	12:06 PM	#369	Bdrm 2	2nd	North	Door	Center	White	Wood	unit 202
PASS	0.09	12/7/16	12:07 PM	#370	Bdrm 2	2nd	West	Door casing	Center	White	Wood	unit 202
▼ unit 204												
▼ Bathroom												
PASS	0.19	12/7/16	12:10 PM	#371	Bathroom	2nd	West	Ceiling	Center	White	Plaster	unit 204
PASS	0.17	12/7/16	12:11 PM	#372	Bathroom	2nd	North	Wall	Center	White	Plaster	unit 204
PASS	0.14	12/7/16	12:11 PM	#373	Bathroom	2nd	South	Wall	Center	White	Plaster	unit 204
PASS	0.25	12/7/16	12:12 PM	#374	Bathroom	2nd	East	Wall	Upper	White	Plaster	unit 204
PASS	0.2	12/7/16	12:12 PM	#375	Bathroom	2nd	West	Wall	Upper	White	Plaster	unit 204
PASS	0.48	12/7/16	12:13 PM	#376	Bathroom	2nd	West	Window casing	Center	White	Wood	unit 204
PASS	0.19	12/7/16	12:14 PM	#377	Bathroom	2nd	North	Door casing	Center	White	Wood	unit 204
PASS	0.15	12/7/16	12:14 PM	#378	Bathroom	2nd	South	Cabinet	Center	White	Wood	unit 204
FAIL	5	12/7/16	12:14 PM	#379	Bathroom	2nd	West	Bathtub	Center	White	Metal	unit 204
▼ Living room												

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.01	12/7/16	12:15 PM	#380	Living room	2nd	West	Ceiling	Center	White	Plaster	unit 204
PASS	0.03	12/7/16	12:16 PM	#381	Living room	2nd	East	Wall	Center	White	Plaster	unit 204
PASS	0.09	12/7/16	12:17 PM	#382	Living room	2nd	North	Wall	Center	White	Plaster	unit 204
PASS	0.41	12/7/16	12:17 PM	#383	Living room	2nd	West	Wall	Upper	White	Plaster	unit 204
PASS	0.01	12/7/16	12:18 PM	#384	Living room	2nd	South	Wall	Lower	White	Plaster	unit 204
PASS	0.06	12/7/16	12:18 PM	#385	Living room	2nd	South	Window casing	Center	Stain	Wood	unit 204
PASS	0.04	12/7/16	12:19 PM	#386	Living room	2nd	East	Door casing	Right	Stain	Wood	unit 204
PASS	0	12/7/16	12:20 PM	#387	Living room	2nd	North	Door	Center	Stain	Wood	unit 204
PASS	0.08	12/7/16	12:20 PM	#388	Living room	2nd	North	Baseboard	Center	Stain	Wood	unit 204
▼ Kitchen												
PASS	0.01	12/7/16	12:21 PM	#389	Kitchen	2nd	North	Ceiling	Center	White	Plaster	unit 204
PASS	0	12/7/16	12:22 PM	#390	Kitchen	2nd	North	Wall	Center	White	Plaster	unit 204
PASS	0.92	12/7/16	12:22 PM	#391	Kitchen	2nd	West	Wall	Right	White	Plaster	unit 204
PASS	0.45	12/7/16	12:23 PM	#392	Kitchen	2nd	West	Wall	Left	White	Plaster	unit 204
PASS	0.2	12/7/16	12:24 PM	#393	Kitchen	2nd	East	Wall	Center	White	Plaster	unit 204
PASS	0.7	12/7/16	12:24 PM	#394	Kitchen	2nd	South	Wall	Upper	White	Plaster	unit 204
PASS	0.06	12/7/16	12:25 PM	#395	Kitchen	2nd	South	Window casing	Upper	Stain	Wood	unit 204
PASS	0.4	12/7/16	12:25 PM	#396	Kitchen	2nd	East	Cabinet	Upper	White	Wood	unit 204
PASS	0.51	12/7/16	12:26 PM	#397	Kitchen	2nd	East	Cabinet	Lower	White	Wood	unit 204
PASS	0.08	12/7/16	12:27 PM	#398	Kitchen	2nd	East	Baseboard	Center	Stain	Wood	unit 204
▼ unit 205												
▼ Kitchen												
PASS	0.01	12/7/16	12:30 PM	#399	Kitchen	2nd	North	Ceiling	Center	White	Plaster	unit 205
PASS	0	12/7/16	12:30 PM	#400	Kitchen	2nd	North	Wall	Center	White	Plaster	unit 205
PASS	0.28	12/7/16	12:31 PM	#401	Kitchen	2nd	South	Wall	Center	White	Plaster	unit 205
PASS	0.32	12/7/16	12:31 PM	#402	Kitchen	2nd	East	Wall	Upper	White	Plaster	unit 205
PASS	0.38	12/7/16	12:32 PM	#403	Kitchen	2nd	East	Window casing	Upper	White	Wood	unit 205
PASS	0.45	12/7/16	12:32 PM	#404	Kitchen	2nd	West	Cabinet	Upper	White	Wood	unit 205
PASS	0.5	12/7/16	12:33 PM	#405	Kitchen	2nd	West	Cabinet	Lower	White	Wood	unit 205
PASS	0	12/7/16	12:33 PM	#406	Kitchen	2nd	North	Baseboard	Center	White	Wood	unit 205
▼ Living room												
PASS	0.01	12/7/16	12:34 PM	#407	Living room	2nd	North	Ceiling	Center	White	Plaster	unit 205
PASS	0.77	12/7/16	12:35 PM	#408	Living room	2nd	North	Wall	Center	White	Plaster	unit 205
PASS	0.54	12/7/16	12:35 PM	#409	Living room	2nd	East	Wall	Center	White	Plaster	unit 205
PASS	0	12/7/16	12:36 PM	#410	Living room	2nd	West	Wall	Upper	White	Plaster	unit 205
PASS	0.71	12/7/16	12:37 PM	#411	Living room	2nd	South	Wall	Lower	White	Plaster	unit 205
PASS	0.31	12/7/16	12:38 PM	#412	Living room	2nd	South	Window casing	Center	White	Wood	unit 205

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.3	12/7/16	12:38 PM	#413	Living room	2nd	North	Door	Center	White	Wood	unit 205
PASS	0.23	12/7/16	12:39 PM	#414	Living room	2nd	East	Door jamb	Center	White	Wood	unit 205
PASS	0.41	12/7/16	12:39 PM	#415	Living room	2nd	East	Baseboard	Center	White	Wood	unit 205
PASS	0	12/7/16	12:40 PM	#416	Living room	2nd	South	Railing cap	Center	White	Metal	unit 205
▼ Bathroom												
PASS	0.42	12/7/16	12:41 PM	#417	Bathroom	2nd	North	Ceiling	Center	White	Plaster	unit 205
PASS	0.48	12/7/16	12:42 PM	#418	Bathroom	2nd	North	Wall	Center	White	Plaster	unit 205
PASS	0	12/7/16	12:42 PM	#419	Bathroom	2nd	South	Wall	Center	White	Plaster	unit 205
PASS	0.39	12/7/16	12:43 PM	#420	Bathroom	2nd	West	Wall	Upper	White	Plaster	unit 205
PASS	0.38	12/7/16	12:43 PM	#421	Bathroom	2nd	East	Wall	Upper	White	Plaster	unit 205
PASS	0.24	12/7/16	12:44 PM	#422	Bathroom	2nd	South	Window casing	Center	White	Wood	unit 205
PASS	0.58	12/7/16	12:44 PM	#423	Bathroom	2nd	North	Door casing	Center	White	Wood	unit 205
PASS	0.32	12/7/16	12:45 PM	#424	Bathroom	2nd	East	Cabinet	Center	White	Wood	unit 205
FAIL	5	12/7/16	12:45 PM	#425	Bathroom	2nd	South	Bathtub	Center	White	Metal	unit 205
PASS	0.7	12/7/16	12:46 PM	#426	Bathroom	2nd	West	Radiator	Center	White	Metal	unit 205
▼ Bdrm 1												
PASS	0	12/7/16	12:47 PM	#427	Bdrm 1	2nd	West	Ceiling	Center	White	Plaster	unit 205
PASS	0.01	12/7/16	12:47 PM	#428	Bdrm 1	2nd	North	Wall	Center	White	Plaster	unit 205
PASS	0	12/7/16	12:48 PM	#429	Bdrm 1	2nd	South	Wall	Center	White	Plaster	unit 205
PASS	0	12/7/16	12:48 PM	#430	Bdrm 1	2nd	West	Wall	Upper	White	Plaster	unit 205
PASS	0	12/7/16	12:49 PM	#431	Bdrm 1	2nd	East	Wall	Lower	White	Plaster	unit 205
PASS	0.1	12/7/16	12:49 PM	#432	Bdrm 1	2nd	South	Window casing	Center	White	Wood	unit 205
PASS	0.12	12/7/16	12:50 PM	#433	Bdrm 1	2nd	North	Door casing	Center	White	Wood	unit 205
PASS	0.01	12/7/16	12:50 PM	#434	Bdrm 1	2nd	West	Door jamb	Center	White	Wood	unit 205
PASS	0.03	12/7/16	12:51 PM	#435	Bdrm 1	2nd	West	Baseboard	Center	White	Wood	unit 205
PASS	0.28	12/7/16	12:51 PM	#436	Bdrm 1	2nd	East	Radiator	Center	White	Metal	unit 205
PASS	0	12/7/16	12:52 PM	#437	Bdrm 1	2nd	East	Floor	Center	Stain	Wood	unit 205
PASS	0.08	12/7/16	12:52 PM	#438	Bdrm 1	2nd	North	Closet	Center	White	Plaster	unit 205
▼ unit 206												
▼ Kitchen												
PASS	0.31	12/7/16	1:01 PM	#439	Kitchen	2nd	North	Ceiling	Center	White	Plaster	unit 206
FAIL	1.87	12/7/16	1:01 PM	#440	Kitchen	2nd	North	Wall	Right	White	Plaster	unit 206
PASS	0.35	12/7/16	1:02 PM	#441	Kitchen	2nd	North	Wall	Left	White	Plaster	unit 206
PASS	0.42	12/7/16	1:03 PM	#442	Kitchen	2nd	South	Wall	Center	White	Plaster	unit 206
PASS	0	12/7/16	1:04 PM	#443	Kitchen	2nd	East	Wall	Upper	White	Plaster	unit 206
PASS	0.01	12/7/16	1:04 PM	#444	Kitchen	2nd	West	Wall	Lower	White	Plaster	unit 206
PASS	0.02	12/7/16	1:05 PM	#445	Kitchen	2nd	West	Window casing	Center	White	Wood	unit 206

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.09	12/7/16	1:06 PM	#446	Kitchen	2nd	West	Cabinet	Right	White	Wood	unit 206
PASS	0.26	12/7/16	1:06 PM	#447	Kitchen	2nd	South	Cabinet	Upper	White	Wood	unit 206
PASS	0.22	12/7/16	1:07 PM	#448	Kitchen	2nd	South	Cabinet	Lower	White	Wood	unit 206
PASS	0	12/7/16	1:07 PM	#449	Kitchen	2nd	East	Baseboard	Center	White	Wood	unit 206
PASS	0.11	12/7/16	1:08 PM	#450	Kitchen	2nd	West	Radiator	Center	White	Metal	unit 206
▼ Living room												
PASS	0.11	12/7/16	1:09 PM	#451	Living room	2nd	West	Radiator	Center	White	Metal	unit 206
PASS	0.14	12/7/16	1:10 PM	#452	Living room	2nd	West	Ceiling	Center	White	Plaster	unit 206
PASS	0.99	12/7/16	1:11 PM	#453	Living room	2nd	North	Wall	Center	White	Plaster	unit 206
PASS	0.13	12/7/16	1:11 PM	#454	Living room	2nd	East	Wall	Center	White	Plaster	unit 206
PASS	0.01	12/7/16	1:12 PM	#455	Living room	2nd	South	Wall	Upper	White	Plaster	unit 206
PASS	0.88	12/7/16	1:12 PM	#456	Living room	2nd	West	Wall	Lower	White	Plaster	unit 206
PASS	0.03	12/7/16	1:13 PM	#457	Living room	2nd	West	Window casing	Center	White	Wood	unit 206
PASS	0.02	12/7/16	1:14 PM	#458	Living room	2nd	East	Door casing	Right	White	Wood	unit 206
PASS	0.01	12/7/16	1:14 PM	#459	Living room	2nd	East	Baseboard	Center	White	Wood	unit 206
▼ Bathroom												
PASS	0.38	12/7/16	1:15 PM	#460	Bathroom	2nd	East	Ceiling	Center	White	Plaster	unit 206
PASS	0.51	12/7/16	1:16 PM	#461	Bathroom	2nd	North	Wall	Center	White	Plaster	unit 206
PASS	0.3	12/7/16	1:16 PM	#462	Bathroom	2nd	South	Wall	Center	White	Plaster	unit 206
PASS	0.56	12/7/16	1:17 PM	#463	Bathroom	2nd	West	Wall	Upper	White	Plaster	unit 206
FAIL	2.26	12/7/16	1:17 PM	#464	Bathroom	2nd	East	Wall	Upper	White	Plaster	unit 206
PASS	0.66	12/7/16	1:18 PM	#465	Bathroom	2nd	East	Wall	Upper	White	Plaster	unit 206
PASS	0.46	12/7/16	1:18 PM	#466	Bathroom	2nd	East	Window casing	Center	White	Wood	unit 206
PASS	0.43	12/7/16	1:19 PM	#467	Bathroom	2nd	South	Cabinet	Center	White	Wood	unit 206
PASS	0.49	12/7/16	1:20 PM	#468	Bathroom	2nd	South	Cabinet	Right	White	Wood	unit 206
▼ Bdrm 1												
PASS	0	12/7/16	1:21 PM	#469	Bdrm 1	2nd	South	Ceiling	Center	White	Plaster	unit 206
PASS	0	12/7/16	1:22 PM	#470	Bdrm 1	2nd	North	Wall	Center	White	Plaster	unit 206
PASS	0	12/7/16	1:22 PM	#471	Bdrm 1	2nd	South	Wall	Center	White	Plaster	unit 206
PASS	0	12/7/16	1:23 PM	#472	Bdrm 1	2nd	West	Wall	Upper	White	Plaster	unit 206
PASS	0	12/7/16	1:23 PM	#473	Bdrm 1	2nd	East	Wall	Lower	White	Plaster	unit 206
PASS	0.53	12/7/16	1:25 PM	#474	Bdrm 1	2nd	East	Window casing	Center	White	Wood	unit 206
PASS	0.4	12/7/16	1:25 PM	#475	Bdrm 1	2nd	South	Window sash	Center	White	Wood	unit 206
PASS	0.21	12/7/16	1:26 PM	#476	Bdrm 1	2nd	West	Door casing	Right	White	Wood	unit 206
PASS	0.22	12/7/16	1:27 PM	#477	Bdrm 1	2nd	West	Door jamb	Left	White	Wood	unit 206
PASS	0.31	12/7/16	1:27 PM	#478	Bdrm 1	2nd	West	Closet	Center	White	Plaster	unit 206
▼ Bdrm 2												



PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0	12/7/16	1:28 PM	#479	Bdrm 2	2nd	West	Floor	Center	White	Plaster	unit 206
PASS	0	12/7/16	1:29 PM	#480	Bdrm 2	2nd	North	Wall	Center	White	Plaster	unit 206
PASS	0	12/7/16	1:29 PM	#481	Bdrm 2	2nd	East	Wall	Center	White	Plaster	unit 206
PASS	0	12/7/16	1:30 PM	#482	Bdrm 2	2nd	West	Wall	Upper	White	Plaster	unit 206
PASS	0	12/7/16	1:30 PM	#483	Bdrm 2	2nd	South	Wall	Lower	White	Plaster	unit 206
PASS	0.1	12/7/16	1:31 PM	#484	Bdrm 2	2nd	South	Window stool	Right	White	Wood	unit 206
PASS	0.62	12/7/16	1:31 PM	#485	Bdrm 2	2nd	West	Window casing	Center	White	Wood	unit 206
PASS	0.22	12/7/16	1:32 PM	#486	Bdrm 2	2nd	East	Door	Left	White	Wood	unit 206
PASS	0.79	12/7/16	1:33 PM	#487	Bdrm 2	2nd	East	Door casing	Right	White	Wood	unit 206
PASS	0.21	12/7/16	1:33 PM	#488	Bdrm 2	2nd	East	Closet	Center	White	Plaster	unit 206
PASS	0.83	12/7/16	1:34 PM	#489	Bdrm 2	2nd	North	Baseboard	Center	White	Plaster	unit 206
▼ unit 201												
▼ Kitchen												
FAIL	1.52	12/7/16	1:37 PM	#490	Kitchen	2nd	North	Ceiling	Center	White	Plaster	unit 201
FAIL	3.09	12/7/16	1:38 PM	#491	Kitchen	2nd	North	Wall	Center	White	Plaster	unit 201
PASS	0	12/7/16	1:38 PM	#492	Kitchen	2nd	South	Wall	Center	White	Plaster	unit 201
PASS	0	12/7/16	1:38 PM	#493	Kitchen	2nd	East	Wall	Upper	White	Plaster	unit 201
PASS	0	12/7/16	1:39 PM	#494	Kitchen	2nd	West	Wall	Lower	White	Plaster	unit 201
PASS	0.44	12/7/16	1:39 PM	#495	Kitchen	2nd	South	Window casing	Center	White	Wood	unit 201
PASS	0.14	12/7/16	1:40 PM	#496	Kitchen	2nd	West	Door casing	Center	White	Wood	unit 201
PASS	0	12/7/16	1:40 PM	#497	Kitchen	2nd	East	Baseboard	Center	White	Wood	unit 201
PASS	0	12/7/16	1:45 PM	#505	Kitchen	2nd	East	Cabinet	Center	White	Wood	unit 201
▼ Dining												
PASS	0	12/7/16	1:41 PM	#498	Dining	2nd	East	Ceiling	Center	White	Plaster	unit 201
PASS	0.43	12/7/16	1:41 PM	#499	Dining	2nd	North	Wall	Center	White	Plaster	unit 201
PASS	0.02	12/7/16	1:42 PM	#500	Dining	2nd	South	Wall	Center	White	Plaster	unit 201
PASS	0.72	12/7/16	1:42 PM	#501	Dining	2nd	East	Wall	Upper	White	Plaster	unit 201
PASS	0.15	12/7/16	1:43 PM	#502	Dining	2nd	West	Wall	Lower	White	Plaster	unit 201
PASS	0.09	12/7/16	1:44 PM	#503	Dining	2nd	North	Window casing	Center	Stain	Wood	unit 201
PASS	0.07	12/7/16	1:44 PM	#504	Dining	2nd	East	Door casing	Center	Stain	Wood	unit 201
PASS	0	12/7/16	1:46 PM	#506	Dining	2nd	East	Floor	Center	Stain	Wood	unit 201
▼ Living room												
PASS	0	12/7/16	1:46 PM	#507	Living room	2nd	East	Floor	Center	Stain	Wood	unit 201
PASS	0	12/7/16	1:47 PM	#508	Living room	2nd	East	Ceiling	Center	White	Plaster	unit 201
PASS	0.03	12/7/16	1:47 PM	#509	Living room	2nd	West	Wall	Center	White	Plaster	unit 201
PASS	0.01	12/7/16	1:48 PM	#510	Living room	2nd	South	Wall	Center	White	Plaster	unit 201
PASS	0.16	12/7/16	1:48 PM	#511	Living room	2nd	East	Wall	Upper	White	Plaster	unit 201

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.39	12/7/16	1:49 PM	#512	Living room	2nd	North	Wall	Lower	White	Plaster	unit 201
PASS	0.08	12/7/16	1:50 PM	#513	Living room	2nd	North	Window casing	Center	Stain	Wood	unit 201
PASS	0	12/7/16	1:50 PM	#514	Living room	2nd	South	Door	Center	Stain	Wood	unit 201
PASS	0.06	12/7/16	1:51 PM	#515	Living room	2nd	West	Door jamb	Center	Stain	Wood	unit 201
▼ Bathroom												
PASS	0	12/7/16	1:52 PM	#516	Bathroom	2nd	West	Ceiling	Center	White	Plaster	unit 201
PASS	0.39	12/7/16	1:53 PM	#517	Bathroom	2nd	West	Wall	Center	White	Plaster	unit 201
PASS	0.47	12/7/16	1:53 PM	#518	Bathroom	2nd	South	Wall	Center	White	Plaster	unit 201
FAIL	4.45	12/7/16	1:54 PM	#519	Bathroom	2nd	East	Wall	Lower	White	Plaster	unit 201
PASS	0.09	12/7/16	1:54 PM	#520	Bathroom	2nd	East	Wall	Upper	White	Plaster	unit 201
PASS	0.08	12/7/16	1:55 PM	#521	Bathroom	2nd	North	Wall	Upper	White	Plaster	unit 201
PASS	0.13	12/7/16	1:55 PM	#522	Bathroom	2nd	North	Window casing	Center	White	Wood	unit 201
PASS	0.31	12/7/16	1:56 PM	#523	Bathroom	2nd	South	Door casing	Center	White	Wood	unit 201
PASS	0.23	12/7/16	1:56 PM	#524	Bathroom	2nd	West	Cabinet	Center	White	Wood	unit 201
PASS	0.28	12/7/16	1:57 PM	#525	Bathroom	2nd	East	Radiator	Center	White	Metal	unit 201
FAIL	5	12/7/16	1:57 PM	#526	Bathroom	2nd	North	Bathtub	Center	White	Metal	unit 201
▼ Bdrm 1												
PASS	0	12/7/16	1:59 PM	#527	Bdrm 1	2nd	North	Ceiling	Center	White	Plaster	unit 201
PASS	0	12/7/16	1:59 PM	#528	Bdrm 1	2nd	North	Wall	Center	White	Plaster	unit 201
PASS	0	12/7/16	2:00 PM	#529	Bdrm 1	2nd	East	Wall	Center	White	Plaster	unit 201
PASS	0	12/7/16	2:01 PM	#530	Bdrm 1	2nd	South	Wall	Upper	White	Plaster	unit 201
PASS	0	12/7/16	2:01 PM	#531	Bdrm 1	2nd	West	Wall	Lower	White	Plaster	unit 201
PASS	0.19	12/7/16	2:02 PM	#532	Bdrm 1	2nd	West	Window casing	Center	White	Wood	unit 201
PASS	0.21	12/7/16	2:02 PM	#533	Bdrm 1	2nd	North	Window stool	Center	White	Wood	unit 201
PASS	0.17	12/7/16	2:03 PM	#534	Bdrm 1	2nd	East	Door casing	Center	White	Wood	unit 201
PASS	0.58	12/7/16	2:04 PM	#535	Bdrm 1	2nd	East	Baseboard	Center	White	Wood	unit 201
PASS	0.08	12/7/16	2:04 PM	#536	Bdrm 1	2nd	East	Radiator	Center	White	Metal	unit 201
▼ unit C												
▼ Kitchen												
PASS	0	12/7/16	2:07 PM	#537	Kitchen	2nd	North	Wall	Center	White	Plastic	unit C
PASS	0	12/7/16	2:08 PM	#538	Kitchen	2nd	South	Wall	Center	White	Plastic	unit C
PASS	0.77	12/7/16	2:09 PM	#539	Kitchen	LL	East	Wall	Center	White	Concrete	unit C
FAIL	1.99	12/7/16	2:09 PM	#540	Kitchen	LL	West	Wall	Center	Stain	Wood	unit C
PASS	0.26	12/7/16	2:10 PM	#541	Kitchen	LL	East	Window casing	Center	White	Wood	unit C
▼ Bdrm 1												
PASS	0.58	12/7/16	2:11 PM	#542	Bdrm 1	LL	North	Window casing	Center	White	Plaster	unit C
PASS	0.01	12/7/16	2:12 PM	#543	Bdrm 1	LL	South	Window casing	Center	White	Plaster	unit C

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
FAIL	3.61	12/7/16	2:12 PM	#544	Bdrm 1	LL	West	Wall	Upper	White	Plaster	unit C
FAIL	2.45	12/7/16	2:12 PM	#545	Bdrm 1	LL	East	Wall	Lower	White	Plaster	unit C
FAIL	5	12/7/16	2:13 PM	#546	Bdrm 1	LL	East	Window casing	Center	White	Wood	unit C
PASS	0.01	12/7/16	2:13 PM	#547	Bdrm 1	LL	South	Door casing	Center	White	Wood	unit C
PASS	0	12/7/16	2:14 PM	#548	Bdrm 1	LL	South	Closet	Center	White	Plaster	unit C
PASS	0.13	12/7/16	2:14 PM	#549	Bdrm 1	LL	North	Door casing	Center	White	Wood	unit C
▼ Living room												
PASS	0	12/7/16	2:16 PM	#550	Living room	LL	South	Wall	Center	White	Plaster	unit C
PASS	0.16	12/7/16	2:16 PM	#551	Living room	LL	West	Wall	Center	White	Plaster	unit C
FAIL	2.04	12/7/16	2:16 PM	#552	Living room	LL	East	Wall	Center	White	Plaster	unit C
FAIL	2.22	12/7/16	2:17 PM	#553	Living room	LL	North	Wall	Center	White	Plaster	unit C
PASS	0.26	12/7/16	2:17 PM	#554	Living room	LL	North	Window casing	Center	White	Wood	unit C
PASS	0.28	12/7/16	2:18 PM	#555	Living room	LL	East	Window casing	Left	White	Wood	unit C
PASS	0	12/7/16	2:18 PM	#556	Living room	LL	West	Door casing	Center	White	Wood	unit C
▼ unit B												
▼ Living room												
PASS	0	12/7/16	2:21 PM	#557	Living room	LL	North	Wall	Center	White	Plaster	unit B
PASS	0.88	12/7/16	2:22 PM	#558	Living room	LL	South	Wall	Center	White	Plaster	unit B
PASS	0.64	12/7/16	2:23 PM	#559	Living room	LL	West	Wall	Upper	White	Plaster	unit B
PASS	0.38	12/7/16	2:23 PM	#560	Living room	LL	East	Wall	Lower	White	Plaster	unit B
PASS	0.89	12/7/16	2:24 PM	#561	Living room	LL	North	Window casing	Center	White	Wood	unit B
PASS	0	12/7/16	2:24 PM	#562	Living room	LL	South	Door casing	Center	White	Wood	unit B
FAIL	1.12	12/7/16	2:25 PM	#563	Living room	LL	East	Door casing	Right	White	Wood	unit B
FAIL	1.21	12/7/16	2:26 PM	#564	Living room	LL	East	Door jamb	Left	White	Wood	unit B
PASS	0.17	12/7/16	2:26 PM	#565	Living room	LL	East	Closet	Right	White	Plaster	unit B
▼ Dining												
PASS	0.3	12/7/16	2:28 PM	#566	Dining	LL	North	Wall	Center	White	Plaster	unit B
PASS	0.72	12/7/16	2:28 PM	#567	Dining	LL	West	Wall	Center	White	Plaster	unit B
PASS	0.64	12/7/16	2:29 PM	#568	Dining	LL	East	Wall	Upper	White	Plaster	unit B
PASS	0.02	12/7/16	2:29 PM	#569	Dining	LL	South	Wall	Lower	White	Plaster	unit B
FAIL	3.01	12/7/16	2:30 PM	#570	Dining	LL	North	Window casing	Center	White	Wood	unit B
FAIL	1.16	12/7/16	2:30 PM	#571	Dining	LL	East	Baseboard	Center	White	Wood	unit B
▼ Bathroom												
FAIL	5	12/7/16	2:31 PM	#572	Bathroom	LL	North	Wall	Center	White	Plaster	unit B
FAIL	5	12/7/16	2:31 PM	#573	Bathroom	LL	East	Wall	Center	White	Plaster	unit B
FAIL	5	12/7/16	2:32 PM	#574	Bathroom	LL	West	Wall	Center	White	Plaster	unit B
FAIL	3.89	12/7/16	2:32 PM	#575	Bathroom	LL	South	Wall	Center	White	Plaster	unit B

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
FAIL	4.6	12/7/16	2:32 PM	#576	Bathroom	LL	North	Window casing	Center	White	Wood	unit B
FAIL	4.05	12/7/16	2:32 PM	#577	Bathroom	LL	South	Door casing	Center	White	Wood	unit B
PASS	0.01	12/7/16	2:33 PM	#578	Bathroom	LL	East	Bathtub	Center	White	Metal	unit B
▼ Kitchen												
FAIL	1.83	12/7/16	2:33 PM	#579	Kitchen	LL	North	Wall	Center	White	Plaster	unit B
PASS	0.62	12/7/16	2:34 PM	#580	Kitchen	LL	South	Wall	Center	White	Plaster	unit B
PASS	0	12/7/16	2:34 PM	#581	Kitchen	LL	East	Wall	Center	White	Plaster	unit B
FAIL	1.04	12/7/16	2:35 PM	#582	Kitchen	LL	West	Wall	Center	White	Plaster	unit B
FAIL	3.07	12/7/16	2:35 PM	#583	Kitchen	LL	West	Cabinet	Upper	White	Wood	unit B
FAIL	2.05	12/7/16	2:36 PM	#584	Kitchen	LL	West	Cabinet	Lower	White	Wood	unit B
▼ unit A												
▼ Kitchen												
PASS	0	12/7/16	2:39 PM	#585	Kitchen	LL	West	Ceiling	Center	White	Plaster	unit A
FAIL	1.22	12/7/16	2:40 PM	#586	Kitchen	LL	North	Wall	Left	White	Plaster	unit A
PASS	0	12/7/16	2:40 PM	#587	Kitchen	LL	East	Wall	Center	White	Plaster	unit A
PASS	0.63	12/7/16	2:41 PM	#588	Kitchen	LL	South	Wall	Upper	White	Plaster	unit A
PASS	0	12/7/16	2:42 PM	#589	Kitchen	LL	West	Wall	Upper	White	Plaster	unit A
PASS	0	12/7/16	2:42 PM	#590	Kitchen	LL	West	Window casing	Center	White	Wood	unit A
▼ Living room												
PASS	0	12/7/16	2:43 PM	#591	Living room	LL	West	Ceiling	Center	White	Plaster	unit A
PASS	0	12/7/16	2:43 PM	#592	Living room	LL	North	Wall	Center	White	Plaster	unit A
PASS	0.01	12/7/16	2:44 PM	#593	Living room	LL	East	Wall	Center	White	Plaster	unit A
PASS	0	12/7/16	2:44 PM	#594	Living room	LL	South	Wall	Upper	White	Plaster	unit A
PASS	0	12/7/16	2:45 PM	#595	Living room	LL	West	Wall	Lower	White	Plaster	unit A
PASS	0.03	12/7/16	2:45 PM	#596	Living room	LL	West	Window casing	Center	White	Wood	unit A
PASS	0.03	12/7/16	2:46 PM	#597	Living room	LL	East	Door casing	Left	White	Wood	unit A
PASS	0.02	12/7/16	2:47 PM	#598	Living room	LL	East	Baseboard	Center	White	Wood	unit A
▼ Bdrm 1												
PASS	0	12/7/16	2:48 PM	#599	Bdrm 1	LL	East	Ceiling	Center	White	Plaster	unit A
PASS	0	12/7/16	2:49 PM	#600	Bdrm 1	LL	North	Wall	Center	White	Plaster	unit A
PASS	0	12/7/16	2:49 PM	#601	Bdrm 1	LL	South	Wall	Center	White	Plaster	unit A
PASS	0	12/7/16	2:50 PM	#602	Bdrm 1	LL	West	Wall	Upper	White	Plaster	unit A
PASS	0	12/7/16	2:51 PM	#603	Bdrm 1	LL	East	Wall	Lower	White	Plaster	unit A
PASS	0	12/7/16	2:51 PM	#604	Bdrm 1	LL	East	Window casing	Center	White	Wood	unit A
PASS	0	12/7/16	2:52 PM	#605	Bdrm 1	LL	West	Door casing	Right	White	Wood	unit A
PASS	0	12/7/16	2:52 PM	#606	Bdrm 1	LL	West	Door	Left	White	Wood	unit A
PASS	0	12/7/16	2:53 PM	#607	Bdrm 1	LL	West	Baseboard	Center	White	Wood	unit A



PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0	12/7/16	2:53 PM	#608	Bdrm 1	LL	South	Radiator	Center	White	Metal	unit A
▼ Bdrm 2												
PASS	0	12/7/16	2:54 PM	#609	Bdrm 2	LL	South	Ceiling	Center	White	Plaster	unit A
PASS	0	12/7/16	2:55 PM	#610	Bdrm 2	LL	South	Wall	Center	White	Plaster	unit A
PASS	0	12/7/16	2:55 PM	#611	Bdrm 2	LL	East	Wall	Center	White	Plaster	unit A
PASS	0	12/7/16	2:56 PM	#612	Bdrm 2	LL	North	Wall	Upper	White	Plaster	unit A
PASS	0	12/7/16	2:56 PM	#613	Bdrm 2	LL	West	Wall	Lower	White	Plaster	unit A
PASS	0	12/7/16	2:57 PM	#614	Bdrm 2	LL	West	Window casing	Center	White	Wood	unit A
PASS	0	12/7/16	2:57 PM	#615	Bdrm 2	LL	East	Baseboard	Center	White	Wood	unit A
PASS	0	12/7/16	2:58 PM	#616	Bdrm 2	LL	East	Door casing	Right	White	Wood	unit A
PASS	0	12/7/16	2:58 PM	#617	Bdrm 2	LL	East	Door jamb	Left	White	Wood	unit A
FAIL	1.04	12/7/16	2:59 PM	#618	Bdrm 2	LL	South	Radiator	Center	White	Metal	unit A
▼ Bathroom												
PASS	0	12/7/16	3:00 PM	#619	Bathroom	LL	South	Ceiling	Center	White	Plaster	unit A
PASS	0	12/7/16	3:00 PM	#620	Bathroom	LL	North	Wall	Center	White	Plaster	unit A
PASS	0	12/7/16	3:00 PM	#621	Bathroom	LL	South	Wall	Center	White	Plaster	unit A
PASS	0	12/7/16	3:01 PM	#622	Bathroom	LL	West	Wall	Center	White	Plaster	unit A
PASS	0	12/7/16	3:01 PM	#623	Bathroom	LL	East	Wall	Center	White	Plaster	unit A
PASS	0	12/7/16	3:01 PM	#624	Bathroom	LL	East	Window casing	Center	White	Wood	unit A
PASS	0.15	12/7/16	3:02 PM	#625	Bathroom	LL	West	Door	Center	White	Wood	unit A
▼ Bdrm 3												
PASS	0	12/7/16	3:03 PM	#626	Bdrm 3	LL	West	Ceiling	Center	White	Plaster	unit A
PASS	0	12/7/16	3:03 PM	#627	Bdrm 3	LL	South	Wall	Center	White	Plaster	unit A
PASS	0	12/7/16	3:03 PM	#628	Bdrm 3	LL	West	Wall	Center	White	Plaster	unit A
PASS	0	12/7/16	3:04 PM	#629	Bdrm 3	LL	North	Wall	Upper	White	Plaster	unit A
PASS	0	12/7/16	3:04 PM	#630	Bdrm 3	LL	East	Wall	Lower	White	Plaster	unit A
PASS	0	12/7/16	3:05 PM	#631	Bdrm 3	LL	East	Window casing	Center	White	Wood	unit A
PASS	0	12/7/16	3:05 PM	#632	Bdrm 3	LL	North	Door casing	Center	White	Wood	unit A
PASS	0.01	12/7/16	3:06 PM	#633	Bdrm 3	LL	East	Railing cap	Center	White	Metal	unit A
FAIL	1.07	12/7/16	3:12 PM	#634-1	Bdrm 3	LL	East	Railing cap	Center	White	Metal	unit A
FAIL	1.09	12/7/16	3:12 PM	#634-2	Bdrm 3	LL	East	Railing cap	Center	White	Metal	unit A
FAIL	1.09	12/7/16	3:13 PM	#634-3	Bdrm 3	LL	East	Railing cap	Center	White	Metal	unit A
FAIL	1.06	12/7/16	3:39 PM	#635-1	Bdrm 3	LL	East	Railing cap	Center	White	Metal	unit A
FAIL	1.07	12/7/16	3:39 PM	#635-2	Bdrm 3	LL	East	Railing cap	Center	White	Metal	unit A
FAIL	1.08	12/7/16	3:40 PM	#635-3	Bdrm 3	LL	East	Railing cap	Center	White	Metal	unit A
▼ (blank)												
▼ (blank)												

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
FAIL	1.08	12/7/16	3:13 PM	34-Avg(3)								
FAIL	1.07	12/7/16	3:40 PM	35-Avg(3)								
▼ Laundry												
FAIL	1.89	12/7/16	3:55 PM	#645	Laundry	LL	North	Radiator	Center	White	Metal	
PASS	0.02	12/7/16	3:56 PM	#646	Laundry	LL	North	Ceiling	Center	White	Plaster	
PASS	0.01	12/7/16	3:56 PM	#647	Laundry	LL	North	Wall	Center	White	Concrete	
PASS	0.02	12/7/16	3:57 PM	#648	Laundry	LL	South	Wall	Center	White	Concrete	
PASS	0.01	12/7/16	3:57 PM	#649	Laundry	LL	West	Wall	Upper	White	Concrete	
PASS	0	12/7/16	3:58 PM	#650	Laundry	LL	East	Wall	Lower	White	Plaster	
PASS	0.4	12/7/16	3:59 PM	#651	Laundry	LL	North	Window casing	Center	Gray	Wood	
PASS	0.05	12/7/16	3:59 PM	#652	Laundry	LL	North	Window casing	Left	Gray	Wood	
PASS	0.21	12/7/16	4:00 PM	#653	Laundry	LL	West	Window sash	Center	Gray	Wood	
PASS	0.02	12/7/16	4:00 PM	#654	Laundry	LL	West	Floor	Center	Gray	Concrete	
PASS	0.17	12/7/16	4:01 PM	#655	Laundry	LL	South	Door casing	Center	Gray	Wood	
▼ Outside												
FAIL	3.34	12/7/16	4:35 PM	#704	Outside	1st	North	Door casing	Center	Red	Wood	
FAIL	5	12/7/16	4:36 PM	#705	Outside	1st	North	Window casing	Center	Tan	Wood	
FAIL	5	12/7/16	4:37 PM	#706	Outside	2nd	South	Window casing	Left	Tan	Wood	
FAIL	5	12/7/16	4:39 PM	#707	Outside	2nd	West	Window casing	Left	Tan	Wood	
FAIL	5	12/7/16	4:41 PM	#708	Outside	2nd	East	Window casing	Right	Tan	Wood	
▼ next to boiler rm												
▼ Storage												
PASS	0.1	12/7/16	3:47 PM	#636	Storage	LL	North	Ceiling	Center	White	Plaster	next to boiler rm
PASS	0	12/7/16	3:48 PM	#637	Storage	LL	North	Wall	Center	Tan	Plaster	next to boiler rm
PASS	0.07	12/7/16	3:48 PM	#638	Storage	LL	South	Wall	Center	White	Plaster	next to boiler rm
PASS	0.1	12/7/16	3:49 PM	#639	Storage	LL	East	Wall	Center	White	Plaster	next to boiler rm
PASS	0.05	12/7/16	3:50 PM	#640	Storage	LL	West	Wall	Center	White	Plaster	next to boiler rm
PASS	0.16	12/7/16	3:50 PM	#641	Storage	LL	South	Window casing	Center	White	Wood	next to boiler rm
PASS	0.23	12/7/16	3:51 PM	#642	Storage	LL	East	Window casing	Right	White	Wood	next to boiler rm
PASS	0.2	12/7/16	3:51 PM	#643	Storage	LL	East	Window sash	Left	White	Wood	next to boiler rm
PASS	0.15	12/7/16	3:52 PM	#644	Storage	LL	East	Radiator	Center	White	Metal	next to boiler rm
▼ common												
▼ Hall												
PASS	0.01	12/7/16	4:02 PM	#656	Hall	LL	North	Wall	Left	White	Plaster	common
PASS	0.01	12/7/16	4:03 PM	#657	Hall	LL	North	Wall	Right	White	Plaster	common
PASS	0.02	12/7/16	4:03 PM	#658	Hall	LL	East	Wall	Right	White	Plaster	common
PASS	0.3	12/7/16	4:04 PM	#659	Hall	LL	South	Door	Left	Red	Plaster	common

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.01	12/7/16	4:04 PM	#660	Hall	LL	South	Wall	Center	Red	Plaster	common
PASS	0.02	12/7/16	4:05 PM	#661	Hall	LL	West	Wall	Center	White	Plaster	common
PASS	0.09	12/7/16	4:05 PM	#662	Hall	LL	West	Door	Right	Red	Wood	common
PASS	0.03	12/7/16	4:06 PM	#663	Hall	LL	South	Door casing	Center	Tan	Wood	common
PASS	0.03	12/7/16	4:07 PM	#664	Hall	LL	North	Door casing	Center	Tan	Wood	common
PASS	0.01	12/7/16	4:07 PM	#665	Hall	LL	North	Ceiling	Left	White	Plaster	common
PASS	0.01	12/7/16	4:08 PM	#666	Hall	LL	East	Ceiling	Right	White	Plaster	common
▼ Hall 2												
PASS	0.01	12/7/16	4:15 PM	#678	Hall 2	3rd	East	Ceiling	Right	White	Plaster	common
PASS	0.01	12/7/16	4:16 PM	#679	Hall 2	3rd	North	Ceiling	Center	White	Plaster	common
PASS	0.01	12/7/16	4:17 PM	#680	Hall 2	3rd	West	Ceiling	Center	White	Plaster	common
PASS	0.1	12/7/16	4:17 PM	#681	Hall 2	3rd	West	Window apron	Center	White	Plaster	common
PASS	0.11	12/7/16	4:18 PM	#682	Hall 2	3rd	North	Wall	Center	White	Plaster	common
PASS	0.13	12/7/16	4:19 PM	#683	Hall 2	3rd	South	Wall	Center	White	Plaster	common
PASS	0.03	12/7/16	4:19 PM	#684	Hall 2	3rd	East	Wall	Center	White	Plaster	common
PASS	0.07	12/7/16	4:20 PM	#685	Hall 2	3rd	East	Door casing	Center	Stain	Wood	common
PASS	0.06	12/7/16	4:20 PM	#686	Hall 2	3rd	North	Door casing	Center	Stain	Wood	common
PASS	0.06	12/7/16	4:21 PM	#687	Hall 2	3rd	South	Door casing	Center	Stain	Wood	common
PASS	0.04	12/7/16	4:21 PM	#688	Hall 2	3rd	West	Door casing	Center	Stain	Wood	common
PASS	0.07	12/7/16	4:22 PM	#689	Hall 2	3rd	West	Baseboard	Center	Stain	Wood	common
▼ Hall 3												
PASS	0.01	12/7/16	4:30 PM	#695	Hall 3	3rd	West	Ceiling	Center	White	Plaster	common
PASS	0.01	12/7/16	4:30 PM	#696	Hall 3	3rd	East	Ceiling	Center	White	Plaster	common
PASS	0.1	12/7/16	4:31 PM	#697	Hall 3	3rd	North	Wall	Center	White	Plaster	common
PASS	0.06	12/7/16	4:31 PM	#698	Hall 3	3rd	South	Wall	Center	White	Plaster	common
PASS	0.03	12/7/16	4:32 PM	#699	Hall 3	3rd	East	Wall	Center	White	Plaster	common
PASS	0.04	12/7/16	4:32 PM	#700	Hall 3	3rd	East	Door casing	Center	Stain	Wood	common
PASS	0.04	12/7/16	4:33 PM	#701	Hall 3	3rd	North	Door casing	Center	Stain	Wood	common
PASS	0.04	12/7/16	4:33 PM	#702	Hall 3	3rd	South	Door casing	Center	Stain	Wood	common
PASS	0.01	12/7/16	4:34 PM	#703	Hall 3	3rd	West	Door casing	Center	Stain	Wood	common
▼ south												
▼ Staircase												
PASS	0.22	12/7/16	4:09 PM	#667	Staircase	LL	South	Wall	Center	White	Plaster	south
PASS	0	12/7/16	4:10 PM	#668	Staircase	LL	North	Wall	Center	White	Plaster	south
PASS	0.2	12/7/16	4:10 PM	#669	Staircase	LL	West	Wall	Center	White	Plaster	south
PASS	0.23	12/7/16	4:11 PM	#670	Staircase	LL	East	Wall	Center	White	Plaster	south
PASS	0.53	12/7/16	4:11 PM	#671	Staircase	LL	East	Stair tread	Center	Gray	Concrete	south

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
FAIL	2.77	12/7/16	4:12 PM	#672	Staircase	LL	East	Stair handrail	Center	Black	Metal	south
FAIL	1.44	12/7/16	4:12 PM	#673	Staircase	3rd	East	Stair handrail	Center	Black	Metal	south
PASS	0.23	12/7/16	4:13 PM	#674	Staircase	3rd	East	Wall	Center	White	Plaster	south
PASS	0.16	12/7/16	4:13 PM	#675	Staircase	3rd	South	Wall	Center	White	Plaster	south
PASS	0.26	12/7/16	4:14 PM	#676	Staircase	3rd	West	Wall	Center	White	Plaster	south
PASS	0.24	12/7/16	4:14 PM	#677	Staircase	3rd	North	Wall	Center	White	Plaster	south
▼ west												
▼ Staircase 2												
PASS	0.22	12/7/16	4:26 PM	#690	Staircase 2	3rd	North	Stair handrail	Center	Black	Metal	west
PASS	0.1	12/7/16	4:27 PM	#691	Staircase 2	3rd	North	Wall	Center	White	Plaster	west
PASS	0.15	12/7/16	4:28 PM	#692	Staircase 2	3rd	South	Wall	Center	White	Plaster	west
PASS	0.13	12/7/16	4:28 PM	#693	Staircase 2	3rd	West	Wall	Center	White	Plaster	west
PASS	0.07	12/7/16	4:29 PM	#694	Staircase 2	3rd	West	Window casing	Center	Stain	Wood	west