

Minnesota Lead Testers

952-200-5044

Client Information

Performance Equity LLC
8362 Tamarack vlg, ste
119-308

Woodburv mn 55125

Contact: Jon 715-220-7467



Paul Nygren
Director, Env. Health Div.

 **LEAD
Risk Assessor**

Licensed by:
State of Minnesota
Department of Health
License No. LR3633
Expires 11/11/2017

Paul Nygren
6225 207th Ave NE
Wyoming, MN 55092

XRF Test Results

Time of Test:	8:27 AM	12/12/16
---------------	---------	----------

Test Site Information

Owner: THOMAS AVENUE APARTMENTS LLC

Age of Property: 1928

Address: 1900 Thomas Ave N
Minneapolis MN 55411



Paul Nygren

Minnesota Lead Testers

6225 207th Ave. NE, Wyoming MN 55092
952-200-5044 Paul Nygren, Owner

Firm License # LF 3614

XRF Analyzer Manufacture: Innov-X

Model: Delta LBP-4000 **Serial #** 560309

Minnesota Lead Testers

952-200-5044

These readings are for calibration purposes only, not part of test results.

Start	8:27 AM	NIST Check - Passed
Finish	3:08 PM	NIST Check - Passed

- = no or minute amounts of lead present
- = 0.2 - .99 Micrograms per square cm of lead present
- = 1.0 Microgram or greater per square cm of lead present: **Lead safe practices required if disturbing these surfaces**

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
▼ unit 301												
▼ Living room												
PASS	█ 0	12/12/16	8:27 AM	#3	Living room	1st	North	Ceiling	Center	White	Plaster	unit 301
PASS	█ 0	12/12/16	8:28 AM	#4	Living room	1st	North	Wall	Center	White	Plaster	unit 301
PASS	█ 0	12/12/16	8:28 AM	#5	Living room	1st	West	Wall	Center	White	Plaster	unit 301
PASS	█ 0	12/12/16	8:29 AM	#6	Living room	1st	South	Wall	Upper	White	Plaster	unit 301
PASS	█ 0	12/12/16	8:29 AM	#7	Living room	1st	East	Wall	Lower	White	Plaster	unit 301
PASS	█ 0.01	12/12/16	8:30 AM	#8	Living room	1st	North	Window casing	Center	Stain	Wood	unit 301
PASS	█ 0.01	12/12/16	8:31 AM	#9	Living room	1st	West	Window sash	Center	Stain	Wood	unit 301
PASS	█ 0	12/12/16	8:31 AM	#10	Living room	1st	South	Door casing	Center	Stain	Wood	unit 301
PASS	█ 0.01	12/12/16	8:32 AM	#11	Living room	1st	East	Door	Center	Stain	Wood	unit 301
PASS	█ 0.01	12/12/16	8:34 AM	#12	Living room	1st	West	Baseboard	Center	Stain	Wood	unit 301
PASS	█ 0	12/12/16	8:35 AM	#13	Living room	1st	East	Closet	Center	White	Plaster	unit 301
▼ Dining												
PASS	█ 0	12/12/16	8:36 AM	#14	Dining	1st	East	Ceiling	Center	White	Plaster	unit 301
PASS	█ 0	12/12/16	8:36 AM	#15	Dining	1st	North	Wall	Center	White	Plaster	unit 301
PASS	█ 0	12/12/16	8:37 AM	#16	Dining	1st	West	Wall	Center	White	Plaster	unit 301
PASS	█ 0	12/12/16	8:37 AM	#17	Dining	1st	East	Wall	Upper	White	Plaster	unit 301
PASS	█ 0.01	12/12/16	8:38 AM	#18	Dining	1st	South	Wall	Lower	White	Plaster	unit 301

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.01	12/12/16	8:39 AM	#19	Dining	1st	North	Window casing	Center	Stain	Wood	unit 301
PASS	0.01	12/12/16	8:40 AM	#20	Dining	1st	East	Door casing	Center	Stain	Wood	unit 301
PASS	0.01	12/12/16	8:41 AM	#21	Dining	1st	North	Baseboard	Center	Stain	Wood	unit 301
PASS	0.33	12/12/16	8:42 AM	#22	Dining	1st	North	Radiator	Center	White	Metal	unit 301
▼ Kitchen												
FAIL	1.38	12/12/16	8:44 AM	#23	Kitchen	1st	North	Ceiling	Center	White	Plaster	unit 301
PASS	0.33	12/12/16	8:44 AM	#24	Kitchen	1st	North	Wall	Center	White	Plaster	unit 301
PASS	0	12/12/16	8:44 AM	#25	Kitchen	1st	South	Wall	Center	White	Plaster	unit 301
PASS	0.49	12/12/16	8:45 AM	#26	Kitchen	1st	East	Wall	Upper	White	Plaster	unit 301
FAIL	1.69	12/12/16	8:46 AM	#27	Kitchen	1st	West	Wall	Lower	White	Plaster	unit 301
PASS	0.73	12/12/16	8:46 AM	#28	Kitchen	1st	West	Baseboard	Lower	White	Wood	unit 301
PASS	0.7	12/12/16	8:47 AM	#29	Kitchen	1st	East	Cabinet	Lower	White	Wood	unit 301
PASS	0.31	12/12/16	8:47 AM	#30	Kitchen	1st	East	Cabinet	Upper	White	Wood	unit 301
▼ Bathroom												
PASS	0.86	12/12/16	8:49 AM	#31	Bathroom	1st	East	Ceiling	Center	White	Plaster	unit 301
FAIL	1.09	12/12/16	8:50 AM	#32	Bathroom	1st	East	Wall	Center	White	Plaster	unit 301
FAIL	1.77	12/12/16	8:50 AM	#33	Bathroom	1st	West	Wall	Center	White	Plaster	unit 301
PASS	0.25	12/12/16	8:50 AM	#34	Bathroom	1st	South	Wall	Lower	White	Plaster	unit 301
PASS	0.92	12/12/16	8:51 AM	#35	Bathroom	1st	North	Wall	Upper	White	Plaster	unit 301
PASS	0.25	12/12/16	8:53 AM	#36	Bathroom	1st	North	Window casing	Center	White	Wood	unit 301
PASS	0.44	12/12/16	8:53 AM	#37	Bathroom	1st	South	Door casing	Center	White	Wood	unit 301
FAIL	1.87	12/12/16	8:54 AM	#38	Bathroom	1st	West	Baseboard	Center	White	Wood	unit 301
PASS	0.03	12/12/16	8:55 AM	#39	Bathroom	1st	North	Floor	Center	White	Ceramic	unit 301
FAIL	5	12/12/16	8:55 AM	#40	Bathroom	1st	North	Bathtub	Center	White	Metal	unit 301
PASS	0.45	12/12/16	8:56 AM	#41	Bathroom	1st	West	Radiator	Center	White	Metal	unit 301
▼ Hall												
PASS	0.01	12/12/16	8:57 AM	#42	Hall	1st	North	Ceiling	Center	White	Plaster	unit 301
PASS	0.01	12/12/16	8:57 AM	#43	Hall	1st	South	Wall	Upper	White	Plaster	unit 301
PASS	0.01	12/12/16	8:58 AM	#44	Hall	1st	West	Wall	Upper	White	Plaster	unit 301
PASS	0.01	12/12/16	8:58 AM	#45	Hall	1st	East	Wall	Upper	White	Plaster	unit 301
PASS	0	12/12/16	8:59 AM	#46	Hall	1st	North	Wall	Lower	White	Plaster	unit 301
PASS	0.41	12/12/16	9:00 AM	#47	Hall	1st	North	Door casing	Center	White	Wood	unit 301
PASS	0.14	12/12/16	9:00 AM	#48	Hall	1st	East	Door jamb	Center	White	Wood	unit 301
PASS	0.11	12/12/16	9:01 AM	#49	Hall	1st	South	Cabinet	Center	White	Wood	unit 301
▼ Bdrm 1												
PASS	0	12/12/16	9:01 AM	#50	Bdrm 1	1st	South	Ceiling	Center	White	Plaster	unit 301
PASS	0	12/12/16	9:02 AM	#51	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 301

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.01	12/12/16	9:02 AM	#52	Bdrm 1	1st	South	Wall	Center	White	Plaster	unit 301
PASS	0.01	12/12/16	9:03 AM	#53	Bdrm 1	1st	West	Wall	Upper	White	Plaster	unit 301
PASS	0.01	12/12/16	9:03 AM	#54	Bdrm 1	1st	East	Wall	Lower	White	Plaster	unit 301
PASS	0.32	12/12/16	9:04 AM	#55	Bdrm 1	1st	North	Window casing	Center	White	Wood	unit 301
PASS	0.47	12/12/16	9:04 AM	#56	Bdrm 1	1st	West	Door casing	Center	White	Wood	unit 301
PASS	0.25	12/12/16	9:05 AM	#57	Bdrm 1	1st	North	Baseboard	Center	White	Wood	unit 301
PASS	0.78	12/12/16	9:06 AM	#58	Bdrm 1	1st	North	Radiator	Center	White	Metal	unit 301
PASS	0.01	12/12/16	9:06 AM	#59	Bdrm 1	1st	West	Door	Left	White	Metal	unit 301
PASS	0.06	12/12/16	9:07 AM	#60	Bdrm 1	1st	West	Closet	Center	White	Plaster	unit 301
▼ unit 104												
▼ Bdrm 1												
PASS	0	12/12/16	9:18 AM	#61	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 104
PASS	0.03	12/12/16	9:19 AM	#62	Bdrm 1	1st	South	Wall	Center	White	Wood	unit 104
PASS	0.02	12/12/16	9:19 AM	#63	Bdrm 1	1st	East	Wall	Upper	White	Wood	unit 104
PASS	0.03	12/12/16	9:20 AM	#64	Bdrm 1	1st	West	Wall	Lower	White	Wood	unit 104
PASS	0.2	12/12/16	9:20 AM	#65	Bdrm 1	1st	South	Window casing	Center	White	Wood	unit 104
PASS	0	12/12/16	9:21 AM	#66	Bdrm 1	1st	East	Door casing	Center	White	Wood	unit 104
PASS	0.14	12/12/16	9:21 AM	#67	Bdrm 1	1st	East	Door jamb	Left	White	Wood	unit 104
PASS	0.32	12/12/16	9:22 AM	#68	Bdrm 1	1st	West	Baseboard	Center	White	Wood	unit 104
PASS	0.06	12/12/16	9:23 AM	#69	Bdrm 1	1st	East	Closet	Center	White	Plaster	unit 104
PASS	0.43	12/12/16	9:23 AM	#70	Bdrm 1	1st	East	Radiator	Center	White	Metal	unit 104
▼ Bathroom												
PASS	0	12/12/16	9:26 AM	#71	Bathroom	1st	North	Wall	Upper	White	Plaster	unit 104
PASS	0	12/12/16	9:26 AM	#72	Bathroom	1st	West	Wall	Lower	White	Plaster	unit 104
PASS	0	12/12/16	9:26 AM	#73	Bathroom	1st	East	Wall	Center	White	Plaster	unit 104
PASS	0	12/12/16	9:27 AM	#74	Bathroom	1st	South	Wall	Center	White	Concrete	unit 104
PASS	0.27	12/12/16	9:28 AM	#75	Bathroom	1st	South	Window casing	Center	White	Wood	unit 104
FAIL	2.16	12/12/16	9:28 AM	#76	Bathroom	1st	North	Bathtub	Center	White	Metal	unit 104
PASS	0.01	12/12/16	9:28 AM	#77	Bathroom	1st	East	Door casing	Center	White	Wood	unit 104
▼ Living room												
PASS	0.05	12/12/16	9:29 AM	#78	Living room	1st	East	Ceiling	Center	White	Plaster	unit 104
PASS	0.02	12/12/16	9:30 AM	#79	Living room	1st	North	Wall	Center	White	Plaster	unit 104
PASS	0	12/12/16	9:30 AM	#80	Living room	1st	West	Wall	Center	White	Plaster	unit 104
PASS	0	12/12/16	9:31 AM	#81	Living room	1st	East	Wall	Upper	White	Plaster	unit 104
PASS	0	12/12/16	9:31 AM	#82	Living room	1st	South	Wall	Lower	White	Concrete	unit 104
PASS	0.26	12/12/16	9:32 AM	#83	Living room	1st	South	Window sash	Right	White	Wood	unit 104
PASS	0.19	12/12/16	9:33 AM	#84	Living room	1st	South	Window stool	Left	White	Wood	unit 104

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0	12/12/16	9:33 AM	#85	Living room	1st	North	Door casing	Center	White	Wood	unit 104
PASS	0.59	12/12/16	9:34 AM	#86	Living room	1st	North	Closet	Center	White	Concrete	unit 104
PASS	0.48	12/12/16	9:35 AM	#87	Living room	1st	East	Window casing	Center	Brown	Wood	unit 104
PASS	0.03	12/12/16	9:35 AM	#88	Living room	1st	East	Radiator	Center	Silver	Metal	unit 104
▼ Kitchen												
PASS	0.94	12/12/16	9:36 AM	#89	Kitchen	1st	North	Wall	Center	White	Concrete	unit 104
PASS	0	12/12/16	9:36 AM	#90	Kitchen	1st	West	Wall	Center	White	Plaster	unit 104
PASS	0.01	12/12/16	9:37 AM	#91	Kitchen	1st	East	Wall	Upper	White	Concrete	unit 104
▼ unit 202												
▼ Kitchen												
FAIL	3.43	12/12/16	9:40 AM	#92	Kitchen	1st	East	Ceiling	Center	White	Plaster	unit 202
FAIL	3.12	12/12/16	9:41 AM	#93	Kitchen	1st	North	Wall	Center	White	Plaster	unit 202
FAIL	1.92	12/12/16	9:41 AM	#94	Kitchen	1st	West	Wall	Center	White	Plaster	unit 202
PASS	0	12/12/16	9:42 AM	#95	Kitchen	1st	East	Wall	Upper	White	Wood	unit 202
PASS	0.61	12/12/16	9:42 AM	#96	Kitchen	1st	South	Wall	Lower	White	Wood	unit 202
FAIL	1.14	12/12/16	9:43 AM	#97	Kitchen	1st	East	Cabinet	Lower	White	Wood	unit 202
FAIL	1.59	12/12/16	9:43 AM	#98	Kitchen	1st	East	Cabinet	Upper	White	Wood	unit 202
▼ Bdrm 1												
PASS	0.01	12/12/16	9:44 AM	#99	Bdrm 1	1st	North	Ceiling	Center	White	Plaster	unit 202
PASS	0	12/12/16	9:45 AM	#100	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 202
PASS	0	12/12/16	9:45 AM	#101	Bdrm 1	1st	South	Wall	Center	White	Plaster	unit 202
PASS	0	12/12/16	9:46 AM	#102	Bdrm 1	1st	East	Wall	Upper	White	Plaster	unit 202
PASS	0	12/12/16	9:46 AM	#103	Bdrm 1	1st	West	Wall	Lower	White	Plaster	unit 202
PASS	0.31	12/12/16	9:47 AM	#104	Bdrm 1	1st	South	Window casing	Center	White	Wood	unit 202
PASS	0	12/12/16	9:47 AM	#105	Bdrm 1	1st	West	Door casing	Center	White	Wood	unit 202
PASS	0.07	12/12/16	9:48 AM	#106	Bdrm 1	1st	West	Door	Right	White	Wood	unit 202
PASS	0.15	12/12/16	9:48 AM	#107	Bdrm 1	1st	East	Baseboard	Center	White	Wood	unit 202
PASS	0.27	12/12/16	9:49 AM	#108	Bdrm 1	1st	West	Cabinet	Left	White	Wood	unit 202
PASS	0	12/12/16	9:49 AM	#109	Bdrm 1	1st	West	Floor	Center	Stain	Wood	unit 202
PASS	0.01	12/12/16	9:50 AM	#110	Bdrm 1	1st	South	Radiator	Center	White	Metal	unit 202
PASS	0.02	12/12/16	9:51 AM	#111	Bdrm 1	1st	West	Closet	Center	White	Plaster	unit 202
▼ Hall												
PASS	0	12/12/16	9:51 AM	#112	Hall	1st	West	Ceiling	Center	White	Plaster	unit 202
PASS	0	12/12/16	9:52 AM	#113	Hall	1st	West	Wall	Upper	White	Plaster	unit 202
PASS	0	12/12/16	9:52 AM	#114	Hall	1st	East	Wall	Upper	White	Plaster	unit 202
PASS	0	12/12/16	9:53 AM	#115	Hall	1st	North	Wall	Upper	White	Plaster	unit 202
PASS	0	12/12/16	9:53 AM	#116	Hall	1st	South	Wall	Lower	White	Plaster	unit 202

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.62	12/12/16	9:54 AM	#117	Hall	1st	South	Door casing	Center	White	Wood	unit 202
PASS	0.28	12/12/16	9:54 AM	#118	Hall	1st	West	Door jamb	Center	White	Wood	unit 202
PASS	0.31	12/12/16	9:55 AM	#119	Hall	1st	North	Cabinet	Center	White	Wood	unit 202
▼ Bathroom												
FAIL	1.75	12/12/16	9:55 AM	#120	Bathroom	1st	North	Wall	Center	White	Plaster	unit 202
FAIL	1.27	12/12/16	9:56 AM	#121	Bathroom	1st	East	Wall	Center	White	Plaster	unit 202
FAIL	2.01	12/12/16	9:56 AM	#122	Bathroom	1st	West	Wall	Lower	White	Plaster	unit 202
FAIL	3.05	12/12/16	9:57 AM	#123	Bathroom	1st	South	Wall	Upper	White	Plaster	unit 202
FAIL	1.81	12/12/16	9:57 AM	#124	Bathroom	1st	South	Window casing	Center	White	Wood	unit 202
FAIL	3.94	12/12/16	9:57 AM	#125	Bathroom	1st	North	Door casing	Center	White	Wood	unit 202
FAIL	1.46	12/12/16	9:58 AM	#126	Bathroom	1st	North	Door	Center	White	Wood	unit 202
FAIL	1.77	12/12/16	9:58 AM	#127	Bathroom	1st	East	Cabinet	Center	White	Wood	unit 202
PASS	0.03	12/12/16	9:59 AM	#128	Bathroom	1st	East	Floor	Center	White	Ceramic	unit 202
FAIL	5	12/12/16	9:59 AM	#129	Bathroom	1st	South	Bathtub	Center	White	Metal	unit 202
PASS	0.34	12/12/16	10:00 AM	#130	Bathroom	1st	West	Radiator	Center	White	Metal	unit 202
▼ Dining												
PASS	0.64	12/12/16	10:00 AM	#131	Dining	1st	South	Radiator	Center	White	Metal	unit 202
PASS	0.01	12/12/16	10:01 AM	#132	Dining	1st	South	Ceiling	Center	White	Plaster	unit 202
PASS	0	12/12/16	10:01 AM	#133	Dining	1st	North	Wall	Center	White	Plaster	unit 202
PASS	0	12/12/16	10:02 AM	#134	Dining	1st	South	Wall	Center	White	Plaster	unit 202
PASS	0	12/12/16	10:02 AM	#135	Dining	1st	West	Wall	Upper	White	Plaster	unit 202
PASS	0	12/12/16	10:03 AM	#136	Dining	1st	East	Wall	Lower	White	Plaster	unit 202
PASS	0.01	12/12/16	10:03 AM	#137	Dining	1st	South	Window casing	Center	White	Wood	unit 202
PASS	0.01	12/12/16	10:04 AM	#138	Dining	1st	East	Door casing	Center	White	Wood	unit 202
PASS	0	12/12/16	10:05 AM	#139	Dining	1st	East	Baseboard	Center	White	Wood	unit 202
PASS	0.01	12/12/16	10:05 AM	#140	Dining	1st	North	Cabinet	Left	White	Wood	unit 202
▼ Living room												
PASS	0.01	12/12/16	10:06 AM	#141	Living room	1st	North	Ceiling	Center	White	Plaster	unit 202
PASS	0	12/12/16	10:06 AM	#142	Living room	1st	North	Wall	Center	White	Plaster	unit 202
PASS	0	12/12/16	10:07 AM	#143	Living room	1st	East	Wall	Center	White	Plaster	unit 202
PASS	0	12/12/16	10:07 AM	#144	Living room	1st	South	Wall	Upper	White	Plaster	unit 202
PASS	0	12/12/16	10:08 AM	#145	Living room	1st	West	Wall	Lower	White	Plaster	unit 202
PASS	0.01	12/12/16	10:08 AM	#146	Living room	1st	West	Window casing	Right	White	Wood	unit 202
PASS	0.03	12/12/16	10:09 AM	#147	Living room	1st	West	Window sash	Left	White	Wood	unit 202
PASS	0	12/12/16	10:10 AM	#148	Living room	1st	South	Window stool	Center	White	Wood	unit 202
PASS	0	12/12/16	10:10 AM	#149	Living room	1st	North	Door	Center	White	Wood	unit 202
PASS	0.01	12/12/16	10:11 AM	#150	Living room	1st	East	Door casing	Center	White	Wood	unit 202

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0	12/12/16	10:11 AM	#151	Living room	1st	East	Baseboard	Center	White	Wood	unit 202
PASS	0.23	12/12/16	10:12 AM	#152	Living room	1st	West	Radiator	Center	White	Metal	unit 202
PASS	0.02	12/12/16	10:13 AM	#153	Living room	1st	East	Closet	Center	White	Plaster	unit 202
▼ common												
▼ Hall												
PASS	0.04	12/12/16	10:16 AM	#154	Hall	3rd	West	Ceiling	Center	White	Plaster	common
PASS	0.22	12/12/16	10:17 AM	#155	Hall	3rd	East	Ceiling	Center	White	Plaster	common
PASS	0.03	12/12/16	10:18 AM	#156	Hall	3rd	North	Wall	Right	White	Plaster	common
PASS	0.37	12/12/16	10:18 AM	#157	Hall	3rd	North	Wall	Left	White	Plaster	common
PASS	0.08	12/12/16	10:19 AM	#158	Hall	3rd	South	Wall	Right	White	Plaster	common
PASS	0.09	12/12/16	10:19 AM	#159	Hall	3rd	South	Wall	Left	White	Plaster	common
PASS	0.04	12/12/16	10:20 AM	#160	Hall	3rd	East	Wall	Upper	White	Plaster	common
PASS	0.02	12/12/16	10:20 AM	#161	Hall	3rd	East	Door casing	Center	Stain	Wood	common
FAIL	1.06	12/12/16	10:21 AM	#162	Hall	3rd	East	Door	Center	Red	Wood	common
PASS	0	12/12/16	10:22 AM	#163	Hall	3rd	North	Door	Right	Red	Wood	common
PASS	0	12/12/16	10:22 AM	#164	Hall	3rd	South	Door	Right	Red	Wood	common
PASS	0.02	12/12/16	10:23 AM	#165	Hall	3rd	North	Door casing	Left	Stain	Wood	common
PASS	0.01	12/12/16	10:24 AM	#166	Hall	3rd	South	Door casing	Left	Stain	Wood	common
PASS	0.01	12/12/16	10:25 AM	#167	Hall	3rd	South	Baseboard	Center	Stain	Wood	common
▼ Staircase												
PASS	0.04	12/12/16	10:36 AM	#186	Staircase	2nd	East	Ceiling	Center	White	Plaster	common
PASS	0.03	12/12/16	10:36 AM	#187	Staircase	2nd	North	Wall	Right	White	Plaster	common
PASS	0.04	12/12/16	10:37 AM	#188	Staircase	2nd	South	Wall	Left	White	Plaster	common
PASS	0.09	12/12/16	10:38 AM	#189	Staircase	2nd	South	Wall	Right	White	Plaster	common
PASS	0.04	12/12/16	10:38 AM	#190	Staircase	2nd	North	Wall	Left	White	Plaster	common
PASS	0.03	12/12/16	10:39 AM	#191	Staircase	2nd	East	Wall	Center	White	Plaster	common
PASS	0.01	12/12/16	10:40 AM	#192	Staircase	2nd	East	Door casing	Center	Stain	Wood	common
▼ Hall 2												
PASS	0.01	12/12/16	10:41 AM	#193	Hall 2	2nd	North	Door casing	Right	Stain	Wood	common
PASS	0	12/12/16	10:41 AM	#194	Hall 2	2nd	South	Door casing	Left	Red	Wood	common
PASS	0.02	12/12/16	10:42 AM	#195	Hall 2	2nd	South	Door casing	Right	Stain	Wood	common
PASS	0.01	12/12/16	10:43 AM	#196	Hall 2	2nd	North	Door	Center	Stain	Wood	common
▼ Hall 3												
PASS	0.01	12/12/16	10:45 AM	#197	Hall 3	1st	North	Ceiling	Center	White	Plaster	common
PASS	0.3	12/12/16	10:45 AM	#198	Hall 3	1st	North	Wall	Center	White	Plaster	common
PASS	0.52	12/12/16	10:46 AM	#199	Hall 3	1st	South	Wall	Center	White	Plaster	common
PASS	0.02	12/12/16	10:46 AM	#200	Hall 3	1st	East	Wall	Upper	White	Plaster	common

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.59	12/12/16	10:47 AM	#201	Hall 3	1st	West	Wall	Lower	White	Plaster	common
FAIL	1.34	12/12/16	10:48 AM	#202	Hall 3	1st	West	Door	Center	White	Metal	common
PASS	0	12/12/16	10:49 AM	#203	Hall 3	1st	North	Door	Left	Red	Metal	common
FAIL	1.38	12/12/16	10:49 AM	#204	Hall 3	1st	South	Door casing	Right	White	Wood	common
PASS	0.96	12/12/16	10:50 AM	#205	Hall 3	1st	South	Door	Center	White	Wood	common
FAIL	1.77	12/12/16	10:50 AM	#206	Hall 3	1st	North	Door casing	Right	White	Wood	common
▼ Laundry												
PASS	0	12/12/16	2:57 PM	#560	Laundry	3rd	West	Ceiling	Center	White	Plaster	common
PASS	0	12/12/16	2:58 PM	#561	Laundry	3rd	North	Wall	Center	Tan	Concrete	common
PASS	0	12/12/16	2:58 PM	#562	Laundry	3rd	West	Wall	Center	Tan	Plaster	common
PASS	0	12/12/16	2:59 PM	#563	Laundry	3rd	South	Wall	Upper	Tan	Plaster	common
PASS	0	12/12/16	2:59 PM	#564	Laundry	3rd	East	Wall	Center	Tan	Wood	common
PASS	0.05	12/12/16	3:00 PM	#565	Laundry	3rd	North	Window casing	Center	Tan	Wood	common
PASS	0.07	12/12/16	3:00 PM	#566	Laundry	3rd	South	Door casing	Center	Tan	Wood	common
PASS	0.01	12/12/16	3:01 PM	#567	Laundry	3rd	South	Floor	Center	Gray	Concrete	common
▼ common east												
▼ Staircase												
PASS	0	12/12/16	10:26 AM	#168	Staircase	3rd	North	Ceiling	Center	White	Plaster	common east
FAIL	1.19	12/12/16	10:26 AM	#169	Staircase	3rd	North	Wall	Center	White	Plaster	common east
FAIL	1.05	12/12/16	10:27 AM	#170	Staircase	3rd	South	Wall	Center	White	Plaster	common east
FAIL	1.29	12/12/16	10:27 AM	#171	Staircase	3rd	West	Wall	Center	White	Plaster	common east
FAIL	1.05	12/12/16	10:28 AM	#172	Staircase	3rd	West	Door casing	Center	Gray	Metal	common east
FAIL	1.2	12/12/16	10:28 AM	#173	Staircase	3rd	West	Floor	Center	Gray	Concrete	common east
FAIL	1.44	12/12/16	10:29 AM	#174	Staircase	2nd	East	Wall	Center	White	Plaster	common east
FAIL	5	12/12/16	10:30 AM	#175	Staircase	2nd	East	Door	Center	Gray	Wood	common east
FAIL	3.08	12/12/16	10:30 AM	#176	Staircase	2nd	East	Stair newel	Center	Black	Metal	common east
FAIL	1.2	12/12/16	10:31 AM	#177	Staircase	2nd	West	Door	Center	Gray	Metal	common east
FAIL	1.22	12/12/16	10:32 AM	#178	Staircase	2nd	North	Wall	Center	White	Plaster	common east
FAIL	1.52	12/12/16	10:32 AM	#179	Staircase	2nd	South	Wall	Center	White	Plaster	common east
FAIL	1.34	12/12/16	10:32 AM	#180	Staircase	2nd	West	Wall	Center	White	Plaster	common east
FAIL	1.4	12/12/16	10:33 AM	#181	Staircase	1st	East	Wall	Center	White	Plaster	common east
FAIL	1.12	12/12/16	10:33 AM	#182	Staircase	1st	South	Wall	Center	White	Plaster	common east
PASS	0.34	12/12/16	10:34 AM	#183	Staircase	1st	North	Wall	Center	White	Plaster	common east
PASS	0.02	12/12/16	10:34 AM	#184	Staircase	1st	East	Door casing	Center	Red	Metal	common east
FAIL	1.42	12/12/16	10:35 AM	#185	Staircase	1st	West	Door	Center	Gray	Metal	common east
▼ common west												
▼ Staircase 2												

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
FAIL	1.35	12/12/16	10:51 AM	#207	Staircase 2	1st	East	Door casing	Center	White	Metal	common west
FAIL	1.18	12/12/16	10:52 AM	#208	Staircase 2	1st	South	Door	Center	Red	Metal	common west
PASS	0.01	12/12/16	10:53 AM	#209	Staircase 2	1st	North	Wall	Center	White	Plaster	common west
PASS	0.01	12/12/16	10:53 AM	#210	Staircase 2	1st	South	Wall	Center	White	Plaster	common west
PASS	0.01	12/12/16	10:53 AM	#211	Staircase 2	1st	East	Wall	Upper	White	Plaster	common west
PASS	0.5	12/12/16	10:54 AM	#212	Staircase 2	1st	West	Wall	Lower	White	Plaster	common west
PASS	0.02	12/12/16	10:56 AM	#213	Staircase 2	2nd	West	Ceiling	Center	White	Plaster	common west
PASS	0.01	12/12/16	10:56 AM	#214	Staircase 2	2nd	North	Wall	Center	White	Plaster	common west
PASS	0.01	12/12/16	10:57 AM	#215	Staircase 2	2nd	South	Wall	Center	White	Plaster	common west
PASS	0.01	12/12/16	10:57 AM	#216	Staircase 2	2nd	East	Wall	Upper	Green	Plaster	common west
PASS	0	12/12/16	10:58 AM	#217	Staircase 2	2nd	West	Wall	Center	White	Plaster	common west
PASS	0.02	12/12/16	10:59 AM	#218	Staircase 2	2nd	West	Window casing	Center	Stain	Wood	common west
PASS	0.02	12/12/16	11:00 AM	#219	Staircase 2	2nd	West	Baseboard	Center	Stain	Wood	common west
PASS	0.06	12/12/16	11:01 AM	#220	Staircase 2	2nd	South	Stair handrail	Center	Black	Metal	common west
PASS	0.27	12/12/16	11:01 AM	#221	Staircase 2	2nd	North	Radiator	Center	White	Metal	common west
▼ common												
▼ Foyer												
PASS	0	12/12/16	11:03 AM	#222	Foyer	2nd	North	Ceiling	Center	White	Plaster	common
PASS	0.78	12/12/16	11:04 AM	#223	Foyer	2nd	North	Wall	Center	White	Plaster	common
FAIL	1.15	12/12/16	11:04 AM	#224	Foyer	2nd	South	Wall	Center	White	Plaster	common
PASS	0.73	12/12/16	11:05 AM	#225	Foyer	2nd	West	Wall	Upper	White	Plaster	common
FAIL	1	12/12/16	11:06 AM	#226	Foyer	2nd	East	Wall	Lower	White	Plaster	common
PASS	0.01	12/12/16	11:06 AM	#227	Foyer	2nd	East	Door	Left	Stain	Wood	common
PASS	0.01	12/12/16	11:07 AM	#228	Foyer	2nd	East	Door casing	Right	Stain	Wood	common
FAIL	4.11	12/12/16	11:07 AM	#229	Foyer	1st	West	Door	Center	Yellow	Wood	common
PASS	0.01	12/12/16	11:08 AM	#230	Foyer	1st	West	Window casing	Right	Stain	Wood	common
PASS	0	12/12/16	11:09 AM	#231	Foyer	1st	West	Floor	Center	Tan	Ceramic	common
▼ unit 102												
▼ Living room												
PASS	0	12/12/16	11:11 AM	#232	Living room	1st	West	Ceiling	Center	White	Plaster	unit 102
PASS	0	12/12/16	11:11 AM	#233	Living room	1st	North	Wall	Center	White	Plaster	unit 102
PASS	0	12/12/16	11:11 AM	#234	Living room	1st	West	Wall	Center	White	Plaster	unit 102
PASS	0	12/12/16	11:12 AM	#235	Living room	1st	East	Wall	Upper	White	Plaster	unit 102
PASS	0	12/12/16	11:12 AM	#236	Living room	1st	South	Wall	Lower	White	Plaster	unit 102
PASS	0.01	12/12/16	11:13 AM	#237	Living room	1st	South	Window casing	Center	Tan	Wood	unit 102
PASS	0.5	12/12/16	11:14 AM	#238	Living room	1st	West	Window sash	Center	Tan	Wood	unit 102
PASS	0.24	12/12/16	11:14 AM	#239	Living room	1st	North	Door casing	Center	White	Wood	unit 102

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.92	12/12/16	11:15 AM	#240	Living room	1st	North	Door	Center	White	Metal	unit 102
PASS	0.01	12/12/16	11:16 AM	#241	Living room	1st	East	Door jamb	Left	White	Wood	unit 102
PASS	0.01	12/12/16	11:16 AM	#242	Living room	1st	East	Baseboard	Center	White	Wood	unit 102
PASS	0	12/12/16	11:17 AM	#243	Living room	1st	East	Closet	Left	White	Plaster	unit 102
▼ Kitchen												
PASS	0	12/12/16	11:18 AM	#244	Kitchen	1st	East	Ceiling	Center	White	Plaster	unit 102
FAIL	2.05	12/12/16	11:18 AM	#245	Kitchen	1st	North	Ceiling	Center	White	Plaster	unit 102
PASS	0	12/12/16	11:18 AM	#246	Kitchen	1st	North	Wall	Center	White	Plaster	unit 102
PASS	0	12/12/16	11:19 AM	#247	Kitchen	1st	West	Wall	Center	White	Plaster	unit 102
PASS	0	12/12/16	11:19 AM	#248	Kitchen	1st	West	Wall	Left	White	Plaster	unit 102
PASS	0	12/12/16	11:20 AM	#249	Kitchen	1st	East	Wall	Left	White	Plaster	unit 102
PASS	0	12/12/16	11:20 AM	#250	Kitchen	1st	East	Wall	Right	White	Plaster	unit 102
PASS	0	12/12/16	11:20 AM	#251	Kitchen	1st	South	Wall	Upper	White	Plaster	unit 102
PASS	0.02	12/12/16	11:21 AM	#252	Kitchen	1st	South	Window casing	Center	Tan	Wood	unit 102
PASS	0.01	12/12/16	11:21 AM	#253	Kitchen	1st	East	Door casing	Center	White	Wood	unit 102
PASS	0	12/12/16	11:22 AM	#254	Kitchen	1st	East	Baseboard	Center	White	Wood	unit 102
PASS	0.83	12/12/16	11:22 AM	#255	Kitchen	1st	East	Radiator	Center	White	Metal	unit 102
PASS	0.01	12/12/16	11:23 AM	#256	Kitchen	1st	North	Cabinet	Left	White	Wood	unit 102
▼ Bathroom												
PASS	0	12/12/16	11:24 AM	#257	Bathroom	1st	North	Wall	Center	White	Plaster	unit 102
PASS	0.01	12/12/16	11:24 AM	#258	Bathroom	1st	East	Wall	Center	White	Plaster	unit 102
PASS	0.01	12/12/16	11:24 AM	#259	Bathroom	1st	West	Wall	Upper	White	Plaster	unit 102
PASS	0.02	12/12/16	11:25 AM	#260	Bathroom	1st	West	Wall	Lower	White	Ceramic	unit 102
PASS	0.01	12/12/16	11:25 AM	#261	Bathroom	1st	West	Floor	Center	White	Ceramic	unit 102
FAIL	5	12/12/16	11:26 AM	#262	Bathroom	1st	South	Wall	Center	White	Plaster	unit 102
PASS	0.88	12/12/16	11:27 AM	#263	Bathroom	1st	South	Window stool	Center	White	Wood	unit 102
FAIL	5	12/12/16	11:27 AM	#264	Bathroom	1st	South	Bathtub	Center	White	Metal	unit 102
PASS	0.75	12/12/16	11:28 AM	#265	Bathroom	1st	North	Door header	Center	White	Wood	unit 102
▼ Hall												
PASS	0	12/12/16	11:28 AM	#266	Hall	1st	North	Ceiling	Center	White	Plaster	unit 102
PASS	0.01	12/12/16	11:29 AM	#267	Hall	1st	North	Wall	Upper	White	Plaster	unit 102
PASS	0.01	12/12/16	11:29 AM	#268	Hall	1st	East	Wall	Upper	White	Plaster	unit 102
PASS	0.01	12/12/16	11:30 AM	#269	Hall	1st	West	Wall	Upper	White	Plaster	unit 102
PASS	0.01	12/12/16	11:30 AM	#270	Hall	1st	South	Wall	Lower	White	Plaster	unit 102
PASS	0.21	12/12/16	11:31 AM	#272	Hall	1st	South	Door casing	Center	White	Wood	unit 102
PASS	0.01	12/12/16	11:31 AM	#273	Hall	1st	West	Door jamb	Center	White	Wood	unit 102
PASS	0.18	12/12/16	11:32 AM	#274	Hall	1st	North	Cabinet	Center	White	Wood	unit 102

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
▼ Bdrm 1												
PASS	0	12/12/16	11:33 AM	#275	Bdrm 1	1st	North	Ceiling	Center	White	Plaster	unit 102
PASS	0.02	12/12/16	11:33 AM	#276	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 102
PASS	0.01	12/12/16	11:34 AM	#277	Bdrm 1	1st	West	Wall	Center	White	Plaster	unit 102
PASS	0.02	12/12/16	11:34 AM	#278	Bdrm 1	1st	East	Wall	Upper	White	Plaster	unit 102
PASS	0	12/12/16	11:34 AM	#279	Bdrm 1	1st	South	Wall	Lower	White	Plaster	unit 102
PASS	0.21	12/12/16	11:35 AM	#280	Bdrm 1	1st	South	Window casing	Center	White	Wood	unit 102
PASS	0.07	12/12/16	11:35 AM	#281	Bdrm 1	1st	South	Window stool	Center	White	Wood	unit 102
PASS	0	12/12/16	11:36 AM	#282	Bdrm 1	1st	West	Door	Left	White	Wood	unit 102
PASS	0.02	12/12/16	11:37 AM	#283	Bdrm 1	1st	West	Door casing	Right	White	Wood	unit 102
PASS	0.19	12/12/16	11:37 AM	#284	Bdrm 1	1st	West	Baseboard	Center	White	Wood	unit 102
PASS	0.28	12/12/16	11:38 AM	#285	Bdrm 1	1st	East	Radiator	Center	White	Metal	unit 102
▼ unit 101												
▼ Kitchen												
PASS	0.02	12/12/16	11:40 AM	#286	Kitchen	1st	North	Wall	Center	White	Wood	unit 101
PASS	0.02	12/12/16	11:41 AM	#287	Kitchen	1st	West	Wall	Center	White	Wood	unit 101
PASS	0	12/12/16	11:41 AM	#288	Kitchen	1st	South	Wall	Upper	White	Plaster	unit 101
PASS	0	12/12/16	11:42 AM	#289	Kitchen	1st	East	Wall	Lower	White	Plaster	unit 101
PASS	0	12/12/16	11:42 AM	#290	Kitchen	1st	North	Door casing	Lower	Stain	Wood	unit 101
PASS	0	12/12/16	11:43 AM	#291	Kitchen	1st	South	Door casing	Center	White	Wood	unit 101
▼ Bathroom												
PASS	0	12/12/16	11:44 AM	#292	Bathroom	1st	North	Wall	Center	White	Wood	unit 101
PASS	0	12/12/16	11:45 AM	#293	Bathroom	1st	West	Wall	Center	White	Wood	unit 101
PASS	0	12/12/16	11:45 AM	#294	Bathroom	1st	North	Wall	Center	White	Plaster	unit 101
PASS	0	12/12/16	11:46 AM	#295	Bathroom	1st	East	Wall	Lower	White	Plaster	unit 101
PASS	0	12/12/16	11:46 AM	#296	Bathroom	1st	North	Window stool	Center	White	Wood	unit 101
PASS	0	12/12/16	11:47 AM	#297	Bathroom	1st	South	Door casing	Center	Stain	Wood	unit 101
PASS	0.01	12/12/16	11:48 AM	#298	Bathroom	1st	North	Radiator	Center	White	Metal	unit 101
▼ Bdrm 1												
PASS	0.01	12/12/16	11:49 AM	#299	Bdrm 1	1st	North	Radiator	Center	White	Metal	unit 101
PASS	0.01	12/12/16	11:49 AM	#300	Bdrm 1	1st	North	Wall	Center	White	Concrete	unit 101
PASS	0.47	12/12/16	11:50 AM	#301	Bdrm 1	1st	North	Window casing	Center	White	Metal	unit 101
PASS	0	12/12/16	11:51 AM	#302	Bdrm 1	1st	South	Door jamb	Center	White	Wood	unit 101
▼ Living room												
PASS	0	12/12/16	11:51 AM	#303	Living room	1st	North	Wall	Center	White	Plaster	unit 101
PASS	0	12/12/16	11:52 AM	#304	Living room	1st	South	Wall	Center	White	Plaster	unit 101
PASS	0	12/12/16	11:53 AM	#305	Living room	1st	East	Wall	Upper	White	Plaster	unit 101

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0	12/12/16	11:53 AM	#306	Living room	1st	West	Wall	Lower	White	Plaster	unit 101
PASS	0.66	12/12/16	11:54 AM	#307	Living room	1st	West	Window casing	Center	White	Metal	unit 101
▼ unit 201												
▼ Living room												
PASS	0	12/12/16	12:01 PM	#308	Living room	1st	North	Ceiling	Center	White	Plaster	unit 201
PASS	0	12/12/16	12:02 PM	#309	Living room	1st	North	Wall	Center	White	Plaster	unit 201
PASS	0	12/12/16	12:02 PM	#310	Living room	1st	South	Wall	Center	White	Plaster	unit 201
PASS	0	12/12/16	12:03 PM	#311	Living room	1st	East	Wall	Upper	White	Plaster	unit 201
PASS	0	12/12/16	12:03 PM	#312	Living room	1st	West	Wall	Lower	White	Plaster	unit 201
PASS	0.18	12/12/16	12:04 PM	#313	Living room	1st	West	Window casing	Center	White	Wood	unit 201
PASS	0.01	12/12/16	12:04 PM	#314	Living room	1st	North	Window sash	Center	White	Wood	unit 201
PASS	0.01	12/12/16	12:05 PM	#315	Living room	1st	South	Door casing	Center	White	Wood	unit 201
PASS	0	12/12/16	12:06 PM	#316	Living room	1st	East	Door jamb	Center	White	Wood	unit 201
PASS	0.13	12/12/16	12:06 PM	#317	Living room	1st	East	Baseboard	Center	White	Wood	unit 201
PASS	0	12/12/16	12:07 PM	#318	Living room	1st	East	Closet	Center	White	Plaster	unit 201
▼ Dining												
PASS	0	12/12/16	12:08 PM	#319	Dining	1st	North	Ceiling	Center	White	Plaster	unit 201
PASS	0	12/12/16	12:08 PM	#320	Dining	1st	West	Wall	Center	White	Plaster	unit 201
PASS	0.01	12/12/16	12:09 PM	#321	Dining	1st	South	Wall	Center	White	Plaster	unit 201
PASS	0	12/12/16	12:09 PM	#322	Dining	1st	East	Wall	Upper	White	Plaster	unit 201
PASS	0	12/12/16	12:10 PM	#323	Dining	1st	North	Wall	Lower	White	Plaster	unit 201
PASS	0.01	12/12/16	12:10 PM	#324	Dining	1st	North	Window casing	Lower	White	Wood	unit 201
PASS	0.01	12/12/16	12:11 PM	#325	Dining	1st	East	Door casing	Center	White	Wood	unit 201
PASS	0.04	12/12/16	12:12 PM	#326	Dining	1st	South	Cabinet	Left	White	Wood	unit 201
PASS	0.02	12/12/16	12:12 PM	#327	Dining	1st	North	Baseboard	Left	White	Wood	unit 201
PASS	0.47	12/12/16	12:13 PM	#328	Dining	1st	North	Radiator	Center	White	Metal	unit 201
▼ Kitchen												
FAIL	1.01	12/12/16	12:14 PM	#329	Kitchen	1st	North	Ceiling	Center	White	Plaster	unit 201
PASS	0	12/12/16	12:15 PM	#330	Kitchen	1st	South	Wall	Center	White	Plaster	unit 201
PASS	0.59	12/12/16	12:16 PM	#331	Kitchen	1st	North	Wall	Center	White	Wood	unit 201
FAIL	1.18	12/12/16	12:17 PM	#332	Kitchen	1st	West	Wall	Upper	White	Plaster	unit 201
FAIL	1.84	12/12/16	12:17 PM	#333	Kitchen	1st	East	Wall	Center	White	Plaster	unit 201
PASS	0	12/12/16	12:18 PM	#334	Kitchen	1st	South	Baseboard	Center	White	Wood	unit 201
PASS	0.61	12/12/16	12:19 PM	#335	Kitchen	1st	East	Cabinet	Center	White	Wood	unit 201
▼ Bathroom												
PASS	0	12/12/16	12:20 PM	#336	Bathroom	1st	East	Ceiling	Center	White	Plaster	unit 201
PASS	0	12/12/16	12:21 PM	#337	Bathroom	1st	South	Wall	Center	White	Plaster	unit 201

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
FAIL	3.1	12/12/16	12:22 PM	#338	Bathroom	1st	North	Wall	Upper	White	Plaster	unit 201
PASS	0.51	12/12/16	12:22 PM	#339	Bathroom	1st	West	Wall	Center	White	Plaster	unit 201
PASS	0	12/12/16	12:23 PM	#340	Bathroom	1st	East	Wall	Center	White	Plaster	unit 201
PASS	0.41	12/12/16	12:24 PM	#341	Bathroom	1st	North	Window casing	Center	White	Wood	unit 201
PASS	0.35	12/12/16	12:24 PM	#342	Bathroom	1st	North	Door casing	Center	White	Wood	unit 201
PASS	0.71	12/12/16	12:25 PM	#343	Bathroom	1st	East	Cabinet	Center	White	Wood	unit 201
PASS	0.57	12/12/16	12:25 PM	#344	Bathroom	1st	West	Radiator	Center	White	Metal	unit 201
PASS	0.03	12/12/16	12:26 PM	#345	Bathroom	1st	West	Floor	Center	White	Ceramic	unit 201
FAIL	5	12/12/16	12:27 PM	#346	Bathroom	1st	North	Bathtub	Center	White	Metal	unit 201
▼ Hall												
PASS	0.38	12/12/16	12:28 PM	#347	Hall	1st	South	Cabinet	Center	White	Wood	unit 201
▼ Bdrm 1												
PASS	0	12/12/16	12:29 PM	#348	Bdrm 1	1st	South	Ceiling	Center	White	Plaster	unit 201
FAIL	1.04	12/12/16	12:30 PM	#349	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 201
PASS	0	12/12/16	12:30 PM	#350	Bdrm 1	1st	South	Wall	Center	White	Plaster	unit 201
PASS	0	12/12/16	12:31 PM	#351	Bdrm 1	1st	East	Wall	Upper	White	Plaster	unit 201
PASS	0	12/12/16	12:32 PM	#352	Bdrm 1	1st	West	Wall	Lower	White	Plaster	unit 201
PASS	0.88	12/12/16	12:32 PM	#353	Bdrm 1	1st	North	Window casing	Center	White	Wood	unit 201
FAIL	1.25	12/12/16	12:33 PM	#354	Bdrm 1	1st	West	Door casing	Center	White	Wood	unit 201
PASS	0.18	12/12/16	12:34 PM	#355	Bdrm 1	1st	West	Door jamb	Left	White	Wood	unit 201
FAIL	2.23	12/12/16	12:35 PM	#356	Bdrm 1	1st	South	Baseboard	Center	White	Wood	unit 201
PASS	0	12/12/16	12:35 PM	#357	Bdrm 1	1st	West	Closet	Center	White	Plaster	unit 201
▼ unit 203												
▼ Bdrm 1												
PASS	0	12/12/16	12:37 PM	#358	Bdrm 1	1st	West	Ceiling	Center	White	Plaster	unit 203
PASS	0	12/12/16	12:38 PM	#359	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 203
PASS	0	12/12/16	12:39 PM	#360	Bdrm 1	1st	West	Wall	Center	White	Plaster	unit 203
PASS	0	12/12/16	12:39 PM	#361	Bdrm 1	1st	South	Wall	Upper	White	Plaster	unit 203
PASS	0	12/12/16	12:40 PM	#362	Bdrm 1	1st	East	Wall	Lower	White	Plaster	unit 203
PASS	0.94	12/12/16	12:41 PM	#363	Bdrm 1	1st	East	Window casing	Center	White	Wood	unit 203
FAIL	1.46	12/12/16	12:41 PM	#364	Bdrm 1	1st	South	Door casing	Left	White	Wood	unit 203
PASS	0.01	12/12/16	12:42 PM	#365	Bdrm 1	1st	South	Closet	Left	White	Plaster	unit 203
PASS	0.4	12/12/16	12:42 PM	#366	Bdrm 1	1st	South	Door jamb	Right	White	Plaster	unit 203
FAIL	1.8	12/12/16	12:43 PM	#367	Bdrm 1	1st	West	Baseboard	Center	White	Wood	unit 203
▼ Bathroom												
PASS	0	12/12/16	12:44 PM	#368	Bathroom	1st	North	Wall	Center	White	Plaster	unit 203
PASS	0	12/12/16	12:44 PM	#369	Bathroom	1st	South	Wall	Center	White	Plaster	unit 203

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0	12/12/16	12:45 PM	#370	Bathroom	1st	West	Wall	Upper	White	Plaster	unit 203
PASS	0	12/12/16	12:46 PM	#371	Bathroom	1st	East	Wall	Upper	White	Plaster	unit 203
PASS	0.21	12/12/16	12:47 PM	#372	Bathroom	1st	East	Window casing	Center	White	Wood	unit 203
PASS	0.54	12/12/16	12:47 PM	#373	Bathroom	1st	West	Door casing	Center	White	Wood	unit 203
PASS	0.28	12/12/16	12:48 PM	#374	Bathroom	1st	South	Cabinet	Center	White	Wood	unit 203
FAIL	5	12/12/16	12:48 PM	#375	Bathroom	1st	East	Bathtub	Center	White	Metal	unit 203
PASS	0.42	12/12/16	12:49 PM	#376	Bathroom	1st	North	Radiator	Center	Black	Metal	unit 203
▼ Hall												
PASS	0.53	12/12/16	12:49 PM	#377	Hall	1st	South	Cabinet	Center	White	Wood	unit 203
▼ Living room												
PASS	0	12/12/16	12:50 PM	#378	Living room	1st	South	Ceiling	Center	White	Plaster	unit 203
PASS	0	12/12/16	12:51 PM	#379	Living room	1st	North	Wall	Center	White	Plaster	unit 203
PASS	0	12/12/16	12:52 PM	#380	Living room	1st	South	Wall	Center	White	Plaster	unit 203
PASS	0	12/12/16	12:52 PM	#381	Living room	1st	East	Wall	Upper	White	Plaster	unit 203
PASS	0	12/12/16	12:53 PM	#382	Living room	1st	West	Wall	Lower	White	Plaster	unit 203
PASS	0	12/12/16	12:54 PM	#383	Living room	1st	North	Window casing	Center	Stain	Wood	unit 203
PASS	0	12/12/16	12:55 PM	#384	Living room	1st	West	Door casing	Center	Stain	Wood	unit 203
PASS	0	12/12/16	12:55 PM	#385	Living room	1st	South	Door casing	Center	Tan	Wood	unit 203
PASS	0	12/12/16	12:56 PM	#386	Living room	1st	South	Baseboard	Center	Stain	Wood	unit 203
PASS	0.04	12/12/16	12:57 PM	#387	Living room	1st	South	Floor	Center	Stain	Wood	unit 203
PASS	0.02	12/12/16	12:57 PM	#388	Living room	1st	West	Closet	Center	White	Plaster	unit 203
▼ Kitchen												
PASS	0	12/12/16	12:58 PM	#389	Kitchen	1st	West	Ceiling	Center	White	Plaster	unit 203
PASS	0	12/12/16	12:59 PM	#390	Kitchen	1st	North	Wall	Center	White	Plaster	unit 203
PASS	0	12/12/16	12:59 PM	#391	Kitchen	1st	East	Wall	Left	White	Plaster	unit 203
PASS	0	12/12/16	1:00 PM	#392	Kitchen	1st	East	Wall	Right	White	Plaster	unit 203
PASS	0	12/12/16	1:00 PM	#393	Kitchen	1st	South	Wall	Upper	White	Plaster	unit 203
PASS	0	12/12/16	1:01 PM	#394	Kitchen	1st	West	Wall	Right	White	Plaster	unit 203
PASS	0	12/12/16	1:02 PM	#395	Kitchen	1st	North	Window casing	Center	Stain	Wood	unit 203
PASS	0.01	12/12/16	1:03 PM	#396	Kitchen	1st	South	Cabinet	Left	Stain	Wood	unit 203
FAIL	1.47	12/12/16	1:03 PM	#397	Kitchen	1st	West	Cabinet	Upper	White	Wood	unit 203
PASS	0	12/12/16	1:04 PM	#398	Kitchen	1st	South	Baseboard	Center	White	Wood	unit 203
▼ unit 204												
▼ Bdrm 1												
PASS	0	12/12/16	1:06 PM	#399	Bdrm 1	1st	South	Ceiling	Center	White	Plaster	unit 204
PASS	0	12/12/16	1:06 PM	#400	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 204
PASS	0	12/12/16	1:07 PM	#401	Bdrm 1	1st	South	Wall	Center	White	Plaster	unit 204

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0	12/12/16	1:07 PM	#402	Bdrm 1	1st	West	Wall	Upper	White	Plaster	unit 204
PASS	0	12/12/16	1:08 PM	#403	Bdrm 1	1st	East	Wall	Lower	White	Plaster	unit 204
PASS	0.55	12/12/16	1:08 PM	#404	Bdrm 1	1st	East	Window casing	Center	White	Wood	unit 204
PASS	0.17	12/12/16	1:09 PM	#405	Bdrm 1	1st	South	Window sash	Center	White	Wood	unit 204
PASS	0.03	12/12/16	1:09 PM	#406	Bdrm 1	1st	North	Door casing	Left	White	Wood	unit 204
PASS	0	12/12/16	1:10 PM	#407	Bdrm 1	1st	North	Door	Right	White	Wood	unit 204
PASS	0.01	12/12/16	1:10 PM	#408	Bdrm 1	1st	North	Baseboard	Center	White	Wood	unit 204
PASS	0.01	12/12/16	1:11 PM	#409	Bdrm 1	1st	North	Closet	Center	White	Plaster	unit 204
PASS	0.36	12/12/16	1:12 PM	#410	Bdrm 1	1st	South	Radiator	Center	White	Metal	unit 204
▼ Bathroom												
PASS	0.3	12/12/16	1:13 PM	#411	Bathroom	1st	South	Radiator	Center	White	Metal	unit 204
PASS	0	12/12/16	1:13 PM	#412	Bathroom	1st	South	Ceiling	Center	White	Plaster	unit 204
FAIL	4.18	12/12/16	1:13 PM	#413	Bathroom	1st	North	Wall	Center	White	Plaster	unit 204
PASS	0	12/12/16	1:14 PM	#414	Bathroom	1st	South	Wall	Center	White	Plaster	unit 204
FAIL	5	12/12/16	1:14 PM	#415	Bathroom	1st	West	Wall	Upper	White	Plaster	unit 204
PASS	0	12/12/16	1:15 PM	#416	Bathroom	1st	East	Wall	Upper	White	Plaster	unit 204
PASS	0.9	12/12/16	1:16 PM	#417	Bathroom	1st	East	Window casing	Center	White	Wood	unit 204
PASS	0.64	12/12/16	1:16 PM	#418	Bathroom	1st	West	Door casing	Center	White	Wood	unit 204
FAIL	5	12/12/16	1:17 PM	#419	Bathroom	1st	East	Bathtub	Center	White	Metal	unit 204
▼ Living room												
PASS	0	12/12/16	1:17 PM	#420	Living room	1st	East	Ceiling	Center	White	Plaster	unit 204
PASS	0	12/12/16	1:19 PM	#421	Living room	1st	North	Wall	Center	White	Plaster	unit 204
PASS	0	12/12/16	1:19 PM	#422	Living room	1st	West	Wall	Center	White	Plaster	unit 204
PASS	0	12/12/16	1:20 PM	#423	Living room	1st	East	Wall	Upper	White	Plaster	unit 204
PASS	0	12/12/16	1:20 PM	#424	Living room	1st	South	Wall	Lower	White	Plaster	unit 204
PASS	0	12/12/16	1:21 PM	#425	Living room	1st	South	Window casing	Center	Stain	Wood	unit 204
PASS	0.11	12/12/16	1:21 PM	#426	Living room	1st	North	Door casing	Center	White	Wood	unit 204
PASS	0	12/12/16	1:22 PM	#427	Living room	1st	East	Door jamb	Center	White	Wood	unit 204
PASS	0	12/12/16	1:23 PM	#428	Living room	1st	West	Door	Center	White	Wood	unit 204
PASS	0	12/12/16	1:23 PM	#429	Living room	1st	West	Baseboard	Center	White	Wood	unit 204
PASS	0	12/12/16	1:24 PM	#430	Living room	1st	West	Closet	Center	White	Plaster	unit 204
▼ Kitchen												
PASS	0	12/12/16	1:25 PM	#431	Kitchen	1st	West	Ceiling	Center	White	Plaster	unit 204
PASS	0	12/12/16	1:25 PM	#432	Kitchen	1st	North	Wall	Center	White	Plaster	unit 204
PASS	0	12/12/16	1:26 PM	#433	Kitchen	1st	South	Wall	Center	White	Plaster	unit 204
PASS	0	12/12/16	1:26 PM	#434	Kitchen	1st	West	Wall	Left	White	Plaster	unit 204
FAIL	3.83	12/12/16	1:27 PM	#435	Kitchen	1st	East	Wall	Left	White	Plaster	unit 204

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0	12/12/16	1:27 PM	#436	Kitchen	1st	East	Wall	Right	White	Plaster	unit 204
PASS	0	12/12/16	1:28 PM	#437	Kitchen	1st	South	Window casing	Center	Stain	Wood	unit 204
PASS	0.18	12/12/16	1:29 PM	#438	Kitchen	1st	West	Cabinet	Right	White	Wood	unit 204
PASS	0	12/12/16	1:29 PM	#439	Kitchen	1st	North	Baseboard	Center	White	Wood	unit 204
▼ unit 302												
▼ Bdrm 1												
PASS	0	12/12/16	1:32 PM	#440	Bdrm 1	1st	North	Ceiling	Center	White	Plaster	unit 302
PASS	0	12/12/16	1:33 PM	#441	Bdrm 1	1st	North	Wall	Center	White	Plaster	unit 302
PASS	0	12/12/16	1:33 PM	#442	Bdrm 1	1st	West	Wall	Center	White	Plaster	unit 302
PASS	0	12/12/16	1:34 PM	#443	Bdrm 1	1st	East	Wall	Upper	White	Plaster	unit 302
PASS	0.01	12/12/16	1:34 PM	#444	Bdrm 1	1st	South	Wall	Lower	White	Plaster	unit 302
PASS	0.44	12/12/16	1:35 PM	#445	Bdrm 1	1st	South	Window casing	Center	White	Wood	unit 302
PASS	0.41	12/12/16	1:36 PM	#446	Bdrm 1	1st	West	Door casing	Left	White	Wood	unit 302
PASS	0.06	12/12/16	1:37 PM	#447	Bdrm 1	1st	West	Door	Right	White	Wood	unit 302
FAIL	1.32	12/12/16	1:37 PM	#448	Bdrm 1	1st	West	Baseboard	Center	White	Wood	unit 302
PASS	0.04	12/12/16	1:38 PM	#449	Bdrm 1	1st	West	Closet	Center	White	Plaster	unit 302
▼ Bathroom												
PASS	0.8	12/12/16	1:39 PM	#450	Bathroom	1st	West	Ceiling	Center	White	Plaster	unit 302
FAIL	1.05	12/12/16	1:40 PM	#451	Bathroom	1st	North	Wall	Center	White	Plaster	unit 302
PASS	0.55	12/12/16	1:40 PM	#452	Bathroom	1st	East	Wall	Center	White	Plaster	unit 302
PASS	0.64	12/12/16	1:41 PM	#453	Bathroom	1st	West	Wall	Lower	White	Plaster	unit 302
PASS	0.79	12/12/16	1:41 PM	#454	Bathroom	1st	South	Wall	Upper	White	Plaster	unit 302
PASS	0.77	12/12/16	1:42 PM	#455	Bathroom	1st	South	Window casing	Center	White	Wood	unit 302
PASS	0.46	12/12/16	1:42 PM	#456	Bathroom	1st	North	Door jamb	Center	White	Wood	unit 302
FAIL	5	12/12/16	1:43 PM	#457	Bathroom	1st	South	Bathtub	Center	White	Metal	unit 302
PASS	0.69	12/12/16	1:43 PM	#458	Bathroom	1st	West	Radiator	Center	White	Metal	unit 302
▼ Kitchen												
PASS	0.01	12/12/16	1:44 PM	#459	Kitchen	1st	West	Ceiling	Center	White	Plaster	unit 302
PASS	0	12/12/16	1:44 PM	#460	Kitchen	1st	West	Wall	Center	White	Plaster	unit 302
PASS	0.71	12/12/16	1:45 PM	#461	Kitchen	1st	North	Wall	Center	White	Plaster	unit 302
PASS	0	12/12/16	1:45 PM	#462	Kitchen	1st	North	Wall	Center	White	Plaster	unit 302
FAIL	2.44	12/12/16	1:46 PM	#463	Kitchen	1st	West	Wall	Right	White	Plaster	unit 302
PASS	0	12/12/16	1:46 PM	#464	Kitchen	1st	West	Wall	Left	White	Plaster	unit 302
PASS	0	12/12/16	1:47 PM	#465	Kitchen	1st	East	Wall	Upper	White	Plaster	unit 302
PASS	0	12/12/16	1:47 PM	#466	Kitchen	1st	South	Wall	Upper	White	Plaster	unit 302
PASS	0.01	12/12/16	1:48 PM	#467	Kitchen	1st	South	Window casing	Center	Stain	Wood	unit 302
PASS	0.01	12/12/16	1:49 PM	#468	Kitchen	1st	East	Door casing	Center	Stain	Wood	unit 302

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
PASS	0.55	12/12/16	1:49 PM	#469	Kitchen	1st	East	Cabinet	Left	White	Wood	unit 302
▼ Living room												
PASS	0	12/12/16	1:50 PM	#470	Living room	1st	East	Ceiling	Center	White	Plaster	unit 302
PASS	0	12/12/16	1:51 PM	#471	Living room	1st	North	Wall	Center	White	Plaster	unit 302
PASS	0	12/12/16	1:51 PM	#472	Living room	1st	East	Wall	Center	White	Plaster	unit 302
PASS	0	12/12/16	1:52 PM	#473	Living room	1st	South	Wall	Upper	White	Plaster	unit 302
PASS	0	12/12/16	1:53 PM	#474	Living room	1st	West	Wall	Lower	White	Plaster	unit 302
PASS	0.01	12/12/16	1:53 PM	#475	Living room	1st	West	Window casing	Center	Stain	Wood	unit 302
PASS	0.27	12/12/16	1:54 PM	#476	Living room	1st	West	Radiator	Center	White	Metal	unit 302
▼ unit 303												
▼ Bdrm 1												
PASS	0	12/12/16	1:57 PM	#477	Bdrm 1	3rd	West	Ceiling	Center	White	Plaster	unit 303
PASS	0	12/12/16	1:58 PM	#478	Bdrm 1	3rd	North	Wall	Center	White	Plaster	unit 303
PASS	0	12/12/16	1:58 PM	#479	Bdrm 1	3rd	East	Wall	Center	White	Plaster	unit 303
PASS	0	12/12/16	1:59 PM	#480	Bdrm 1	3rd	South	Wall	Center	White	Plaster	unit 303
PASS	0.58	12/12/16	1:59 PM	#481	Bdrm 1	3rd	West	Wall	Upper	White	Plaster	unit 303
PASS	0.24	12/12/16	2:00 PM	#482	Bdrm 1	3rd	South	Window casing	Center	White	Wood	unit 303
PASS	0	12/12/16	2:01 PM	#483	Bdrm 1	3rd	East	Window sash	Center	White	Wood	unit 303
PASS	0.08	12/12/16	2:02 PM	#484	Bdrm 1	3rd	South	Door	Left	White	Wood	unit 303
PASS	0.48	12/12/16	2:02 PM	#485	Bdrm 1	3rd	South	Door casing	Right	White	Wood	unit 303
PASS	0.58	12/12/16	2:03 PM	#486	Bdrm 1	3rd	South	Baseboard	Center	White	Wood	unit 303
PASS	0.02	12/12/16	2:03 PM	#487	Bdrm 1	3rd	South	Closet	Center	White	Plaster	unit 303
PASS	0.41	12/12/16	2:04 PM	#488	Bdrm 1	3rd	West	Radiator	Center	White	Metal	unit 303
▼ Bathroom												
PASS	0.44	12/12/16	2:05 PM	#489	Bathroom	3rd	West	Ceiling	Center	White	Plaster	unit 303
PASS	0	12/12/16	2:06 PM	#490	Bathroom	3rd	North	Wall	Center	White	Plaster	unit 303
PASS	0.41	12/12/16	2:06 PM	#491	Bathroom	3rd	South	Wall	Center	White	Plaster	unit 303
PASS	0.53	12/12/16	2:07 PM	#492	Bathroom	3rd	West	Wall	Upper	White	Plaster	unit 303
PASS	0.46	12/12/16	2:07 PM	#493	Bathroom	3rd	East	Wall	Upper	White	Plaster	unit 303
PASS	0.2	12/12/16	2:08 PM	#494	Bathroom	3rd	East	Window casing	Center	White	Wood	unit 303
PASS	0.19	12/12/16	2:08 PM	#495	Bathroom	3rd	West	Door casing	Center	White	Wood	unit 303
PASS	0.15	12/12/16	2:09 PM	#496	Bathroom	3rd	South	Cabinet	Center	White	Wood	unit 303
PASS	0.39	12/12/16	2:09 PM	#497	Bathroom	3rd	North	Radiator	Center	White	Metal	unit 303
FAIL	5	12/12/16	2:10 PM	#498	Bathroom	3rd	East	Bathtub	Center	White	Metal	unit 303
▼ Hall												
PASS	0.17	12/12/16	2:11 PM	#499	Hall	3rd	South	Cabinet	Center	White	Wood	unit 303
PASS	0.37	12/12/16	2:11 PM	#500	Hall	3rd	North	Door casing	Right	White	Wood	unit 303

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
▼ Living room												
PASS	0	12/12/16	2:12 PM	#501	Living room	3rd	North	Ceiling	Center	White	Plaster	unit 303
PASS	0	12/12/16	2:12 PM	#502	Living room	3rd	South	Wall	Center	White	Plaster	unit 303
PASS	0	12/12/16	2:13 PM	#503	Living room	3rd	East	Wall	Center	White	Plaster	unit 303
PASS	0	12/12/16	2:13 PM	#504	Living room	3rd	West	Wall	Upper	White	Plaster	unit 303
PASS	0	12/12/16	2:13 PM	#505	Living room	3rd	North	Wall	Lower	White	Plaster	unit 303
PASS	0.01	12/12/16	2:14 PM	#506	Living room	3rd	North	Window casing	Center	Stain	Wood	unit 303
PASS	0.01	12/12/16	2:15 PM	#507	Living room	3rd	West	Door casing	Center	Stain	Wood	unit 303
PASS	0	12/12/16	2:15 PM	#508	Living room	3rd	South	Door casing	Center	White	Wood	unit 303
PASS	0.01	12/12/16	2:16 PM	#509	Living room	3rd	West	Baseboard	Center	Stain	Wood	unit 303
▼ Kitchen												
PASS	0	12/12/16	2:17 PM	#510	Kitchen	3rd	West	Ceiling	Center	White	Plaster	unit 303
PASS	0	12/12/16	2:18 PM	#511	Kitchen	3rd	South	Wall	Center	White	Plaster	unit 303
PASS	0.53	12/12/16	2:18 PM	#512	Kitchen	3rd	East	Wall	Right	White	Plaster	unit 303
PASS	0	12/12/16	2:19 PM	#513	Kitchen	3rd	East	Wall	Left	White	Plaster	unit 303
PASS	0	12/12/16	2:19 PM	#514	Kitchen	3rd	West	Wall	Right	White	Plaster	unit 303
PASS	0	12/12/16	2:20 PM	#515	Kitchen	3rd	North	Wall	Upper	White	Plaster	unit 303
PASS	0	12/12/16	2:20 PM	#516	Kitchen	3rd	North	Window casing	Center	Stain	Plaster	unit 303
FAIL	1.4	12/12/16	2:21 PM	#517	Kitchen	3rd	West	Cabinet	Left	White	Wood	unit 303
PASS	0	12/12/16	2:22 PM	#518	Kitchen	3rd	South	Baseboard	Center	White	Wood	unit 303
▼ unit 304												
▼ Bdrm 1												
PASS	0	12/12/16	2:24 PM	#519	Bdrm 1	3rd	North	Ceiling	Center	White	Plaster	unit 304
PASS	0	12/12/16	2:24 PM	#520	Bdrm 1	3rd	North	Wall	Center	White	Plaster	unit 304
PASS	0	12/12/16	2:25 PM	#521	Bdrm 1	3rd	South	Wall	Center	White	Plaster	unit 304
PASS	0	12/12/16	2:25 PM	#522	Bdrm 1	3rd	West	Wall	Upper	White	Plaster	unit 304
PASS	0	12/12/16	2:26 PM	#523	Bdrm 1	3rd	East	Wall	Lower	White	Plaster	unit 304
PASS	0.08	12/12/16	2:26 PM	#524	Bdrm 1	3rd	East	Window casing	Center	White	Wood	unit 304
PASS	0.01	12/12/16	2:27 PM	#525	Bdrm 1	3rd	North	Door casing	Left	White	Wood	unit 304
PASS	0.05	12/12/16	2:28 PM	#526	Bdrm 1	3rd	North	Door	Right	White	Wood	unit 304
PASS	0	12/12/16	2:28 PM	#527	Bdrm 1	3rd	North	Baseboard	Center	White	Wood	unit 304
PASS	0.63	12/12/16	2:29 PM	#528	Bdrm 1	3rd	West	Radiator	Center	White	Metal	unit 304
PASS	0.03	12/12/16	2:30 PM	#529	Bdrm 1	3rd	North	Closet	Right	White	Plaster	unit 304
▼ Bathroom												
FAIL	2.17	12/12/16	2:30 PM	#530	Bathroom	3rd	North	Ceiling	Center	White	Plaster	unit 304
PASS	0.85	12/12/16	2:31 PM	#531	Bathroom	3rd	North	Wall	Center	White	Plaster	unit 304
PASS	0.94	12/12/16	2:31 PM	#532	Bathroom	3rd	West	Wall	Center	White	Plaster	unit 304

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
FAIL	1.47	12/12/16	2:32 PM	#533	Bathroom	3rd	South	Wall	Lower	White	Plaster	unit 304
FAIL	1.25	12/12/16	2:32 PM	#534	Bathroom	3rd	East	Wall	Upper	White	Plaster	unit 304
FAIL	1.06	12/12/16	2:33 PM	#535	Bathroom	3rd	East	Window casing	Center	White	Wood	unit 304
FAIL	5	12/12/16	2:33 PM	#536	Bathroom	3rd	West	Door casing	Center	White	Wood	unit 304
PASS	0	12/12/16	2:33 PM	#537	Bathroom	3rd	South	Radiator	Center	White	Metal	unit 304
FAIL	5	12/12/16	2:34 PM	#538	Bathroom	3rd	East	Bathtub	Center	White	Metal	unit 304
▼ Hall												
PASS	0.05	12/12/16	2:35 PM	#539	Hall	3rd	South	Cabinet	Center	White	Wood	unit 304
PASS	0.05	12/12/16	2:35 PM	#540	Hall	3rd	West	Door casing	Center	White	Wood	unit 304
▼ Living room												
PASS	0	12/12/16	2:36 PM	#541	Living room	3rd	West	Ceiling	Center	White	Plaster	unit 304
PASS	0	12/12/16	2:36 PM	#542	Living room	3rd	North	Wall	Center	White	Plaster	unit 304
PASS	0	12/12/16	2:37 PM	#543	Living room	3rd	East	Wall	Center	White	Plaster	unit 304
PASS	0	12/12/16	2:37 PM	#544	Living room	3rd	West	Wall	Upper	White	Plaster	unit 304
PASS	0	12/12/16	2:38 PM	#545	Living room	3rd	South	Wall	Lower	White	Plaster	unit 304
PASS	0	12/12/16	2:39 PM	#546	Living room	3rd	South	Window casing	Center	Stain	Wood	unit 304
PASS	0.01	12/12/16	2:39 PM	#547	Living room	3rd	East	Door casing	Center	Stain	Wood	unit 304
PASS	0	12/12/16	2:40 PM	#548	Living room	3rd	North	Door	Center	Tan	Wood	unit 304
PASS	0.05	12/12/16	2:41 PM	#549	Living room	3rd	North	Closet	Center	White	Plaster	unit 304
▼ Kitchen												
PASS	0	12/12/16	2:42 PM	#550	Kitchen	3rd	North	Ceiling	Center	White	Plaster	unit 304
PASS	0	12/12/16	2:42 PM	#551	Kitchen	3rd	North	Wall	Center	White	Plaster	unit 304
PASS	0.71	12/12/16	2:43 PM	#552	Kitchen	3rd	East	Wall	Left	White	Plaster	unit 304
PASS	0	12/12/16	2:43 PM	#553	Kitchen	3rd	East	Wall	Right	White	Plaster	unit 304
PASS	0	12/12/16	2:44 PM	#554	Kitchen	3rd	West	Wall	Left	White	Plaster	unit 304
PASS	0	12/12/16	2:44 PM	#555	Kitchen	3rd	South	Wall	Upper	White	Plaster	unit 304
PASS	0.01	12/12/16	2:45 PM	#556	Kitchen	3rd	South	Window casing	Center	Stain	Wood	unit 304
PASS	0.02	12/12/16	2:46 PM	#557	Kitchen	3rd	South	Baseboard	Center	Stain	Wood	unit 304
PASS	0.4	12/12/16	2:46 PM	#558	Kitchen	3rd	South	Radiator	Center	White	Metal	unit 304
FAIL	1.23	12/12/16	2:47 PM	#559	Kitchen	3rd	West	Cabinet	Center	White	Wood	unit 304
▼ (blank)												
▼ Outside												
FAIL	5	12/12/16	3:02 PM	#568	Outside	1st	West	Door casing	Center	Brown	Wood	
FAIL	3.25	12/12/16	3:03 PM	#570	Outside	1st	West	Door	Center	Yellow	Wood	
FAIL	5	12/12/16	3:05 PM	#571	Outside	1st	West	Window casing	Left	Tan	Wood	
FAIL	5	12/12/16	3:05 PM	#572	Outside	1st	West	Window casing	Right	Tan	Wood	
FAIL	5	12/12/16	3:06 PM	#573	Outside	1st	North	Window casing	Right	Brown	Wood	

PASS/FAIL	Lead Level	Date	Time	Test#	Room	Floor	Side	Component	Quadrant	Color	Substrate	Notes
FAIL	4.63	12/12/16	3:06 PM	#574	Outside	2nd	North	Window casing	Left	Brown	Wood	
FAIL	1.19	12/12/16	3:07 PM	#575	Outside	1st	East	Window casing	Right	Tan	Wood	
FAIL	1.35	12/12/16	3:07 PM	#576	Outside	2nd	South	Window casing	Right	Tan	Wood	
FAIL	5	12/12/16	3:07 PM	#577	Outside	1st	South	Window casing	Right	Tan	Wood	
FAIL	5	12/12/16	3:08 PM	#578	Outside	2nd	South	Window casing	Left	Tan	Wood	